



2026

Wiper Blade Catalogue

(Design Blade and Conventional Blade)

ワイパーブレードカタログ



Contents

● 03	About DENSO	●●●●● 15	Line-up
●● 04	About Wiper	●●● 17	Design Blade Premium [DDP Series]
●●● 05	Important Factors to Determine Wiping Performance	●● 18	Design Blade Standard [DDS Series]
●●●●● 06	Wiper Blade - Features	● 19	Conventional Blade Series [Premium DCP Series]
●●● 07	Outstanding Merit of "DENSO Wiper Blade"	●●●●● 20	Conventional Blade Series [Standard DCS-G Series]
● 08	Comparison with Competitors	●●● 21	Conventional Blade Series [Value DCV Series]
●● 09	Durability Performance	●● 22	Rear Blade Series [DRA Type]
● 10	About Replacement	● 23	Rear Blade Series [DRB Type]
●●● 11	Replacement Signs	●●●●● 25	Applications - Design Blade Series
●●●●● 13	Installation Type Availability	●● 74	Applications - Conventional Blade Series
●● 14	Part No. and Available Length Chart	●●● 145	Applications - Rear Blade
		● 174	Regional Sales Network in Asia Pacific and Middle East

Copyright Notice and Disclaimer

This catalogue has been published for its intended users.

The material contained in this catalogue is based on information available at the time of publication, and all data and information provided is for informational purpose only. DENSO has taken every precaution to ensure that information in this catalogue is accurate, valid and complete at time of publishing. DENSO will not be liable for any errors, omissions, or delays in this information.

All specifications may be subjected to change without prior notice.

DENSO and their logos are trademarks of DENSO Corporation.

All information is correct at time of publishing.
Copyrighted DENSO 2026

About DENSO

DENSO is a leading supplier of advanced automotive technology, systems and components for major automakers. We are committed to making the world a better place through our world-first products and technologies.

DENSO Philosophy

The "DENSO Philosophy" guides our corporate actions, ensuring that we will continue to be a corporation that is trusted by people around the world.

Our Mission

Contributing to a better world by creating value together with a vision for the future




Our Management Principles

- 1 Customer satisfaction through quality products and services
- 2 Global growth through anticipation of change
- 3 Environmental preservation and harmony with society
- 4 Corporate vitality respect for individuality



Our Individual Spirit

- 1 To be creative in thought and steady in action
- 2 To be cooperative and pioneering
- 3 To be trustworthy by improving ourselves





All business locations:
224 companies (38 countries and regions)

Consolidated subsidiaries:
188 (Japan: 62, North America: 28, Europe: 34, Asia: 58, South America/Others: 6)


Affiliates under the equity method:
36 (Japan: 13, North America: 04, Europe: 04, Asia: 13, South America/Others: 2)

About Wiper


The Wiper System & Configuration



How the Wiper Blade wipes the Glass



The uniform spread of water on the glass allows light to pass through it without refracting.




When the windshield has not been wiped, water droplets create an uneven surface causing light to refract as it passes through, ruining the driver's field of vision.

The wiper blade smoothens the water on the surface of the glass to create an "even thin film" to allow light to pass through it without refracting or bending


Important Factors to Determine Wiping Performance

Even Pressure

Both the frame and rubber need to be in good condition!
Changing only the rubber will not provide you with a CLEAR VISION




Rubber Bending Angles & Super Cut Edge



Wiper Blade - Features

OE Wiper Blade





DENSO is OE manufacturer, as such the Wiper blade fits well on your vehicle.

Graphite Coated Rubber

All DENSO Wiper Blade series now come with Graphite Coating.

Graphite is a type of carbon particle that helps to reduce "frictional resistance" on window glass with water repellent coating.



- 1) High wiping performance without the chattering sound.
- 2) Doesn't spoil the water repellent coating on the glass so it can last longer time.




Carbon particles reduce friction and ensures smooth wiping

Super-cut Wiper Rubber


DENSO Super-cut manufacturing method results in evenly cut and sharp Wiper Rubber edge that enhances wiping performance.



Bonnet side





Driver seat side



Fin shape


Fin shape designed for firm and even pressure of DENSO Wiper Blade on glass curved windscreen in headwind, which provides stable pressure even in high speed.



Outstanding Merit of "DENSO Wiper Blade"

Design Type

Sharp Rubber Edge by "Super-cut"



DENSO original "Super-cut" makes sharp edge.




Compatible of high speed performance and design by "Sharpened Light Aero Plastic Cover".

Wiping performance → Increased

Conventional Type

Outer Yoke (Case of 6 points support)




Unsymmetrical Secondary Lever & Yoke



To keep load distribution even till the end.



Sharp Rubber Edge by "Super-cut"



DENSO original "Super-cut" makes sharp edge.

Unsymmetrical Shape Between Face and Back of Primary & Secondary Lever (Aero design)




• DENSO



Air Streamline

Not lifted up

• Other Brands




Air Streamline

Lifted up

Similar to the shape of the wing of racing cars, DENSO Wiper Blades will not be lifted up by the pressure of the wind, even during high speed.



Comparison with Competitors

Load Distribution of Wiper Blade (compared at 500mm)




Due to equal pressure, streak is less likely to appear with DENSO Wiper Blade.

Shape of Rubber Edge



Due to sharp cut edge, usage of DENSO Wiper Blade will have a clearer vision

Graphite Coating



DENSO Wiper Blade has higher Graphite density on the rubber which ensures smoother wiping performance


Initial Test Result

DENSO Wiper Blade has equal pressure and sharp rubber edge of blade which provides a superior wiping performance



DENSO

- Clearer visibility with less streak marks
- Smoother movement with less vibration and sound
- Easy DIY installation without additional clip



Other Brands


- Severe streak marks that impedes visibility
- Lack of durability (chattering sound and streak marks)

Durability Performance

Wiping performance

DCV is same as or greater performance than Company B.

Initial wiping



After wiping equivalent to a year by the test machine



*result of inhouse testing


Item		Performance Check Result	Evaluation
Wiping Performance	Initial	<p>DCV ✓ Good!!</p> <p>DCV Competitor B</p>	<p>In terms of “wiping performance”, DCV is better than Competitor in both Initial and Durability to secure vision of the drivers.</p>
	Durability	<p>DCV ✓ Good!!</p> <p>Good judder performance ↑</p> <p>DCV — Competitor B</p> <p>Wiping times →</p>	
Judder Performance	Initial	<p>Same</p> <p>DCV Competitor B</p>	<p>In terms of “Judder performance”, DCV is same with Competitor in initial stage, but DCV has better durability performance.</p>
	Durability	<p>DCV ✓ Good!!</p>	

(In-house benchmarking evaluation result)

About Replacement

Bend Angle of Rubber

Proper angle can make a uniform thin film of water on the glass surface to keep safe vision. Proper bend angle of rubber is 30 – 50 degree



Bigger play between levers
Rubber deformation
▶ Smear

Rubber hardening
▶ Chattering

Connection →

Yoke →

Main reason for improper bend angle

- ▶ Play of claw of yoke
- ▶ Play at the connecting portion

↓

Improper rolling angle

Rolling angle

X

Too much bend

Even new rubber cannot resume original wiping performance if the superstructure is used for a long time

**Example showed is tournament type wiper.

A malfunctioned Wiper Blade will affect your vision and endanger your driving experience

Replacement Signs

These are the four main signs of Wiper Blade deterioration that are visible on the windscreen glass. These symptoms will help you determine when a Wiper Blade needs changing.



Streaking

Symptom: Narrow streaks are left on the windshield.

Cause: Foreign matter has attached itself to the rubber blade, or edge of the blade is worn.

Remedy

First, clean the edge of the blade. If streaks still appear, replace Wiper Blade.



Unwiped Spots

Symptom: Wiper Blade leaves one or more un wiped spots.

Cause: Rubber deformation.

Remedy

Replace Wiper Blade.



Jumping

Symptom: Wiper Blade jumps and makes a lot of noise.

Cause: The Wiper Blade does not move smoothly across the windshield, but vibrates noisily and bounces.

Remedy

First, clean the windshield; then check the angle. If jumping persists, replace the Wiper Blade.



Uneven Blade Pressure

Symptom: Wiper Blade does not contact the windshield surface evenly, leaving a large un wiped surface.



Cause: Out of shape Wiper Blade arm.

Remedy

Replace the Wiper Blade.

Replacement Signs

Inspect the Wiper Blade for wear and tear signs



Increasing frame plastic whitening over time (colour fading)
 -> Decrease in strength and may result in possibility of breakage

Tournament Wiper Blade Safety Check

Check the [Rattle]

Shake the wiper blade itself and check if sounds [Gata-Gata] (loose) New DENSO Tournament Wiper Blade will not make sound when shaking

[Caution]

Wiper blade with rattle, will not last long after even changing rubber because rubber will wear unevenly by not having even pressure from the frame

Check the [Spring]

Check if the spring function is normal by pulling the rubber from the center

[Caution]

Unwiped area will appear by not following the glass curve due to the spring function declining



NG symptoms appear on wiper blade



Discolouration of main structure

Loose and noisy structure joints

Damaged or worn wiper



How to safely check the design type wiper blade

Check the plastic cover discolouration

Discolouration(white) = long use High possibility the whole wiper blade is damaged.



Check the rattle & rubber deformation

Check rattle of the connection area by holding the tip and shake the cover back and forth. If the rattle is big, it is NG



Connection area


Explain the NG area & recommend to replace

If there is a rattle, even pressure from frame will not come and rubber is not stable so even though changing the rubber, the rubber will not last long. We recommend to change the whole rubber.

You can see the difference if you compare it with new wiper blade

It is important to not only change Wiper Rubber but change Wiper Blade as a whole.

When "Rattling" occurs, changing of Wiper Blade is important to prevent damaging of entire Wiper system



If there is a rattle to wiper frame, the extra load will be on the wiper link itself and wiper link will rattle too.

Even if one wiper has a rattle or a chatter it will affect the other side and will damage the good wiper too. Also, it will damage the wiper link.

Installation Type Availability

Conventional Blades
VALUE (DCV SERIES)

Design Blades Series

PREMIUM (DDP SERIES)

STANDARD(DDS SERIES)

Rear Blades

Conventional Blades Series


PREMIUM (DCP SERIES)

STANDARD(DCS-G SERIES)


		BLADE TYPE				
		DESIGN		CONVENTIONAL		
		PREMIUM	STANDARD	PREMIUM	STANDARD	VALUE
PART NUMBER		DDP-XXX	DDS-XXX	DCP-XXX	DCS-XXX	DCV-XXX
LENGTH	MM	350-750	350-650	350-650	350-650	350-650
	INCH	14-30	12-26	12-26	12-26	12-26
GRAPHITE COATING		◎	◎	◎	◎	○
U-HOOK	9 X 3	○	○	○	○	○
	9 X 4	×	×	×	○	○
CLIP TYPE	BAYONET	×	×	▲ [341-0218-0002D]	○	○
	SCREW	×	×	▲ [AS01-R] [AS02-L]	▲ [AS01-R] [AS02-L]	▲ [AS01-R] [AS02-L]
PIN TYPE	ON ARM	×	×	×	▲ [AS02]	▲ [AS02]
	ON BLADE	×	×	×	×	×
OEM APPLY		○	×	○	×	×
COMMON USED FOR RHD & LHD		×	×	×	○	○

◎ Applicable (More Graphite Coating Than ○) ○ Applicable ▲ Applicable with Additional Adapter × Not Applicable
 [AS01-R]
 [AS02-L]


U-Hook Type (9x3)



U-Hook Type (9x4)




Bayonet Type




❖ Optional adapter
[341-0218-0002D]

Screw Type



❖ Need optional adapter RHD [AS01-R] or LHD [AS01-L]

Pin on Arm



❖ Need optional adapter [AS02]

Part No. and Available Length Chart

LENGTH	DESIGN BLADE				CONVENTIONAL BLADE			
	PREMIUM		STANDARD		PREMIUM		STANDARD	VALUE
	RHD	LHD	RHD	LHD	RHD	LHD		
300			DDS-012R	DDS-012L	DCP-012R	DCP-012L	DCS-G012	DCV-012
325			DDS-013R	DDS-013L			DCS-G013	DCV-013
350	DDP-014R	DDP-014L	DDS-014R	DDS-014L	DCP-014R	DCP-014L	DCS-G014	DCV-014
375			DDS-015R	DDS-015L	DCP-015R	DCP-015L	DCS-G015	DCV-015
400	DDP-016R	DDP-016L	DDS-016R	DDS-016L	DCP-016R	DCP-016L	DCS-G016	DCV-016
425	DDP-017R	DDP-017L	DDS-017R	DDS-017L	DCP-017R	DCP-017L	DCS-G017	DCV-017
450	DDP-018R	DDP-018L	DDS-018R	DDS-018L	DCP-018R	DCP-018L	DCS-G018	DCV-018
475	DDP-019R	DDP-019L	DDS-019R	DDS-019L	DCP-019R	DCP-019L	DCS-G019	DCV-019
500	DDP-020R	DDP-020L	DDS-020R	DDS-020L	DCP-020R	DCP-020L	DCS-G020	DCV-020
525		DDP-021L	DDS-021R	DDS-021L	DCP-021R	DCP-021L	DCS-G021	DCV-021
550	DDP-022R	DDP-022L	DDS-022R	DDS-022L	DCP-022R	DCP-022L	DCS-G022	DCV-022
600	DDP-024R	DDP-024L	DDS-024R	DDS-024L	DCP-024R	DCP-024L	DCS-G024	DCV-024
650	DDP-026R	DDP-026L	DDS-026R	DDS-026L	DCP-026R	DCP-026L	DCS-G026	DCV-026
700	DDP-028R	DDP-028L						
750	DDP-030R	DDP-030L						

LENGTH (MM)	REAR WIPER	
	A TYPE	B TYPE
195		DRB-008
250	DRA-010	DR B-010
275		DRB-011
305	DRA-012	DRB-012
350	DRA-014	DRB-014
400	DRA-016	DRB-016

Optional Adapter

TYPE	CONVENTIONAL BLADE	
	PREMIUM	
	RHD	LHD
BAYONET	341-0218-0002D	
SCREW	AS01-R	AS01-L

TYPE	STANDARD	VALUE
SCREW	AS01-R or AS01-L	AS01-R or AS01-L
PIN ON ARM	AS02	AS02

Line-up

As well as superior OE quality and advanced design, DENSO's Wiper Blade programme for the aftermarket offers complete convenience and choice – there is a DENSO Wiper Blade for almost every car. What's more, the DENSO programme offers 2 essential Wiper Blade types, and a choice of easy fitting options including bayonet, hook or twin screw installation systems.



**PREMIUM
(DDP SERIES)**

**STANDARD
(DDS SERIES)**

Design Blades Series

Truly advanced, OEM specification wiping technology – developed by DENSO - that blends outstanding wiping performance with stylish, integrated design. You can also take advantage of our Retrofit Design Blade range. Covering hundreds of key applications the range enables your customers to upgrade from conventional blades to high performance Uni Wiper Blades.

Premium and Standard available

Conventional Blades Series

A popular choice for the everyday motorist, DENSO's Conventional Wiper Blades offer all-round, long-lasting performance with a selection of different blade and installation options.

Premium, Standard and Value available



**VALUE
(DCV SERIES)**

**PREMIUM
(DCP SERIES)**

**STANDARD
(DCS-G SERIES)**



Fully covered, Aero Dynamic & Stylish matt black body



Aero Dynamic construction



Low profile & Unobstructive shape



"Super-Cut" Rubber Edge for effective wiping performance



Graphite Coating for smooth wiping



Unique OEM Design



Common use for RHD & LHD



Rear Blades

DENSO Rear Wiper Blades deliver excellent wiping performance through the sharp-edge **Super Cut Method**, ensuring clear and consistent rear visibility even in challenging weather conditions.

Featuring All-Resin Molding, the blade is designed as a unified, integrated form with the wiper arm. This seamless design enhances both aesthetics and wiping performance, while ensuring durability and a precise OE-quality fit.

With a focus on performance and design harmony, DENSO Rear Wiper Blades provide a refreshing rear view you can rely on—combining function, style, and long-lasting quality.

Features by Line-up


BLADE TYPE		SUPER-CUT RUBBER EDGE	GRAPHITE COATING	AERO DYNAMIC SHAPE	COMMON FOR R/L USE
DESIGN	PREMIUM [DDP SERIES]	✓	✓	✓	NOT APPLICABLE
	STANDARD [DDS SERIES]	✓	✓	✓	✓
CONVENTIONAL	PREMIUM [DCP SERIES]	✓	✓	✓	NOT APPLICABLE
	STANDARD [DCS SERIES]	✓	✓	NOT APPLICABLE	✓
REAR	TYPE A	✓	✓	✓	✓
	TYPE B	✓	✓	✓	✓


Design Blade Series


Combining the superior wiping performance of DENSO conventional blades with the style and aerodynamic advantages of flat blades, DENSO's Uni design blade is the perfect fit for various range of vehicles in the world. Their innovative engineering, superior materials and futuristic design make DENSO's Uni Design Blade the original equipment choice of some of the world's top vehicle marques. Featuring the same advanced technologies and stylish design, our aftermarket Design blade range was the first to be launched by an OEM brand – and delivers unprecedented wiper performance whenever a replacement is needed.





PREMIUM (DDP SERIES)

- 

Fully covered, Aero Dynamic & Stylish matt black body
- 

Low profile & Unobstructive shape
- 

Graphite Coating for smooth wiping
- 

"Super-Cut" Rubber Edge for effective wiping performance
- 

Unique OEM design, compatible with conventional type

(View from car inside)
Conventional Type Blade




(View from car inside) Design Blade





Installation Type Availability

U-Hook Type (9x3)






How to Replace the Blade

DETACH




ATTACH



For others, check the owner's manual for the correct installation method.

STANDARD (DDS SERIES)



Fully covered,
Aero Dynamic &
Stylish matt black body




Graphite Coating for
smooth wiping



"Super-Cut" Rubber
Edge for effective wiping
performance



Installation Type Availability

U-Hook Type (9x3)






How to Replace the Blade

DETACH



ATTACH



For others, check the owner's manual for the correct installation method.


Category	Design Wiper Premium (DDP)	Design Wiper Standard (DDS)
Design	◎	○
With Graphite Coating	◎	◎
OEM Apply	○	✕
Common Use for RHD and LHD	✕	✕
High Speed Performance	◎	○

Conventional Blade Series

One of our top-selling Wiper Blade ranges, DENSO's Conventional Blade is well-known for its superior wiping performance. There are four different choices of installation system, and three clip options to suit you and your customer.



PREMIUM (DCP SERIES)



Graphite Coating for smooth wiping



Aero dynamic construction



"Super-Cut" Rubber Edge for effective wiping performance




OEM Design Unique OEM design, compatible with conventional type


Unsymmetrical Shape Between Face and Back of Primary & Secondary Lever (Aero design)



DENSO vs OTHER BRANDS



Not lifted up




Lifted up

Air Streamline


Air Streamline

Installation Type Availability

U-Hook Type (9x3)




Bayonet Type



❖ Need optional adapter [341-0218-0002D]



Screw Type





❖ Need optional adapter
RHD [AS01-R]
LHD [AS01-L]

How to Replace the Blade

DETACH




ATTACH



For others, check the owner's manual for the correct installation method.

STANDARD (DCS-G SERIES)



Graphite Coating
for smooth wiping




"Super-Cut" Rubber
Edge for effective wiping
performance




Common use
for RHD & LHD

Installation Type Availability


U-Hook Type (9x3)




U-Hook Type (9x4)



Bayonet Type




Screw Type



❖ Need optional
adapter [AS01-R]
or [AS01-L]



Pin on Arm






❖ Need optional
adapter [AS02]

How to Replace the Blade

DETACH




ATTACH




For others, check the owner's manual for the correct installation method.


BAYONET ARM




STEP 1



STEP 2



STEP 3



Optional adapter is needed for "Screw type" and "Pin on arm".
For more details, please contact DENSO authorized dealers.

Conventional Blade Series

VALUE (DCV SERIES)





Graphite Coating for smooth wiping






Common use for RHD & LHD

How to Replace the Blade

DETACH




ATTACH



For others, check the owner's manual for the correct installation method.

BAYONET ARM



Optional adapter is needed for "Screw type". For more details, please contact DENSO authorised dealers.

Category	Conventional Wiper Premium (DCP)	Conventional Wiper Standard (DCS)	Conventional Wiper Value (DCV)
Design	○	△	△
With Graphite Coating	◎	◎	○
OEM Apply	○	✗	✗
Common Use for RHD and LHD	✗	○	○
High Speed Performance	○	△	△

Rear Blade Series

Due to variations in rear wiper length and arm type across vehicles, DENSO provides a lineup designed to cover applicable configurations for Rear Wiper.

REAR (DRA Type)



Graphite Coating for smooth wiping



"Super-Cut" Rubber Edge for effective wiping performance



Unique OEM design, compatible with conventional type

DRA Type

- Honda Type
- Nissan Type
- Subaru Type

Others

- DRA-010
- DRA-012
- DRA-014
- DRA-016



How to Replace the Blade

DETACH

- Stand the wiper arm.
- Rotate the blade and make proper angle to detach the blade.

"Do not detach it forcibly!"

ATTACH

- Set the blade so that Stopper is located in the bottom of Center bar.

- Rotate the blade and make proper angle so that Center bar can go into "B" smoothly, at the same time, fit Stopper into Groove, "C".

- After inserting the blade to the depths,
 - Rotate the blade as shown in the instruction.
 - Check if the blade is fixed with wiper arm correctly.

For others, check the owner's manual for the correct installation method.

Rear Blade Series

REAR (DRB Type)



Graphite Coating
for smooth wiping



"Super-Cut" Rubber
Edge for effective wiping
performance



Unique OEM design,
compatible with
conventional type



DRB Type

Toyota Type
Daihatsu Type
Suzuki Type

Others

- DRB-008
- DRB-010
- DRB-011
- DRB-012
- DRB-014
- DRB-016




Category	Rear Wiper
Design	◎
With Graphite Coating	◎
OEM Apply	○
Common Use for RHD and LHD	○

How to Replace the Blade

DETACH

① Stand the wiper arm.





② Rotate the blade and make proper angle to detach the blade.

**Do not detach it forcibly!*

ATTACH


① Insert Center bar into tip of Wiper Arm, "B".



② Set the blade so that Bump is located in the bottom of Center bar.

③ Rotate the blade and make proper angle so that Center bar can go into "B" smoothly.

④ After inserting the blade to the depths,
1. Rotate the blade as shown in the instruction.
2. Check if the blade is fixed with wiper arm correctly.



Notes

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
DAIHATSU						
ALTIS	2001-2005	ACV30N, ACV35N	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
ALTIS	2006-2010	ACV40N, ACV45N	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
ALTIS	2012-2017	AVV50N	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
ALTIS	2017-2023	AXVH70N, AXVH75N	DDP-026R/L	DDP-020R/L	DDS-026R/L	DDS-020R/L
APPLAUSE	1998-2000	A101S, A111S	DDP-019R/L +Screw clip	DDP-017R/L +Screw clip	DDS-019R/L +Screw clip	DDS-017R/L +Screw clip
ATLEY	1999-2005	S220G, S220V, S230G, S230V	DDP-019R/L	*7 DDP-014R/L	DDS-019R/L	*7 DDS-014R/L
ATLEY	2005-2021	S321G, S331G, S321G, S331G	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
ATLEY	2021-	S700V, S710V, S700W, S710W	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDPS-014R/L
ATLEY 7	2000-2004	S221G, S231G	DDP-019R/L	*7 DDP-014R/L	DDS-019R/L	*7 DDS-014R/L
BE-GO	2006-2016	J200G, J210G	DDP-021L	DDP-018R/L	DDS-021L	DDS-018R/L
BOON	2004-2010	M300S, M301S, M310S, M312S	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
BOON	2010-2016	M600S, M601S, M610S	DDP-021L	DDP-017R/L	DDS-021L	DDS-017R/L
BOON	2016-2018	M700S, M710S	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
BOON LUMINAS	2008-2012	M502G, M512G	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
CAST	2015-2023	LA250S, LA260S	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
CHARADE	1993-2000	G200S, G201S, G203S, G213S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
COO	2006-2013	M401S, M402S, M411S	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
COPEN	2002-2012	L880K	DDP-018R/L	*1 DDP-016R/L	DDS-018R/L	*1 DDS-016R/L
COPEN	2014-	LA400K	DDP-017R/L	DDP-018R/L	DDS-017R/L	DDS-018R/L
COPEN GR SPORT	2019-	LA400K	DDP-017R/L	DDP-018R/L	DDS-017R/L	DDS-018R/L
DELTA VAN/WAGON	1998-2001	CR40N, CR50N, SR40N	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
ESSE	2005-2011	L235S, L245S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
GRAN MAX (CARGO)	2020-2024	S403V, S413V	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
GRAN MAX (TRUCK)	2020-2024	S403P, S413P	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
HIJET CADDIE	2016-2017	LA700V, LA710V	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
HIJET TRUCK	1999-2014	S200P, S210P, S201P, S211P	DDP-016R/L	*1 DDP-016R/L	DDS-016R/L	*1 DDS-016R/L
HIJET TRUCK	2014-	S500P, S510P	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
DAIHATSU						
HIJET VAN/CARGO	1999-2004	S200V, S210V	DDP-019R/L	*7 DDP-014R/L	DDS-019R/L	*7 DDS-014R/L
HIJET VAN/CARGO	2004-2017	S320V, S321V, S330V, S331V	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
HIJET VAN/CARGO	2017-2021	S321V, S331V, S321W, S331W	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
HIJET VAN/CARGO	2021-	S700V, S710V, S700W, S710W	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
MAX	2001-2005	L950S, L952S, L960S, L962S	*7 DDP-020R/L	DDP-014R/L	DDS-021L	DDS-014R/L
MEBIUS	2013-2021	ZVW41N	DDP-028R/L	DDP-014R/L	*2	DDS-014R/L
MIDGET II	1999-2001	K100C, K100P	*1 DDP-019R/L	-	*1 DDS-019R/L	-
MIRA	1998-2000	L700S, L700V, L710S, L710V	DDP-018R/L	*7 DDP-014R/L	DDS-018R/L	*7 DDS-014R/L
MIRA	2002-2006	L250S, L250V, L260S, L260V	*7 DDP-020R/L	*2	DDS-021L	*2
MIRA	2006-2018	L275S, L285S, L275V, L285V	DDP-022R/L	*2	DDS-022R/L	*2
MIRA AVY	2002-2006	L250S, L250V, L260S, L260V	*7 DDP-020R/L	*2	DDS-021L	*2
MIRA COCOA	2009-2018	L675S, L685S	DDP-018R/L	*1 DDP-018R/L	DDS-018R/L	*1 DDS-018R/L
MIRA E:S	2011-2017	LA300S, LA310S	*1 DDP-020R/L	DDP-014R/L	*1 DDS-020R/L	DDS-014R/L
MIRA E:S	2017-	LA350S, LA360S	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
MIRA GINO	1999-2004	L700S, L710S	DDP-018R/L	*7 DDP-014R/L	DDS-018R/L	*7 DDS-014R/L
MIRA GINO	2004-2009	L650S, L660S	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
MIRA GINO 1000	2002-2004	L701S, L711S	DDP-018R/L	*7 DDP-014R/L	DDS-018R/L	*7 DDS-014R/L
MIRA TOCOT	2018-2023	LA550S, LA560S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
MOVE (INCL. CUSTOM)	1999-2002	L900S, L902S, L910S, L912S	DDP-019R/L	DDP-017R/L	DDS-019R/L	DDS-017R/L
MOVE (INCL. CUSTOM)	2002-2006	L150S, L152S, L160S	DDP-020R/L	*1 DDP-016R/L	DDS-020R/L	*1 DDS-016R/L
MOVE (INCL. CUSTOM)	2006-2010	L175S, L185S	DDP-022R/L	*1 DDP-016R/L	DDS-022R/L	*1 DDS-016R/L
MOVE (INCL. CUSTOM)	2010-2014	LA100S, LA110S	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
MOVE (INCL. CUSTOM)	2014-	LA150S, LA160S	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
MOVE CANVAS	2016-2022	LA800S, LA810S	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
MOVE CANVAS	2022-	LA850S, LA860S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
MOVE CONTE	2008-2017	L575S, L585S	DDP-018R/L	*1 DDP-018R/L	DDS-018R/L	*1 DDS-018R/L
MOVE TERA	2004-2009	L550S, L560S	DDP-019R/L	DDP-017R/L	DDS-019R/L	DDS-017R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
DAIHATSU						
NAKED	1999-2004	L750S, L760S	DDP-018R/L	DDP-017R/L	DDS-018R/L	DDS-017R/L
OPTI	1998-2002	L800S, L802S, L810S	DDP-018R/L	*1 DDP-014R/L	DDS-018R/L	*1 DDS-014R/L
PYZAR	1998-2002	G301G, G303G, G311G, G313G	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
ROCKY	2019-	A200S, A201S, A202S, A210S	DDP-021L	*2	DDS-021L	*2
SONICA	2006-2009	L405S, L415S	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
STORIA	1998-2004	M100S, M101S, M110S, M111S, M112S	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
TAFT	2020-	LA900S, LA910S	DDP-016R/L	DDP-017R/L	DDS-016R/L	DDS-017R/L
TANTO (INCL. CUSTOM)	2003-2007	L350S, L360S	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
TANTO (INCL. CUSTOM)	2007-2013	L375S, L385S	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
TANTO (INCL. CUSTOM)	2013-2019	LA600S, LA610S	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
TANTO (INCL. CUSTOM)	2016-	LA600S, LA610S	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
TANTO EXE	2009-2014	L455S, L465S	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
TANTO FUN CROSS	2022-	LA650S, LA660S	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
TERIOS	2000-2005	J102G, J122G	DDP-022R/L	*2	*1 DDS-022R/L	*2
TERIOS	1997-2000	J100G	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
TERIOS KID	1998-2000	J111G, J131G	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
TERIOS KID/LUCIA	2000-2012	J111G, J131G	DDP-022R/L	*2	*1 DDS-022R/L	*2
THOR (INCL. CUSTOM)	2016-	M900S, M910S	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
WAKE	2014-2022	LA700S, LA710S	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
YRV	2000-2005	M200G, M201G, M211G	*7 DDP-020R/L	DDP-014R/L	DDS-021L	DDS-014R/L
HINO						
DUTRO	1999-2011	N/A	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
DUTRO	2011-	XKU7#, XZC7#, XZU7#	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
DUTRO (STANDARD)	2011-	BZU6#, TRC6#, TRU6#, XKC6#, XKU6#, XZC6#, XZU6#	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
DUTRO (WIDE - WITH ADAS)	2017	XKU7#, XZC7#, XZU7#	DDP-022R/L	DDP-022R/L	DDS-022R/L	DDS-022R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
HINO						
DUTRO (WIDE - WITHOUT ADAS)	2011-	XKU7#, XZC7#, XZU7#	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
RANGER	1989-2001	All	*2	*2	*2	*2
RANGER	2011-2017	N/A	DDP-026R/L	*2	DDS-026R/L	*2
RANGER	2017-	FC, FD, FE, FJ, FX, GC, GD, GX	DDP-026R/L	*2	DDS-026R/L	*2
SUPER DOLPHIN PROFIA/PROFIA	1992-2003	N/A	*2	*2	*2	*2
SUPER DOLPHIN PROFIA/PROFIA	2003-2017	N/A	DDP-022R/L x 2	DDP-022R/L	DDS-022R/L x 2	DDS-022R/L
SUPER DOLPHIN PROFIA/PROFIA	2017-	FH, FN, FQ, FR, FS, FW, SH, SS	DDP-022R/L x 2	DDP-022R/L	DDS-022R/L x 2	DDS-022R/L
HONDA						
ACCORD (INCL. HYBRID)	1997-2002	CF3, CF4, CF5, CL1, CL3	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
ACCORD (INCL. HYBRID)	2002-2005	CL7, CL8, CL9	*4 DDP-026R/L	*1 DDP-014R/L	*4 DDS-026R/L	*1 DDS-014R/L
ACCORD (INCL. HYBRID)	2005-2008	CL7, CL8, CL9	DDP-026R/L +Side clip	*7 DDP-014R/L +Side clip	DDS-026R/L +Side clip	*7 DDS-014R/L +Side clip
ACCORD (INCL. HYBRID)	2008-2013	CU1, CU2	*3	DDP-022R/L	*3	DDS-022R/L
ACCORD (INCL. HYBRID)	2013-2020	CR5, CR6	*7 DDP-024R/L +Side clip	DDP-019R/L +Side clip	*7 DDS-024R/L +Side clip	DDS-019R/L +Side clip
ACCORD (INCL. HYBRID)	2020-2023	CV3	*3	DDP-016R/L	*3	DDS-016R/L
ACCORD (INCL. HYBRID)	2024-	CY2	*3	*3	*3	*3
ACCORD (INCL. HYBRID) (WITH ADAS)	2013-2020	CR5, CR6, CR7	*7 DDP-024R/L +Side clip	DDP-019R/L +Side clip	*7 DDS-024R/L +Side clip	DDS-019R/L +Side clip
ACCORD TOURER	2008-2013	CW1, CW2	*3	DDP-022R/L	*3	DDS-022R/L
ACCORD WAGON	1997-2002	CF6, CF7, CH9, CL2	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
ACCORD WAGON	2002-2005	CM1, CM2, CM3	*4 DDP-026R/L	*1 DDS-014R/L	*4 DDS-026R/L	*1 DDS-014R/L
ACCORD WAGON	2005-2008	CM1, CM2, CM3	DDP-026R/L +Side clip	*7 DDP-014R/L +Side clip	DDS-026R/L +Side clip	*7 DDS-014R/L +Side clip
ACTY	1999-2018	HH5, HH6	DDP-017R/L	*7 DDP-014R/L	DDS-017R/L	*7 DDS-014R/L
ACTY (TRUCK)	1999-2009	HA6, HA7	DDP-017R/L	*7 DDP-014R/L	DDS-017R/L	*7 DDS-014R/L
ACTY (TRUCK)	2009-2021	HA8, HA9	DDP-018R/L	DDP-017R/L	DDS-018R/L	DDS-017R/L
AIRWAVE	2005-2008	GJ1, GJ2	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
HONDA						
AIRWAVE	2008-2010	GJ1, GJ2	*3	*3	*3	*3
AVANCIER	1999-2003	TA1, TA2, TA3, TA4	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
CAPA	1998-2002	GA4, GA6	DDP-019R/L	DDP-017R/L	DDS-019R/L	DDS-017R/L
CIVIC FERIO (INCL. HYBRID) (4 DOOR)	1995-2000	EK2, EK3, EK4, EK5, EK8	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
CIVIC FERIO (INCL. HYBRID) (4 DOOR)	2000-2005	ES1, ES2, ES3, ES9, ET2	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
CIVIC HATCHBACK (INCL. HYBRID)	1995-2000	EK2, EK3, EK4	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
CIVIC HATCHBACK (INCL. HYBRID/TYPE R)	2017-2021	FK7, FK8	DDP-026R/L	DDP-018R/L +Side clip	DDS-026R/L	DDS-018R/L +Side clip
CIVIC (INCL. HYBRID)	2005-2007	FD1, FD2, FD3	*2	*2	*2	*2
CIVIC (INCL. HYBRID)	2007-2010	FD1, FD2, FD3	*3	*2	*3	*2
CIVIC (INCL. HYBRID/TYPE R)	2021-	FL1, FL4, FL5	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
CIVIC SEDAN (INCL. HYBRID)	2017-2020	FC1	DDP-026R/L	DDP-018R/L +Side clip	DDS-026R/L	DDS-018R/L +Side clip
CIVIC TYPE R (INCL. HYBRID) (EXCL. 5 DOOR)	2000-2003	EU1, EU2, EU3, EU4	DDP-024R/L	*7 DDP-014R/L	DDS-024R/L	*7 DDS-014R/L
CIVIC TYPE R (INCL. HYBRID) (EXCL. 5 DOOR)	2003-2005	EU3, EU4	DDP-024R/L	*7 DDP-014R/L	DDS-024R/L	*7 DDS-014R/L
CLARITY PHEV	2018-2021	ZC5	*3	*2	*3	*2
CROSSROAD	2007-2010	RT1, RT2, RT3, RT4	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
CR-V (INCL. HYBRID)	1995-2001	RD1, RD2	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
CR-V (INCL. HYBRID)	2001-2006	RD4, RD5, RD6, RD7	*7 DDP-020R/L	DDP-020R/L	DDS-021L	DDS-020R/L
CR-V (INCL. HYBRID)	2006-2011	RE3, RE4	*7 DDP-024R/L +Side clip	DDP-017R/L +Side clip	*7 DDS-024R/L +Side clip	DDS-017R/L +Side clip
CR-V (INCL. HYBRID)	2011-2016	RM1, RM4	DDP-026R/L +Side clip	DDP-016R/L +Side clip	DDS-026R/L +Side clip	DDS-016R/L +Side clip
CR-V (INCL. HYBRID)	2018-2020	RT5, RT6, RW1, RW2	DDP-026R/L +Side clip	DDP-016R/L +Side clip	DDS-026R/L +Side clip	DDS-016R/L +Side clip
CR-V (INCL. HYBRID)	2020-2022	RT5, RT6, RW1, RW2	*3	DDP-016R/L +Side clip	*3	*3
CR-Z	2010-2017	ZF1, ZF2	DDP-026R/L	DDP-020R/L	DDS-026R/L	DDS-020R/L
DOMANI	1997-2000	MB3, MB4, MB5	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
HONDA						
E	2020-2024	ZC7	*3	DDP-018R/L	*3	DDS-018R/L
EDIX	2004-2009	BE1, BE2, BE3, BE4, BE8	DDP-026R/L	DDP-019R/L	DDS-026R/L	DDS-019R/L
ELEMENT	2003-2005	YH2	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
ELYSION	2004-2013	RR1, RR2, RR3, RR4, RR5, RR6	DDP-026R/L	*2	DDS-026R/L	*2
FIT (INCL. HYBRID)	2001-2007	GD1, GD2, GD3, GD4	DDP-020R/L	*7 DDP-014R/L	DDS-020R/L	*7 DDS-014R/L
FIT (INCL. HYBRID)	2007-2013	GE6, GE7, GE8, GE9, GP1, GP4	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
FIT (INCL. HYBRID)	2013-2020	GK3, GK4, GK5, GK6, GP5, GP6	DDP-026R/L +Side clip	DDP-014R/L	DDS-026R/L +Side clip	DDS-014R/L
FIT (INCL. HYBRID)	2020-	GR1, GR2, GR3, GR4, GR5, GR6, GR7, GR8	*8 DDP-026R/L +Side clip	*7 DDP-014R/L	*8 DDS-026R/L +Side clip	*7 DDS-014R/L
FIT ARIA	2002-2009	GD6, GD7, GD8, GD9	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
FIT SHUTTLE (INCL. HYBRID)	2011-2015	GG7, GG8, GP2	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
FREED	2024-	GT1, GT2, GT3, GT4, GT5, GT6, GT7, GT8	*8 DDP-026R/L +Side clip	*2	*8 DDS-026R/L +Side clip	*3
FREED (INCL. HYBRID)	2016-2024	GB5, GB6, GB7, GB8	DDP-026R/L	*7 DDP-014R/L	DDS-026R/L	*7 DDS-014R/L
FREED/FREED SPIKE (INCL. HYBRID)	2008-2016	GB3, GB4, GP3	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
GRACE	2014-2017	GM4, GM5, GM6, GM9	*7 DDP-024R/L +Side clip	*6 DDP-014R/L +Side clip	*7 DDS-024R/L +Side clip	*6 DDS-014R/L +Side clip
GRACE	2017-2020	GM4, GM5, GM6, GM9	*7 DDP-024R/L +Side clip	*6 DDP-014R/L +Side clip	*7 DDS-024R/L +Side clip	*6 DDS-014R/L +Side clip
HR-V	1998-2006	GH1, GH2, GH3, GH4	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
INSIGHT	2009-2011	ZE2	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
INSIGHT	2011-2014	ZE2, ZE3	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
INSIGHT	2018-2022	ZE4	*3	DDP-018R/ L+Side clip	*3	DDS-018R/ L+Side clip
INSPIRE	1998-2003	UA4, UA5	*3	*1 DDP-019R/L	*3	*1 DDS-019R/L
INSPIRE	2003-2007	UC1	*4 DDP-026R/L	DDP-018R/L	*4 DDS-026R/L	DDS-018R/L
INSPIRE	2007-2010	CP3	*3	*3	*3	*3
INTEGRA	1993-2001	DB6, DB7, DB8, DB9, DC1, DC2	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
INTEGRA	2001-2006	DC5	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
INTEGRA SJ	1996-2001	EK3	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
HONDA						
JADE (INCL. HYBRID)	2015-2020	FR4, FR5	DDP-028R/L +Side clip	*2	*2	*2
JADE (INCL. HYBRID) (WITH ADAS)	2015-2020	FR4, FR5	DDP-028R/L +Side clip	*2	*2	*2
LAGREAT	1999-2004	RL1	DDP-024R/L	*7 DDP-020R/L	DDS-024R/L	DDS-021L
LEGEND	1990-2004	KA7, KA8, KA9	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
LEGEND	2004-2012	KB1, KB2	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
LEGEND	2015-2022	KC2	DDP-026R/L	DDP-020R/L	DDS-026R/L	DDS-020R/L
LIFE	1998-2003	JB1, JB2	DDP-019R/L	DDP-014R/L	DDS-019R/L	DDS-014R/L
LIFE	2003-2008	JB5, JB6, JB7, JB8	*7 DDP-020R/L	*2	DDS-021L	*2
LIFE	2008-2014	JC1, JC2	DDP-021L	*2	DDS-021L	*2
LIFE DUNK	2000-2003	JB3, JB4	DDP-019R/L	DDP-014R/L	DDS-019R/L	DDS-014R/L
LOGO	1999-2001	GA3, GA5	DDP-019R/L	DDP-017R/L	DDS-019R/L	DDS-017R/L
MDX	2003-2006	YD1	*4 DDP-024R/L	*7 DDP-020R/L	*4 DDS-024R/L	DDS-021L
MOBILIO	2001-2008	GB1, GB2	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
MOBILIO SPIKE	2002-2008	GK1, GK2	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
N-BOX	2011-2017	JF1, JF2	DDP-018R/L	DDP-017R/L	DDS-018R/L	DDS-017R/L
N-BOX	2017-2023	JF3, JF4	DDP-019R/L	DDP-017R/L	DDS-019R/L	DDS-017R/L
N-BOX	2023-	JF5, JF6	DDP-019R/L	DDP-017R/L	*1	DDS-017R/L
N-BOX SLASH (INCL. CUSTOM)	2014-2020	JF1, JF2	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
N-BOX+ (INCL. CUSTOM)	2012-2018	JF1, JF2	DDP-018R/L	DDP-017R/L	DDS-018R/L	DDS-017R/L
N-ONE	2012-2020	JG1, JG2	DDP-019R/L	*1 DDP-014R/L	DDS-019R/L	*1 DDS-014R/L
N-ONE	2020-	JG3, JG4	DDP-019R/L	*7 DDP-014R/L	DDS-019R/L	*7 DDS-014R/L
NSX	2017-2022	NC1	N/A	N/A	N/A	N/A
N-VAN (LOW ROOF)	2018-2021	JJ1, JJ2	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
N-VAN (HIGH ROOF)	2018-	JJ1, JJ2	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
N-WGN (INCL. CUSTOM)	2013-2019	JH1, JH2	DDP-021L	DDP-014R/L	DDS-021L	DDS-014R/L
N-WGN (INCL. CUSTOM)	2019-	JH3, JH4	DDP-021L	DDP-014R/L	DDS-021L	DDS-014R/L
ODYSSEY (INCL. HYBRID)	1999-2003	RA6, RA7, RA8, RA9	DDP-024R/L	*2	DDS-024R/L	*2

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
HONDA						
ODYSSEY (INCL. HYBRID)	2003-2008	RB1, RB2	*2	*1 DDP-014R/L	*2	*1:DDS-014R/L
ODYSSEY (INCL. HYBRID)	2008-2013	RB3, RB4	*7 DDP-024R/L+Side clip	*3	*7 DDS-024R/L+Side clip	*3
ODYSSEY (INCL. HYBRID)	2013-2022	RC1, RC2, RC4	*7 DDP-026R/L+Side clip	*6 • *7 DDP-014R/L+Side clip	*7 DDS-026R/L+Side clip	*6 • *7 DDS-014R/L+Side clip
ODYSSEY (INCL. HYBRID)	2023-	RC5	*2	*3	*2	*3
ORTHIA	1996-2002	EL1, EL2, EL3	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
PARTNER	1996-2006	EY6, EY7, EY8, EY9	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
PARTNER	2006-2010	GJ3, GJ4	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
PRELUDE	1996-2000	BB5, BB6, BB7, BB8	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
S2000	1999-2009	AP1, AP2	DDP-016R/L	*1 DDP-020R/L	DDS-016R/L	*1 DDS-020R/L
S660	2015-2022	JW5	*7 DDP-019R/L+Side clip	*3	*7 DDS-019R/L+Side clip	*3
SAVER	1998-2003	UA4, UA5	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
SHUTTLE (INCL. HYBRID)	2015-2022	GK8, GK9, GP7, GP8	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
S-MX	1996-2002	RH1, RH2	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
STEP WAGON (INCL. HYBRID)	1996-2001	RF1, RF2	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
STEP WAGON (INCL. HYBRID)	2003-2005	RF3, RF4, RF5, RF6, RF7, RF8	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
STEP WAGON (INCL. HYBRID)	2005-2007	RG1, RG2, RG3, RG4	*3	DDP-014R/L+Side clip	*3	DDS-014R/L+Side clip
STEP WAGON (INCL. HYBRID)	2007-2009	RG1, RG2, RG3, RG4	DDP-026R/L+Side clip	DDP-014R/L+Side clip	DDS-026R/L+Side clip	DDS-014R/L+Side clip
STEP WAGON (INCL. HYBRID)	2009-2015	RK1, RK2, RK3, RK4, RK5, RK6, RK7	*7 DDP-026R/L+Side clip	*6 • *7 DDP-014R/L+Side clip	*7 DDS-026R/L+Side clip	*6 • *7 DDS-014R/L+Side clip
STEP WAGON (INCL. HYBRID)	2015-2022	RP1, RP2, RP3, RP4, RP5	*7 • *8 DDP-026+Side clip	*6 DDP-014R/L+Side clip	*7 • *8 DDS-026R/L+Side clip	*6 DDS-014R/L+Side clip
STEP WAGON (INCL. HYBRID)	2021-2023	RF3, RF4	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
STEP WAGON (INCL. HYBRID)	2022-	RP6, RP7, RP8	*3	*3	*3	*3
STREAM	2000-2006	RN1, RN2, RN3, RN4, RN5	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
STREAM	2006-2014	RN6, RN7, RN8, RN9	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
HONDA						
THAT'S	2002-2007	JD1, JD2	DDP-019R/L	DDP-014R/L	DDS-019R/L	DDS-014R/L
TORNEO	1997-2002	CF3, CF4, CF5, CL1, CL3	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
VAMOS	1999-2003	HM1, HM2	DDP-017R/L	*7 DDP-014R/L	DDS-017R/L	*7 DDS-014R/L
VAMOS	2003-2018	HM1, HM2	DDP-017R/L	*7 DDP-014R/L	DDS-017R/L	*7 DDS-014R/L
VAMOS HOBIO	2003-2018	HM3, HM4, HJ1, HJ2	DDP-017R/L	*7 DDP-014R/L	DDS-017R/L	*7 DDS-014R/L
VEZEL (INCL. HYBRID)	2013-2021	RU1, RU2, RU3, RU4	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
VEZEL (INCL. HYBRID)	2021-	RV3, RV4, RV5, RV6	DDP-022R/L	DDP-019R/L	*3	*3
WR-V	2024-	DG5	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
Z	1998-2022	PA1	DDP-019R/L	DDP-014R/L	DDS-019R/L	DDS-014R/L
ZEST	1996-2012	JE1, JE2	DDP-021L	*7 DDP-014R/L	*1 DDS-021R/L	*7 DDS-014R/L
ZR-V	2023-	RZ3, RZ4, RZ5, RZ6	*2	*2	*2	*2
HYUNDAI						
AVANTE MD	2010-		DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
GENESIS	2010-		DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
GENESIS COUPE	2008-		DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
GRANDEUR HG (5G)	2011-		DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
I30 (GD)	2011-		DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
I40	2011-		DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
NEW EQUUS	2009-		DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
NEW SANTA FE (DM)	2012-		DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
TUCSON IX	2009-		DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
VELOSTER	2011-		DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
VERACRUZ	2010-		DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
YF SONATA	2009-		DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
ISUZU						
ASKA	1997-2001	CJ2, CJ3	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
ELF (STANDARD)	1993-2023	NHR, NHS, NJR, NJS, NKR, NKS, NLR, NLS, NMR, NMS	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
ELF (STANDARD)	2007-2018	NHR, NHS, NJR, NJS, NKR, NKS, NLR, NLS, NMR, NMS	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
ELF (STANDARD)	2018-2023	NHR, NHS, NJR, NJS, NKR, NKS, NLR, NLS, NMR, NMS	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
ISUZU						
ELF (WIDE)	1993-2023	NNR, NNS, NPR, NPS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
ELF (WIDE)	2006-2018	NNR, NNS, NPR, NPS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
ELF (WIDE)	2018-2023	NNR, NNS, NPR, NPS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
FARGO (LD)	1995-2001	All	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
FARGO (LT)	1995-2001	All	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
FILLY	1997-2002	JALE50, JALWE50, JAPE50, JAPWE50, JATE50, JATWE50, JAVE50, JAVWE50	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
FORWARD	1995-2007		DDP-020R/L	DDP-019R/L(DDP-019R/L)	DDS-020R/L	DDS-019R/L(DDS-019R/L)
FORWARD	1995-2007		DDP-022R/L	*2	DDS-022R/L	*2
FORWARD	2007	FRR, FSR, FTR	DDP-022R/L	*2	DDS-022R/L	*2
FORWARD	2007-2023	FRR, FSR, FTR	DDP-020R/L	DDP-020R/L(DDP-019R/L)	DDS-020R/L	DDS-020R/L(DDS-019R/L)
GEMINI	1995-2000	MJ4, MJ5, MJ6	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
GIGA	1994-2016	CV#, CX#, CY#, EX#	DDP-022R/L	DDP-020R/L(DDP-020R/L)	DDS-022R/L	DDS-020R/L(DDS-020R/L)
GIGA	2015-	CYL, CYJ, CXG, CXZ	DDP-020R/L	DDP-020R/L(DDP-019R/L)	DDS-020R/L	DDS-020R/L(DDS-019R/L)
GIGA (TRACTOR)	2016-	EXD, EXY, EXZ	DDP-020R/L	DDP-020R/L(DDP-019R/L)	DDS-020R/L	DDS-020R/L(DDS-019R/L)
MOCO	2001-2012	E25	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
MOCO (EXCL. WIDE)	2012-	E26	DDP-022R/L	*8 DDP-019R/L	DDS-022R/L	*8 DDS-019R/L
MU/WIZARD	1998-2002	UES25EW, UES73EW	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
RODEO BIGHORN	1995-2002	UBS25DW, UBS26DW, UBS26GW, UBS69DW, UBS69GW, UBS73DW, UBS73GW	DDP-020R/L	DDP-022R/L	DDS-020R/L	DDS-022R/L
VEHICROSS	1997-2000	UGS25DW	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
KIA						
K3	2012-		DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
K5	2010-		DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
K7	2009-		DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
K9	2012-		DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
MOHAVE	2008-		DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
KIA						
NEW PRIDE (UB)	2011-		DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
NEW SPORTAGE R	2010-		DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
OPIRUS	2003-		DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
SORENTO R	2010-		DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
LEXUS						
CT	2011-2022	ZWA10	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
ES	2018-	AXZH10, AXZH11	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
GS (INCL. HYBRID)	2005-2011	GRS191, GRS196, GWS191, URS190, UZS190	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
GS (INCL. HYBRID)	2012-2020	ARL10, AWL10, GRL10, GRL11, GRL12, GRL15, GRL16, GWL10	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
HS	2009-2018	ANF10	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
IS (INCL. HYBRID)	2005-2013	GSE20, GSE21, GSE25	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
IS (INCL. HYBRID)	2013-	ASE30, AVE30, AVE35, GSE30, GSE31, GSE35	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LBX	2023-	MAYH10, MAYH15, GAYA16	*3	*3	*3	*3
LC (INCL. HYBRID)	2017-	GWZ100, URZ100	*3	*2	*3	*2
LM	2023-	TAWH15W	DDP-030R/L	DDP-014R/L	*2	DDS-014R/L
LS (INCL. HYBRID)	2006-2017	USF40, USF41, USF45, USF46, UVF45, UVF46	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
LS (INCL. HYBRID)	2017-	GVF50, GVF55, VXFA50VX FA55	*3	*2	*3	*2
LX	2015-2021	URJ201W	DDP-024R/L	DDP-022R/L	DDS-024R/L	DDS-022R/L
LX	2022-	VJA310W, VJH310W	DDP-024R/L	DDP-022R/L	DDS-024R/L	DDS-022R/L
NX (INCL. HYBRID)	2014-2018	AGZ10, AGZ15, AYZ10, AYZ15	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
NX (INCL. HYBRID)	2018-2021	AGZ10, AGZ15, AYZ10, AYZ15	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
NX (INCL. HYBRID)	2021-	AAZA20, AAZA25, AAZH20, AAZH25, AAZH26, TAZA25	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
RC (INCL. HYBRID)	2014-2025	ASC10, AVC10, GSC10	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
RX	2022-	AALH16, TALA10, TALA15, TALH17, AALH10, AALH15	*3	*3	*3	*3
RX (INCL. HYBRID)	2009-2015	AGL10W, GGL10W, GGL15W, GGL16W, GYL10W, GYL15W, GYL16W	DDP-026R/L	DDP-022R/L	DDS-026R/L	DDS-022R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
LEXUS						
RX (INCL. HYBRID)	2015-2022	AGL20W, AGL25W, GYL20W, GYL25W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
RX (INCL. HYBRID)	2017-2022	GYL26W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
RZ	2023-	XEBM15	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
SC	2005-2006	UZZ40	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
SC	2006-2010	UZZ40	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
MAZDA						
2	2019-	DJ5AS, DJ5FS, DJLFS, DJLAS	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
3 FASTBACK	2019-	BP5P, BP8P, BPEP, BPFJ3P, BPFJ3R, BP5R, BP8R, BPFJ3R, BPEK3R	*3	*3	*3	*3
3 SEDAN	2019-	BP5P, BP8P, BPEP, BPFJ3P, BPFJ3R, BP5R, BP8R, BPFJ3R, BPEK3R	*3	*3	*3	*3
6 SEDAN	2019-2024	GJEFP, GJ2AP, GJ2FP, GJ5FP	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
6 WAGON	2019-2024	GJEFW, GJ2AW, GJ2FW, GJ5FW	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
ATENZA SEDAN	2008-2012	GHEFP, GH5AP, GH5FP	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
ATENZA SEDAN	2012-2014	GJEFP, GJ2FP, GJ5FP	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
ATENZA SEDAN	2015-2018	GJEFP, GJ2AP, GJ2FP, GJ5FP	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
ATENZA SEDAN	2016-2018	GJEFP, GJ2AP, GJ2FP, GJ5FP	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
ATENZA SEDAN	2018-2019	GJEFP, GJ2AP, GJ2FP, GJ5FP	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
ATENZA SPORTS	2002-2007	GG3S, GGES	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
ATENZA SPORTS	2008-2012	GHEFS, GH5AS, GH5FS	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
ATENZA WAGON (INCL. SPORTS WAGON)	2002-2007	GYEW, GY3W	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
ATENZA WAGON (INCL. SPORTS WAGON)	2008-2012	GHEFW, GH5AW, GH5FW	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
ATENZA WAGON (INCL. SPORTS WAGON)	2012-2014	GJEFW, GJ2FW, GJ5FW	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
ATENZA WAGON (INCL. SPORTS WAGON)	2015-2018	GJEFW, GJ2AW, GJ2FW, GJ5FW	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
ATENZA WAGON (INCL. SPORTS WAGON)	2016-2018	GJEFW, GJ2AW, GJ2FW, GJ5FW	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
MAZDA						
ATENZA WAGON (INCL. SPORTS WAGON)	2018-2019	GJEFW, GJ2AW, GJ2FW, GJ5FW	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
AXELA SEDAN (INCL. HYBRID)	2003-2009	BK3P, BK5P, BKEP	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
AXELA SEDAN (INCL. HYBRID)	2009-2013	BL5FP, BLEFP, BLEAP, BLFFP	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
AXELA SEDAN (INCL. HYBRID)	2013-2016	BM5FP, BM5AP, BM6FJ, BYEFP	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
AXELA SEDAN (INCL. HYBRID)	2016-2019	BM2AP, BM2FP, BM5FP, BM5AP, BM6FJ, BMLFP, BYEFP	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
AXELA SPORTS	2003-2009	BK3P, BK5P, BKEP	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
AXELA SPORTS	2009-2013	BL5FW, BLEFW, BLEAW, BL3PW, BL6FJ, BLFFW, BL3FW	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
AXELA SPORTS	2013-2016	BM2FS, BM5FS, BM5AS, BMEFS	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
AXELA SPORTS	2016-2019	BM2AS, BM2FS, BM5FS, BM5AS, BMEFS, BMLFS	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
AZ OFFROAD	1998-2014	JM23W	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
AZ WAGON	1999-2003	MD11S, MD12S, MD21S, MD22S	DDP-018R/L	*7 DDP-014R/L	DDS-018R/L	*7 DDS-014R/L
AZ WAGON	2003-2007	MJ21S, MJ22S	DDP-019R/L	DDP-016R/L	DDS-019R/L	DDS-016R/L
AZ WAGON	2007-2008	MJ22S	DDP-019R/L	DDP-016R/L	DDS-019R/L	DDS-016R/L
AZ WAGON	2008-2012	MJ23S	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
BIANTE	2008-2018	CC3FW, CCEAW, CCEFW, CCFW	DDP-026R/L +Side clip	*7 DDP-014R/L +Side clip	DDS-026R/L +Side clip	*7 DDS-014R/L +Side clip
BONGO	1999-2020	SK82V, SKF2V, SKP2V, SKP2M, SLP2L, SLP2M, SLP2T, SLP2V	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
BONGO (TRUCK)	2020-	S403F, S413F	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
BONGO (VAN)	2020-	S403Z, S413Z	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
BONGO BRAWNY	1999-2010	SKE6V, SKF6V	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
BONGO BRAWNY (VAN)	2019-	GDH206M, TRH200M, GDH201M	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
BONGO FRIENDEE	1995-2005	SG5W, SGEW, SGE3, SGL3, SGL5, SGLR, SGLW	DDP-024R/L	*3	DDS-024R/L	*3
CAPELLA	1997-2002	GF8P, GFEP, GFER, GFFP	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
MAZDA						
CAPELLA WAGON (CAPELLA CARGO)	1997-2002	GW5R, GW8W, GWER, GWEW, GWFV	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
CAROL (INCL. HYBRID)	1998-2004	HB12S, HB22S, HB23S	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
CAROL (INCL. HYBRID)	2004-2009	HB24S	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
CAROL (INCL. HYBRID)	2009-2014	HB25S, HB35S	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
CAROL (INCL. HYBRID)	2015-2021	HB36S	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
CAROL (INCL. HYBRID)	2022-	HB37S, HB97S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
CX-3	2015-2016	DK5AW, DK5FW	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
CX-3	2016-	DK5##, DK8##, DKE##, DKL##	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
CX-30	2019-	DMEP, DMFP, DM8P, DMEJ3P	*3	*3	*3	*3
CX-5	2012-2017	KEEAW, KEEFW, KE2AW, KE2FW, KE5AW, KE5FW	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
CX-5	2015-2017	KEEAW, KEEFW, KE2AW, KE2FW, KE5AW, KE5FW	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
CX-5	2017-	KF2P, KF5P, KFEP	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
CX-60	2022-2024	KH3P, KH5P, KH3R3P, KH5S3P	*3	*3	*3	*3
CX-60	2024-	KH3P, KH5P, KH3R3P, KH5S3P	*3	*3	*3	*3
CX-7	2006-2011	ER3P	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
CX-8	2017-2023	KG2P, KG5P	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
CX-80	2024-	KL3P, KL3R3P, KL5S3P	*3	*3	*3	*3
DEMIO	1999-2002	DW3W, DW5W	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
DEMIO	2002-2007	DY3R, DY3W, DY5R, DY5W	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
DEMIO	2007-2014	DE3AS, DE3FS, DE5FS, DEJFS	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
DEMIO	2014-2016	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
DEMIO	2016-2017	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
DEMIO	2017-2019	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS, DJLAS	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
FAMILIA	1998-2003	BJ3P, BJ5P, BJEP, BJLS	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
MAZDA						
FAMILIA S-WAGON	1999-2003	BJ5W, BJ8W, BJFW	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
FAMILIA VAN	1999-2008	#Y11	*2	DDP-016R/L	*2	DDS-016R/L
FAMILIA VAN	2007-2018	BVY12, BVAY12, BVJY12, BVZNY12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
FAMILIA VAN	2018-	NCP160M, NCP165M	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
FLAIR (INCL. HYBRID)	2012-2017	MJ34S, MJ44S	DDP-020R/L	*7 DDP-014R/L	DDS-020R/L	*7 DDS-014R/L
FLAIR (INCL. HYBRID)	2017-2022	MJ55S, MJ95S	DDP-021L	*7 • *9 DDP-014R/L	DDS-021L	*7 • *9 DDS-014R/L
FLAIR (INCL. HYBRID)	2022-	MJ55S, MJ95S	DDP-022L	*2	DDS-021L	*2
FLAIR CROSSOVER (INCL. HYBRID)	2014-2015	MS31S, MS41S	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
FLAIR CROSSOVER (INCL. HYBRID)	2015-2018	MS41S	DDP-016R/L	DDP-017R/L	DDS-016R/L	DDS-017R/L
FLAIR CROSSOVER (INCL. HYBRID)	2020-	MS52S, MS92S	DDP-016R/L	DDP-017R/L	DDS-016R/L	DDS-017R/L
FLAIR WAGON (INCL. HYBRID)	2012-2013	MM21S	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
FLAIR WAGON (INCL. HYBRID)	2013-2018	MM32S, MM42S	*1 DDP-020R/L	DDP-017R/L	*1 DDS-020R/L	DDS-017R/L
FLAIR WAGON (INCL. HYBRID)	2018-2023	MM53S	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
FLAIR WAGON (INCL. HYBRID)	2020-2023	MM53S	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
FLAIR WAGON (INCL. HYBRID)	2023-	MM94S MM54S	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
LAPUTA	1999-2006	HP11S, HP12S, HP21S, HP22S	DDP-019R/L	DDP-016R/L	DDS-019R/L	DDS-016R/L
MILLENNIA/EUNOS 800	1993-2003	TA3A, TA3P, TA3Y, TA3Z, TA5A, TA5P, TA5Y, TAFP	*7 DDP-020R/L	DDP-020R/L	DDS-021L	DDS-020R/L
MPV	1999-2006	LW3W, LW5W, LWEW, LWFV	DDP-024R/L	*2	DDS-024R/L	*2
MPV	2006-2016	LY3P	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
MX-30	2020-	DREJ3P, DRH3P	*3	*3	*3	*3
PREMACY	1999-2005	CP8W, CPEW	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
PREMACY	2005-2010	CR3W, CREW	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
PREMACY	2010-2018	CWEAW, CWEFW, CWFFW	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
ROADSTER	1998-2005	NB6C, NB8C	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
ROADSTER	2005-2015	NCEC	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
MAZDA						
ROADSTER	2015-	ND5RC, NDERC, ND5RE, NDERE	DDP-018R/L	DDP-019R/L	DDS-018R/L	DDS-019R/L
RX-7	1991-2003	FD3S	DDP-020R/L	*1 DDP-020R/L	DDS-020R/L	*1 DDS-020R/L
RX-8	2003-2012	SE3P	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
SCRUM	1999-2005	DG52V, DG52W, DH52V, DH52W, DG62W, DG62V	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
SCRUM	2005-2015	DG64V, DG64W	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
SCRUM	2015-	DG17V, DG17W	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
SCRUM TRUCK	2005-2013	DG63T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
SCRUM TRUCK	2013-	DG16T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
SENTIA	1995-2000	HEEA, HEEP	*7 DDP-020R/L	DDP-020R/L	DDS-021L	DDS-020R/L
SPIANO	2002-2003	HF21S	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
SPIANO	2003-2008	HF21S	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
TITAN	2007-2023	LNR, LNS, LPR, LPS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
TITAN	2019-2023	LNR, LNS, LPR, LPS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
TITAN (LHR)	2024-	LHR87AF	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
TITAN (STANDARD)	2007-2019	LJR, LJS, LKR, LKS, LLR, LLS, LMR, LMS	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
TITAN (STANDARD)	2019-	LHR, LHS, LJR, LJS, LKR, LKS, LLR, LLS, LMR, LMS	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
TITAN (STANDARD/HI)	2023-	LJR88AF, LKR88AF, LKR88C, LKR88AC, LMR88C, LLR88AC, LMR88AC, LMR88C	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
TITAN (WIDE)	2007-2023	LNR, LNS, LPR, LPS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
TITAN (WIDE)	2019-2023	LNR, LNS, LPR, LPS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
TITAN (WIDE)	2023-	LPR88AC, LPR88YM, LNR88AC	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
TRIBUTE	2000-2005	EP3W, EPEW, EPFW	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
VERISA	2004-2015	DC5R, DC5W	DDP-022R/L	*7 DDP-014R/L	DDS-022R/L	*7 DDS-014R/L
MAZDA (FORD JP)						
FESTIVA WAGON	1999-2003	DW3WF, DW5WF	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
FREDA	1995-2000	SG5WF, SGE3F, SGEWF, SGL3F, SGL5F, SGLRF, SGLWF	DDP-024R/L	*3	DDS-024R/L	*3

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
MAZDA (FORD JP)						
IXION	1999-2001	CP8WF	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
LASER	1998-2001	BJ3PF, BJ5PF, BJ5WF, BJ8WF, BJEPF	*7 DDP-020R/L	*3	DDS-021L	*3
MITSUBISHI						
AIRTREK	2001-2005	CU2W, CU4W, CU5W	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
ASPIRE	1998-2002	EA1A, EC1A, EA7A, EC7A	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
CANTER (STANDARD)	1993-2010	All	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
CANTER (STANDARD)	2010-	FEA, FBA, FDA, FGA	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
CANTER (WIDE)	1993-2010	All	*7 DDP-020R/L	*3	DDS-021L	*3
CANTER (WIDE)	2010-	FEB, FEC, FGB	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
CHALLENGER	1996-2001	K94W, K94WG, K96W, K97WG, K99W	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
COLT	2002-2013	Z21A, Z22A, Z23A, Z24A, Z25A, Z26A, Z27A, Z27AG, Z28A	DDP-026R/L	*2	DDS-026R/L	*2
COLT PLUS	2004-2006	Z23W, Z24W, Z27W, Z27WG	DDP-026R/L	*2	DDS-026R/L	*2
COLT PLUS	2006-2012	Z21W, Z22W, Z23W, Z24W, Z27WG	DDP-026R/L	*2	DDS-026R/L	*2
DELICA D:2 (INCL. HYBRID)	2011-2015	MB15S	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
DELICA D:2 (INCL. HYBRID)	2015-2020	MB36S, MB46S	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
DELICA D:2 (INCL. HYBRID)	2020-2025	MB37S	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
DELICA D:2 (INCL. HYBRID)	2025-	MBD7S	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
DELICA D:3	2011-2019	BM20	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
DELICA D:5	2007-2019	CV1W, CV2W, CV4W, CV5W	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
DELICA D:5 (DIESEL)	2019-	CV1W	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
DELICA D:5 (GASOLINE)	2019	CV2W, CV5W	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
DELICA MINI	2023-	B34A B35A B37A B38A	DDP-020R/L	*7 DDP-014R/L	DDS-020R/L	*7 DDS-014R/L
DELICA SPACE GEAR	1994-2005	PA4W, PA5W, PB4W, PB5W, PB6W, PC4W, PC5W, PD4W, PD6W, PD8W, PE8W, PF6W, PF8W	*2	*2	*2	*2
DELICA SPACE GEAR	2005-2007	PD6W	*2	*2	*2	*2

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
MITSUBISHI						
DELICA VAN/CARGO	1999-2011	SK22VM, SK22MM, SK82VM, SKF2VM, SKE6VM, SKF6VM	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
DELICA VAN/CARGO	2011-2019	BVM20	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
DIAMANTE	1996-2005	F31A, F34A, F36A, F41A, F46A	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
DIAMANTE WAGON	1999-2001	F36W	*3	DDP-020R/L	*3	DDS-020R/L
DIGNITY	2012-2016	BHGY51	DDP-026R/L +Side clip	DDP-019R/L +Side clip	DDS-026R/L +Side clip	DDS-019R/L +Side clip
DION	2000-2002	CR6W, CR9W	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
DION	2002-2006	CR5W, CR6W, CR9W	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
ECLIPSE CROSS (INCL. PHEV)	2018-2020	GK1W, GK9W	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
ECLIPSE CROSS (INCL. PHEV)	2020-	GK1W, GL3W	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
EK CROSS	2019-	B34W, B35W, B37W, B38W	DDP-024R/L	*2	DDS-024R/L	*2
EK CROSS EV	2022-	B5AW	DDP-024R/L	*2	DDS-024R/L	*2
EK CROSS SPACE	2020-2023	B34A, B35A, B37A, B38A	DDP-020R/L	*2	DDS-020R/L	*2
EK SPACE	2014-2020	B11A	DDP-020R/L	*3	DDS-020R/L	*3
EK SPACE	2020-	B34A, B35A, B37A, B38A	DDP-020R/L	*2	DDS-020R/L	*2
EK WAGON (INCL. CUSTOM)	2001-2006	H81W	DDP-019R/L	DDP-014R/L	DDS-019R/L	DDS-014R/L
EK WAGON (INCL. CUSTOM)	2006-2013	H82W	DDP-019R/L	DDP-014R/L	DDS-019R/L	DDS-014R/L
EK WAGON (INCL. CUSTOM)	2013-2019	B11W	DDP-021L	DDP-014R/L	DDS-021L	DDS-014R/L
EK WAGON (INCL. CUSTOM)	2019-	B33W, B36W	DDP-024R/L	*2	DDS-024R/L	*2
EK WAGON (INCL. CUSTOM) (WITH ADAS)	2014-2019	B11W	DDP-024R/L	*2	DDS-024R/L	*2
FIGHTER	1992-	FK, FL, FM, FN	*2	*2	*2	*2
FIGHTER	2005-	FK, FL	DDP-026R/L	*2	DDS-026R/L	*2
GALANT	1996-2005	EA1A, EC1A, EA3A, EC3A, EC5A, EA7A, EC7A	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
GALANT FORTIS	2007-2015	CY3A, CY4A, CY6A	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
MITSUBISHI						
GRANDIS	1997-2003	N84W, N86W, N94W, N96W	*2	*3	*2	*3
GRANDIS	2003-2009	NA4W	*2	*2	*2	*2
GTO	1990-2001	Z15A, Z16A	*7 DDP-020R/L	DDP-020R/L	DDS-021L	DDS-020R/L
I	2006-2007	HA1W	*2	-	*2	-
I	2007-2009	HA1W	*2	-	*2	-
I	2009-2013	HA1W	*3	-	*3	-
I-MIEV	2009-2021	HA3W, HA4W, HD4W	*3	-	*3	-
I-MIEV	2009	HA3W	*2	-	*2	-
LANCER	1997-2000	CK1A, CK2A, CK4A, CK6A, CK8A, CM2A, CM5A, CM8A	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
LANCER	2003-2010	CS2A, CS5A, CS6A	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LANGER CARGO	2002-2008	CS2V	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LANCER CARGO	2008-2019	CVAY12, CVJY12, CVY12, CVZNY12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
LANCER CEDIA	2000-2003	CS2A, CS5A	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LANCER CEDIA WAGON	2000-2003	CS5W	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LANCER EVOLUTION (VII - IX)	2001-2007	CT9A	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LANCER EVOLUTION (X)	2007-2016	CZ4A	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
LANCER EVOLUTION WAGON	2005-2007	CT9W	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LANCER WAGON	2003-2008	CS2W, CS5W	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LEGNUM	1998-2002	EA1W, EA3W, EA4W, EA7W, EC1W, EC3W, EC5W, EC7W	*3	*3	*3	*3
LIBERO	1998-2002	CB2W, CB4W, CB5W, CB8W, CD5W	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
MINICA	1998-2011	H42A, H42V, H47A, H47V	DDP-018R/L	*7 DDP-014R/L	DDS-018R/L	*7 DDS-014R/L
MINICAB EV	2023-	U69V	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L
MINICAB MIEV	2011-2023	U67V, U68V	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L
MINICAB MIEV TRUCK	2012-2017	U68T	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L
MINICAB TRUCK	2014-	DS16T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
MINICAB/TOWN BOX (INCL. WIDE)	1999-2005	U61W, U62W, U63W, U64W, U65W, U66W, U6#V	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
mitsubishi						
MINICAB/TOWN BOX (INCL. WIDE)	2005-2014	U61W, U62W, U61V, U62V, U61T, U61TP, U62T, U62TP	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L
MINICAB/TOWN BOX (INCL. WIDE)	2014-2015	DS64V, DS64W	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
MINICAB/TOWN BOX (INCL. WIDE)	2015-	DS17V, DS17W	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
MIRAGE	2012-2020	A03A, A05A	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
MIRAGE	2020-2023	A03A	DDP-022R/L	*2	DDS-022R/L	*2
MIRAGE DINGO	1998-2002	CQ1A, CQ2A, CQ5A	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
MIRAGE SEDAN	1997-2000	CK1A, CK2A, CK4A, CK6A, CK8A, CM2A, CM5A, CM8A	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
OUTLANDER	2005-2012	CW4W, CW5W, CW6W	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
OUTLANDER	2012-2013	GF7W, GF8W	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
OUTLANDER	2014-2020	GF7W, GF8W	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
OUTLANDER PHEV	2013-2021	GG2W, GG3W	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
OUTLANDER PHEV	2021-	GN0W	*3	*3	*3	*3
PAJERO	1999-2006	V63W, V65W, V68W, V73W, V75W, V77W, V78W	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
PAJERO	2006-2009	V83W, V87W, V93W, V97W, V98W	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
PAJERO	2009-2019	V83W, V87W, V88W, V93W, V97W, V98W	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
PAJERO IO	1998-2007	H61W, H62W, H66W, H67W, H71W, H72W, H76W, H77W	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
PAJERO MINI	1998-2008	H53A, H58A	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
PAJERO MINI	1998-2013	H53A, H58A	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
PROUDIA	2012-2016	BY51, BKY51, BKNY51	DDP-026R/L +Side clip	DDP-019R/L +Side clip	DDS-026R/L +Side clip	DDS-019R/L +Side clip
ROSA	1997-2019	BE6#, BG6#	DDP-022R/L	*7 DDP-020R/L	DDS-022R/L	DDS-021L
ROSA	2019-	BE7#, BG7#	DDP-022R/L	*7 DDP-020R/L	DDS-022R/L	DDS-021L
RVR	1997-2002	N61W, N64WG, N71W, N73WG, N74WG	*2	DDP-016R/L	*2	DDS-016R/L
RVR	2010-2024	GA3W, GA4W	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
TOPPO	2008-2013	H82A	DDP-020R/L	*7 DDP-014R/L	DDS-020R/L	*7 DDS-014R/L
TOPPO BJ (INCL. WIDE)	1998-2001	H41A, H42A, H42V, H43A, H46A, H47A, H47V, H48A	DDP-020R/L	*7 DDP-014R/L	DDS-020R/L	*7 DDS-014R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
MITSUBISHI						
TOPPO BJ (INCL. WIDE)	2001-2004	H41A, H42A, H42V, H46A, H47A, H47V	DDP-020R/L	*7 DDP-014R/L	DDS-020R/L	*7 DDS-014R/L
TRITON	2006-2011	KB9T	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
TRITON	2024-	LC2T	*2	*2	*2	*2
MITSUOKA						
GALUE I	1999-2001	HK30	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
GALUE II	1999-2005	HY34, MY34	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
GALUE III	2005-2010	Y50, PY50, PNY50	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
NOUERA	2003-2008	CL7, CL8, CL9	*4 DDP-026R/L	*7 DDP-014R/L	*4 DDS-026R/L	*7 DDS-014R/L
NOUERA	2003-2008	CL7, CL8, CL9				
RAY	1996-2000	AC6P, AC6R, HB12S	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
TYPE-F	1996-2000	N/A	*2	*2	*2	*2
VIEWT	1996-2005	K11, K11, AK11, HK11	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
VIEWT	2005-2010	AK12, BNK12, YK12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
ZERO 1	1994-2000	MS01	*2	*2	*2	*2
NISSAN						
AD	2021-	VY12, VZNY12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
AD WAGON/VAN/MAX	2004-2008	Y11	*2	DDP-016R/L	*2	DDS-016R/L
AD WAGON/VAN/MAX	1999-2004	Y11	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
AD/AD EXPART	2006-2016	VAY12, VJY12, VY12, VZNY12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
ARIYA	2022-	FE0, SNFE0	*3	*3	*3	*3
ATLAS (F24)	2007-2021	F24	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
ATLAS (F25)	2019-2023	AHR, AHS	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
ATLAS (F25) (STANDARD)	2021-2023	AJR, ALS, ALR, AJS, AKR, AMR, AKS, AMS	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
ATLAS (F25) (WIDE)	2021-2023	ANR, APR, APS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
ATLAS (F26) (STANDARD)	2023-	AJR88AF, AKR88AF, AKR88C, AKR88AC, AMR88C, ALR88AC, AMR88AC, AJR88AT, AKR88AT	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
ATLAS (F26) (WIDE)	2023-	ANR88AC, APR88AC	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
ATLAS (H42) (STANDARD)	1995-2006	AKR, AKS	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
NISSAN						
ATLAS (H42) (WIDE)	1995-2006	AKR, AKS	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
ATLAS (H43) (STANDARD)	2007-2012	STD WIDE	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
ATLAS (H43) (WIDE)	2007-2012	WIDE	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
ATLAS MAX	1998-2001	AHR, AKR	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
AURA	2021-	FE13, FSNE13	DDP-026R/L +Side clip	DDP-014R/L	DDS-026R/L +Side clip	DDS-014R/L
AVENIR	1998-2005	PW11, PNW11, RW11, RNW11, SW11, W11	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
BASSARA	1999-2000	JU30, JNU30, JHU30, JVU30, JVNU30	DDP-026R/L	*7 DDP-020R/L	DDS-026R/L	DDS-021L
BASSARA	2000-2003	JTU30, JTNU30, JHU30, JU30, JNU30, JVU30, JVNU30	DDP-026R/L	*7 DDP-020R/L	DDS-026R/L	DDS-021L
BLUEBIRD	1996-2000	EU14, ENU14, HU14, HNU14, SU14, QU14	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
BLUEBIRD SYLPHY	2000-2005	QG10, QNG10, FG10, TG10	*2	DDP-016R/L	*2	DDS-016R/L
BLUEBIRD SYLPHY	2005-2012	G11, NG11, KG11	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
CARAVAN (EXCL. WIDE)	2021-	###E26	DDP-022R/L	*8 DDP-019R/L	DDS-022R/L	*8 DDS-019R/L
CARAVAN/HOMY	1997-2001	KRE24, KRME24, KRGE24	DDP-019R/L	*3	DDS-019R/L	*3
CARAVAN/HOMY	2001-2003	CQGE25, CWGE25, CWMGE25, QGE25	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
CARAVAN/HOMY	2003-2012	SE25, SGE25, QE25, QGE25, VPE25, VWE25, VWME25	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
CEDRIC/GLORIA	1999-2004	MY34, ENY34, HY34	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
CEFIRO	1998-2003	A33, PA33	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
CEFIRO WAGON	1998-2003	WPA32, WHA32, WA32	DDP-022R/L	*7 DDP-020R/L	DDS-022R/L	DDS-021L
CIMA	1998-2000	FGY33, FHY33, FGDY33, FGN33	*3	*3	*3	*3
CIMA	2001-2010	GF50, GNF50, HF50	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
CIMA	2012-2022	HGY51	DDP-026R/L +Side clip	DDP-019R/L +Side clip	DDS-026R/L +Side clip	DDS-019R/L +Side clip
CIMA (WITH ADAS)	2012-2022	HGY51	DDP-026R/L +Side clip	DDP-019R/L +Side clip	DDS-026R/L +Side clip	DDS-019R/L +Side clip
CIVILIAN	1999-2021	ECW41, EVW41, DCW41, DVW41, EJW41, EHW41, DJW41, DHW41	DDP-024R/L	DDP-024R/L	DDS-024R/L	DDS-024R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
NISSAN						
CLIPPER EV	2024-	U79V	DDP-017R/L	DDP-015R/L	DDS-017R/L	DDS-015R/L
CLIPPER TRUCK (NT100)	2024-	DR16T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
CLIPPER VAN/TRUCK	2003-2005	U71W, U72W, U71V, U72V, U71T, U71TP, U72T, U72TP	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L
CLIPPER VAN/TRUCK (INCL. RIO)	2006-2012	U71W, U72W, U71V, U72V, U71T, U71TP, U72T, U72TP	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L
CLIPPER VAN/WAGON (NV100)	2024-	DR17V, DR17W	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
CREW	1994-2009	HK30, SK30	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
CUBE/CUBE CUBIC	1999-2000	Z10, AZ10, ANZ10	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
CUBE/CUBE CUBIC	2000-2002	AZ10, ANZ10	DDP-022R/L	*7 DDP-014R/L	DDS-022R/L	*7 DDS-014R/L
CUBE/CUBE CUBIC	2002-2008	BZ11, BNZ11, YZ11, BGZ11, YGZ11, YGNZ11	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
CUBE/CUBE CUBIC	2008-2020	Z12, NZ12	*2	*2	*2	*2
DATSUN TRUCK	1999-2002	LFD22, LFMD22, LRMD22	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
DAYS	2013-2019	B21W	DDP-021L	DDP-014R/L	DDS-021L	DDS-014R/L
DAYS (WITH ADAS)	2014-2019	B21W	DDP-024R/L	*2	DDS-024R/L	*2
DAYS	2019-	B43W, B44W, B45W, B46W, B47W, B48W	DDP-024R/L	*2	DDS-024R/L	*2
DAYS ROOX	2014-2020	B21A	DDP-020R/L	*3	DDS-020R/L	*3
DUALIS	2007-2014	J10, KJ10, NJ10, KNJ10	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
ELGRAND	1997-2002	ALE50, ALWE50, APE50, APWE50, ATE50, ATWE50, FLGE50, FLWGE50	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
ELGRAND	2002-2010	E51, ME51, MNE51, NE51	DDP-026R/L	*1 DDP-016R/L	DDS-026R/L	*1 DDS-016R/L
ELGRAND	2010-	PE52, PNE52, TE52, TNE52	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
EXPERT	1999-2006	VW11, VNW11, VEW11, VENW11	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
EXTRAIL (INCL. HYBRID)	2022-	SNT33, T33	*3	*3	*3	*3
FAIRLADY Z	1993-2000	Z32, GZ32, CZ32, GCZ32, HZ32	*7 DDP-020R/L	*3	DDS-021L	*3
FAIRLADY Z	2002-2008	Z33, HZ33	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
FAIRLADY Z	2008-2012	Z34, HZ34	DDP-021L +Side clip	DDP-019RL +Side clip	DDS-021R/L +Side clip	DDS-019R/L +Side clip

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
NISSAN						
FAIRLADY Z	2008-2022	Z34, HZ34	DDP-021L +Side clip	DDP-019R/L +Side clip	DDS-021R/L +Side clip	DDS-019R/L +Side clip
FAIRLADY Z	2022-	RZ34	DDP-021L +Side clip	DDP-019R/L +Side clip	DDS-021R/L +Side clip	DDS-019R/L +Side clip
FUGA (INCL. HYBRID)	2004-2009	Y50, PY50, GY50, PNY50	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
FUGA (INCL. HYBRID)	2009-2010	KNY51, KY51, Y51	*3	*3	*3	*3
FUGA (INCL. HYBRID)	2010-2022	HY51, KNY51, KY51, Y51	DDP-026R/L +Side clip	DDP-019R/L +Side clip	DDS-026R/L +Side clip	DDS-019R/L +Side clip
GT-R	2007-2025	R35	N/A	N/A	N/A	N/A
JUKE	2010-2020	YF15, F15, NF15	*2	*2	*2	*2
KICKS	2008-2012	H59A	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
KICKS E-POWER	2020-	P15	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
LAFESTA (INCL. JOY)	2004-2012	B30, NB30	*2	*2	*2	*2
LAFESTA HIGHWAY STAR	2011-2018	CWEAWN, CWEFWN, CWFFWN	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
LATIO	2012-2016	N17	DDP-021L	DDP-014R/L	DDS-021L	DDS-014R/L
LAUREL	1997-2002	HC35, GC35, GNC35, GCC35, SC35	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
LEAF	2010-2017	ZE0, AZE0	DDP-026R/L +Side clip	*7 DDP-014R/L +Side clip	DDS-026R/L +Side clip	*7 DDS-014R/L +Side clip
LEAF	2017-	ZE1	DDP-026R/L +Side clip	DDP-016R/L +Side clip	DDS-026R/L +Side clip	DDS-016R/L +Side clip
MARCH	1995-2002	K11, AK11, ANK11, HK11, FHK11	*3	*3	*3	*3
MARCH	2002-2003	K12, AK12, BK12, BNK12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
MARCH	2003-2010	AK12, BK12, BNK12, YK12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
MARCH	2010-2022	K13, NK13	DDP-021L	DDP-014R/L	DDS-021L	DDS-014R/L
MICRA C+C	2007-2010	FHZK12	*2	*2	*2	*2
MOCO	2002-2004	MG21S	*7 DDP-020R/L	*2	DDS-021L	*2
MOCO	2004-2006	MG21S	*7 DDP-020R/L	*2	DDS-021L	*2
MOCO	2006-2011	MG22S	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
MOCO	2011-2016	MG33S	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
MURANO	2004-2008	TZ50, PZ50, PNZ50	*3	DDP-018R/L +Side clip	*3	DDS-018R/L +Side clip

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
NISSAN						
MURANO	2008-2015	TNZ51, PNZ51, TZ51	*3	DDP-016R/ L+Side clip	*3	DDS-016R/ L+Side clip
NOTE (INCL. E-POWER)	2005-2012	E11, NE11, ZE11	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
NOTE (INCL. E-POWER) (E12)	2012-2021	E12, HE12, NE12, SNE12	DDP-026R/L +Side clip	*2	DDS-026R/L +Side clip	*2
NOTE (INCL. E-POWER) (E13)	2020-	E13, SNE13	DDP-026R/L +Side clip	DDP-014R/L	DDS-026R/L +Side clip	DDS-014R/L
NT100 CLIPPER TRUCK	2012-2013	U71T, U71TP, U72T, U72TP	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L
NT100 CLIPPER TRUCK	2013-2024	DR16T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
NT100 CLIPPER TRUCK	2019-2024	DR16T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
NT45 ATLAS (H44) (STANDARD)	2013-2021	FBA, FDA, FEA, FGA	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
NT45 ATLAS (H44) (WIDE)	2013-2021	FEB, FGB	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
NV100 CLIPPER (INCL. RIO)	2012-2013	U71V, U72V, U71W, U72W	DDP-017R/L	*1 DDP-014R/L	DDS-017R/L	*1 DDS-014R/L
NV100 CLIPPER (INCL. RIO)	2013-2015	DR64V, DR64W	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
NV100 CLIPPER (INCL. RIO)	2015-2024	DR17V, DR17W	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
NV100 CLIPPER (INCL. RIO)	2019-2024	DR17V, DR17W	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
NV150 AD	2016-2021	VY12, VZNY12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
NV200 VANNET	2009-	M20, VM20, VNM20	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
NV350 CARAVAN (EXCL. WIDE)	2012-2022	###E26	DDP-022R/L	*8 DDP-019R/L	DDS-022R/L	*8 DDS-019R/L
OTTI	2005-2006	H91W	DDP-019R/L	DDP-014R/L	DDS-019R/L	DDS-014R/L
OTTI	2006-2013	H92W	DDP-019R/L	DDP-014R/L	DDS-019R/L	DDS-014R/L
PINO	2007-2010	HC24S	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
PRAIRIE/LIBERTY	1998-2004	PM12, PNM12, RM12, RNM12	*1 DDP-028R/L	*7 DDP-014R/L	*2	*7 DDS-014R/L
PRESEA	1995-2000	R11, HR11, PR11	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
PRESAGE	1998-2000	U30, NU30, HU30, VU30, VNU30	*3	*3	*3	*3
PRESAGE	2000-2003	TU30, TNU30, HU30, U30, NU30, VU30, VNU30	*3	*3	*3	*3
PRESAGE	2003-2009	TU31, TNU31, PU31, PNU31	DDP-028R/L	DDP-016R/L	*2	DDS-016R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
NISSAN						
PRIMER/PRIMERA CAMINO	2001-2005	HP12, TP12, TNP12, QP12, RP12	*1 DDP-026R/L	DDP-019R/L	*1 DDS-026R/L	DDS-019R/L
PRIMER/PRIMERA CAMINO	1995-2000	P11, FHP11, HP11, HNP11, QP11	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
PRIMERA WAGON/ PRIMERA CAMINO WAGON	2000-2000	WQP11, WHP11, WHNP11	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
PRIMERA WAGON/ PRIMERA CAMINO WAGON	2001-2005	WTP12, WTNP12, WRP12, WHP12	*1 DDP-026R/L	DDP-019R/L	*1 DDS-026R/L	DDS-019R/L
PULSAR/LANGLEY HATCHBACK	1995-2000	FN15, FNN15, EN15, JN15, HN15	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
PULSAR/LANGLEY SEDAN	1995-2000	FN15, FNN15, SN15, SNN15, EN15, JN15, HN15	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
PULSAR/LANGLEY (5 DOOR)	1995-2000	N15	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
PULSAR SERIE S-RV	1996-2000	FN15, FNN15, JN15, HNN15	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
RASHEEN	1994-2000	RKNB14, RFNB14	*3	DDP-020R/L	*3	DDS-020R/L
R'NESSA	1998-2001	N30, NN30, PNN30	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
ROOX	2009-2010	ML21S	DDP-021L	DDP-016R/L	DDS-021L	DDS-016R/L
ROOX	2010-2013	ML21S	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
ROOX	2020-	B44A, B45A, B47A, B48A	DDP-020R/L	*2	DDS-020R/L	*2
SAFARI	1997-2007	WFGY61, WTY61, VRGY61, WGY61, WYY61	DDP-019R/L	DDP-020R/L	DDS-019R/L	DDS-020R/L
SAKURA	2022-		DDP-024R/L	*3	DDS-024R/L	*3
SERENA (INCL. HYBRID)	1999-2001	PC24, PNC24, VC24, VNC24	*2	DDP-014R/L	*2	DDS-014R/L
SERENA (INCL. HYBRID)	2001-2005	TC24, TNC24, RC24	*2	DDP-014R/L	*2	DDS-014R/L
SERENA (INCL. HYBRID)	2005-2010	C25, NC25, CC25, CNC25	DDP-026R/L	*2	DDS-026R/L	*2
SERENA (INCL. HYBRID)	2010-2013	C26, FC26, NC26, FNC26, HC26, HFC26	DDP-026R/L	*2	DDS-026R/L	*2
SERENA (INCL. HYBRID)	2013-2016	C26, NC26, FNC26, HC26, HFC26	DDP-026R/L +Side clip	DDP-014R/L +Side clip	DDS-026R/L +Side clip	DDS-014R/L +Side clip
SERENA (INCL. HYBRID)	2016-2022	C27, GC27, GFC27, GFNC27, GNC27, HC27, HFC27	*7 DDP-024R/L + Side clip	DDP-014R/L +Side clip	*7 DDS-024R/L +Side clip	DDS-014R/L +Side clip
SERENA (INCL. HYBRID)	2022-	C28 FC28 FNC28 GC28 GFC28 NC28 SFNC28 SNC28	*7 DDP-024R/L +Side clip	DDP-014R/L +Side clip	*7 DDS-024R/L +Side clip	DDS-014R/L +Side clip
SILVIA	1999-2002	S15	*7 DDP-020R/L	DDP-020R/L	DDS-021L	DDS-020R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS		
			Driver	Passenger	Driver	Passenger	
			P/N	P/N	P/N	P/N	
NISSAN							
SKYLINE	1998-2000	ER34, BNR34, ENR34, HR34	*7 DDP-020R/L	*7 DDP-020R/L	DDS-021L	DDS-021L	
SKYLINE	2000-2001	BNR34, HR34, ER34, ENR34	*7 DDP-020R/L	*7 DDP-020R/L	DDS-021L	DDS-021L	
SKYLINE	2001-2006	V35, NV35, PV35, HV35	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L	
SKYLINE	2006-2010	V36, NV36, KV36, PV36	DDP-024R/L +Side clip	*7 DDP-016R/L +Side clip	DDS-024R/L +Side clip	*7 DDS-016R/L +Side clip	
SKYLINE	2011-2014	V36, NV36, KV36, PV36	DDP-024R/L +Side clip	*7 DDP-016R/L +Side clip	DDS-024R/L +Side clip	*7 DDS-016R/L +Side clip	
SKYLINE (INCL. HYBRID)	2014-	HV37, HNV37, ZV37	DDP-026R/L +Side clip	DDP-017R/L +Side clip	DDS-026R/L +Side clip	DDS-017R/L +Side clip	
SKYLINE (INCL. HYBRID) (WITH ADAS)	2014-	HV37, HNV37, RV37, YV37, ZV37	DDP-026R/L +Side clip	DDP-017R/L +Side clip	DDS-026R/L +Side clip	DDS-017R/L +Side clip	
SKYLINE COUPE	2003-2007	CPV35	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L	
SKYLINE COUPE	2007-2010	CKV36	DDP-024R/L +Side clip	*7 DDP-016R/L +Side clip	DDS-024R/L +Side clip	*7 DDS-016R/L +Side clip	
SKYLINE COUPE	2011-2016	CKV36	*3	*3	*3	*3	
SKYLINE CROSSOVER	2009-2011	J50, NJ50	*7 DDP-024R/L +Side clip	*7 DDP-017R/L +Side clip	*7 DDS-022R/L +Side clip	*7 DDS-017R/L +Side clip	
SKYLINE CROSSOVER	2011-2012	J50, NJ50	*7 DDP-022R/L +Side clip or *2	*7 DDP-017R/L +Side clip or *2	*7 DDS-022R/L +Side clip or *2	*7 DDS-017R/L +Side clip or *2	
SKYLINE CROSSOVER	2012-2016	J50, NJ50	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L	
STAGEA	1999-2001	WHC34, WGC34, WGNC34	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L	
STAGEA	2001-2007	M35, NM35, PM35, PNM35	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L	
SUNNY	1998-2004	B15, FB15, FNB15, QB15, SB15, JB15	*7 DDP-020R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L	
SUNNY LUCINO HATCH	1995-2000	FN15, FNN15, EN15, JN15, HN15	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L	
SUNNY LUCINO S-RV	1996-2000	FN15, FNN15, JN15, HNN15	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L	
SYLPHY	2012-2021	TB17	*3	DDP-014R/L +Side clip	*3	DDS-014R/L +Side clip	
TEANA	2003-2008	J31, TNJ31, PJ31	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L	
TEANA	2008-2014	J32, TNJ32, PJ32	DDP-026R/ L+Side clip	DDP-017R/ L+Side clip	DDS-026R/ L+Side clip	DDS-017R/ L+Side clip	
TEANA	2014-2020	L33	DDP-026R/L +Side clip	DDP-016R/L+ Side clip	DDS-026R/L +Side clip	DDS-016R/L +Side clip	
TERRANO (INCL. REGRAS)	1998-2002	TR50, LR50, LUR50, JTR50, JLUR50	DDP-022R/L	*7 DDP-020R/L	DDS-022R/L	DDS-021L	
TIIDA	2004-2012	C11, NC11, JC11	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L	

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
NISSAN						
TIIDA LATIO	2004-2012	SC11, SNC11, SJC11	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
TINO	1998-2003	V10, HV10, PV10	DDP-026R/L	DDP-019R/L	DDS-026R/L	DDS-019R/L
VANNETTE	1999-2017	SK	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
WINGROAD	1999-2001	WFY11, WHNY11, WHY11, WPY11	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
WINGROAD	2001-2005	WFY11, WHNY11, WRY11	*2	DDP-016R/L	*2	DDS-016R/L
WINGROAD	2005-2018	Y12, NY12, JY12	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
X-TRAIL (INCL. HYBRID)	2000-2007	T30, NT30, PNT30	DDP-024R/L	*7 DDP-014R/L	DDS-024R/L	*7 DDS-014R/L
X-TRAIL (INCL. HYBRID)	2007-2010	DNT31, NT31, T31, TNT31	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
X-TRAIL (INCL. HYBRID)	2010-2013	DNT31, NT31, T31, TNT31	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
X-TRAIL (INCL. HYBRID)	2013-2022	HNT32, HT32, NT32, T32	*3	DDP-017R/L	*3	DDS-017R/L
SUBARU						
BRZ	2012-2021	ZC6	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
BRZ	2021-	ZD8	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
CHIFFON (INCL. CUSTOM)	2016-2019	LA600F, LA610F	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
CHIFFON (INCL. CUSTOM)	2019-	LA650F, LA660F	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
CROSSTRECK	2022-	GUD GUE GUF	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
DEX	2008-2011	M401F, M411F	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
DIAS WAGON	2009-2017	S321N, S331N	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
DIAS WAGON	2017-2020	S321N, S331N	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
EXIGA	2008-2015	YA4, YA5, YA9, YAM	DDP-024R/L	DDP-018R/L	*1 DDS-024R/L	DDS-018R/L
FORESTER	2000-2002	SF5	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
FORESTER	2000-2002	SF5	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
FORESTER	2002-2003	SG5	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
FORESTER	2003-2005	SG5 SG9	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
FORESTER	2005-2007	SG5 SG9	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
FORESTER	2007-2012	SH5, SH9, SHJ	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
FORESTER	2017-2018	SJ5, SJG	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
FORESTER	2018-2025	SK5, SK9, SKE	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
SUBARU						
FORESTER (2.0i)	2012-2017	SJ5	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
FORESTER (2.0i-L/2.0i-S)	2012-2015	SJ5	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
FORESTER (2.0i-L/2.0i-S)	2015-2017	SJ5	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
FORESTER (S/X/2.0XT)	2012-2015	SJ5, SJG	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
FORESTER (S/X/2.0XT)	2015-2017	SJ5, SJG	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
IMPREZA	2023-	GU6 GU7 GUD GUE	*2	*2	*2	*2
IMPREZA (1.5i)	2009-2011	GH2, GH3	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA (1.5i-S)	2009-2011	GH2, GH3	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA (5 DOOR)	2007-2009	GH2, GH3, GH6, GH7, GH8	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA (5 DOOR)	2009-2011	GH6, GH7, GH8	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA ANESIS	2008-2009	GE2, GE3, GE6, GE7	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA ANESIS	2009-2011	GE6, GE7	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA ANESIS (1.5i)	2009-2011	GE2, GE3	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA ANESIS (1.5-i-L)	2009-2011	GE2, GE3	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA G4	2011-2014	GJ2, GJ3, GJ6, GJ7	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
IMPREZA G4	2014-2016	GJ2, GJ3, GJ6, GJ7	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
IMPREZA G4	2016-2023	GK2, GK3, GK6, GK7	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
IMPREZA SEDAN	1992-2000	GC1, GC2, GC4, GC6, GC8	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
IMPREZA SEDAN	2000-2007	GD2, GD3, GD9, GDA, GDB, GDC, GDD	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
IMPREZA SPORT (INCL. HYBRID)	2011-2014	GP2, GP3, GP6, GP7, GPE	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
IMPREZA SPORT (INCL. HYBRID)	2014-2016	GP2, GP3, GP6, GP7, GPE	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
IMPREZA SPORT (INCL. HYBRID)	2016-2023	GT2, GT3, GT6, GT7, GTE	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
IMPREZA WAGON	1992-2000	GF1, GF2, GF3, GF4, GF5, GF6, GF8, GFA	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
IMPREZA WAGON	2000-2004	GG2, GG3, GG9, GGA, GGB	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
IMPREZA WAGON	2004-2007	GG2, GG3, GG9, GGA, GGD, GGC, GGD	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
SUBARU						
IMPREZA WRX STI (4 DOOR)	2010-2014	GVB, GVF	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA WRX STI (5 DOOR)	2007-2014	GRB, GRF	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IMPREZA XV	2010-2011	GH2, GH3, GH6, GH7	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
JUSTY (INCL. CUSTOM)	2016-2018	M900F, M910F	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
JUSTY (INCL. CUSTOM)	2018-	M900F, M910F	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
LEGACY AUTOBACK	2003-2009	BP9, BPE, BPH	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LEGACY AUTOBACK	2009-2014	BR9, BRF, BRM	DDP-026R/L	DDP-019R/L	DDS-026R/L	DDS-019R/L
LEGACY AUTOBACK	2014-2021	BS9	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
LEGACY AUTOBACK	2021-2025	BT5	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
LEGACY B4 SEDAN	1998-2001	BE5, BE9	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
LEGACY B4 SEDAN	2001-2003	BE5, BE9, BEE, BES	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
LEGACY B4 SEDAN	2003-2009	BL5, BL9, BLE	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LEGACY B4 SEDAN	2009-2014	BM9, BMG, BMM	DDP-026R/L	DDP-019R/L	DDS-026R/L	DDS-019R/L
LEGACY B4 SEDAN	2014-2015	BN9	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
LEGACY B4 SEDAN	2015-2020	BN9	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
LEGACY OUTBACK	2009-2014	BR9, BRF, BRM	DDP-026R/L	DDP-019R/L	DDS-026R/L	DDS-019R/L
LEGACY OUTBACK	2014-	BS9	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
LEGACY TOURING WAGON	1998-2003	BH5, BH9, BHC, BHE	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
LEGACY TOURING WAGON	2003-2009	BP5, BP9, BPE	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
LEGACY TOURING WAGON	2009-2014	BR9, BRG, BRM	DDP-026R/L	DDP-019R/L	DDS-026R/L	DDS-019R/L
LEONE VAN	1999-2001	Y 11	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
LEVORG	2014-2020	VM4, VMG	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
LEVORG	2020-	VN5, VNH	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
LUCRA	2010-2015	L455F, L465F	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
PREO	1998-2000	RA1, RA2, RV1, RV2	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
PREO	2000-2010	RA1, RA2, RV1, RV2	DDP-020R/L	*3	DDS-020R/L	*3

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
SUBARU						
PREO	2010-2018	L275F, L285F	DDP-022R/L	*2	DDS-022R/L	*2
PREO PLUS	2012-2017	LA300F, LA310F	*1 DDP-020R/L	DDP-014R/L	*1 DDS-020R/L	DDS-014R/L
PREO PLUS	2017-	LA350F, LA360F	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
R1	2004-2010	RJ1, RJ2	DDP-022R/L	*1 DDP-014R/L	DDS-022R/L	*1 DDS-014R/L
R2	2003-2010	RC1, RC2	DDP-022R/L	*1 DDP-014R/L	DDS-022R/L	*1 DDS-014R/L
REX	2022-	A201F	DDP-021R/L	*2	DDS-021R/L	*2
SAMBAR TRUCK	2012-2014	S201J, S211J	DDP-016R/L	*1 DDP-016R/L	DDS-016R/L	*1 DDS-016R/L
SAMBAR TRUCK	2014-2018	S500J, S510J	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
SAMBAR TRUCK (INCL. GRAND CAB)	2018-	S500J, S510J	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
SAMBAR TRY/DIAS	1999-2002	TV1, TV2, TW1	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
SAMBAR TRY/DIAS	2002-2003	TW1, TW2, TV1, TV2, TT1, TT2	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
SAMBAR TRY/DIAS	2003-2006	TW1, TW2, TV1, TV2, TT1, TT2	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
SAMBAR TRY/DIAS	2006-2012	TW1, TW2, TV1, TV2, TT1, TT2	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
SAMBAR TRY/DIAS	2012-2017	S321B, S331B, S321Q, S331Q	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
SAMBAR TRY/DIAS	2017-2021	S321B, S331B, S321Q, S331Q	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
SAMBAR VAN	2022-	S700B, S710B	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
SOLTERRA	2022-	XEAM10X, YEAM15X	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
STELLA (INCL. CUSTOM)	2006-2011	RN1, RN2	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
STELLA (INCL. CUSTOM)	2011-2014	LA100F, LA110F	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
STELLA (INCL. CUSTOM)	2014-2017	LA150F, LA160F	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
STELLA (INCL. CUSTOM)	2017-	LA150F, LA160F	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
TRAVIQ	2000-2004	XM182, XM220	*2	*2	*2	*2
TREZIA	2010-2016	NSP120X, NCP120X, NCP125X	DDP-028R/L	-	*2	-
WRX S4	2014-2016	VAG	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
WRX S4	2016-2021	VAG	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
SUBARU						
WRX S4	2021-	VBH	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
WRX STI	2014-2016	VAB	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
WRX STI	2016-2020	VAB	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
XV (INCL. HYBRID)	2012-2014	GP7, GPE	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
XV (INCL. HYBRID)	2014-2017	GP7, GPE	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
XV (INCL. HYBRID)	2017-2022	GT3, GT7, GTE	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
SUZUKI						
AERIO	2001-2003	RA21S, RB21S, RC51S, RD51S	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
AERIO	2003-2007	RA21S, RB21S, RC51S, RD51S	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
ALTO (INCL. HYBRID)	1998-2004	HA12S, HA12V, HA22S, HA23S, HA23V	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
ALTO (INCL. HYBRID)	2004-2009	HA24S, HA24V	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
ALTO (INCL. HYBRID)	2009-2014	HA25S, HA25V, HA35S	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
ALTO (INCL. HYBRID)	2014-2021	HA36S, HA36V	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
ALTO (INCL. HYBRID)	2021-	HA37S, HA97S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
BALENO	2016-2020	WB32S, WB42S	DDP-021L	DDP-018R/L	DDS-021R/L	DDS-018R/L
CARRY (INCL. SUPER CARRY)	2013-2019	DA16T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
CARRY (INCL. SUPER CARRY)	2019-	DA16T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
CARRY/EVERY	1999-2002	DA52V, DA52W, DA62V, DA62W, DB52V, DA62T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
CARRY/EVERY	2002-2005	DA62V, DA62W, DA63T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
CARRY/EVERY	2005-2013	DA64V, DA64W, DA63T, DA65T	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
CERVO	2006-2009	HG21S	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
CHEVROLET CRUISE	2001-2008	HR51S, HR52S, HR81S, HR82S	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
CHEVROLET MW	2000-2010	ME34S, ME63S, ME64S	DDP-020R/L	*3	DDS-020R/L	*3
ESCUDO (INCL. HYBRID)	1997-2005	TA02W, TA52W, TD02W, TD32W, TD62W, TL52W	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
ESCUDO (INCL. HYBRID)	2005-2015	TA74W, TDA4W, TDB4W, TD54W, TD94W	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
SUZUKI						
ESCUDO (INCL. HYBRID)	2015-2024	YD21S, YE21S, YEA1S, YEH1S	*3	*3	*3	*3
ESCUDO 2.4	2015-2017	TDA4W	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
EVERY	2013-2015	DA64V, DA64W	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
EVERY	2015-2019	DA17V, DA17W	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
EVERY	2019-	DA17V, DA17W	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
EVERY PLUS/LANDY	1999-2005	DA32W	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
FRONX	2024-	WDB3S WEB3S	DDP-021L	DDP-018R/L	DDS-021R/L	DDS-018R/L
HUSSLER (INCL. HYBRID)	2014-2015	MR31S, MR41S	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
HUSSLER (INCL. HYBRID)	2015-2019	MR31S, MR41S	DDP-016R/L	DDP-017R/L	DDS-016R/L	DDS-017R/L
HUSSLER (INCL. HYBRID)	2015-2019	MR41S	DDP-016R/L	DDP-017R/L	DDS-016R/L	DDS-017R/L
HUSSLER (INCL. HYBRID)	2020-	MR52S, MR92S	DDP-016R/L	DDP-017R/L	DDS-016R/L	DDS-017R/L
IGNIS (INCL. HYBRID)	2016-	FF21S	DDP-021L	DDP-018R/L	DDS-021L	DDS-018R/L
JIMNY	1995-1998	JA12C, JA12V, JA12W, JA22W	*1 DDP-014R/L	DDP-014R/L	*1 DDS-014R/L	DDS-014R/L
JIMNY	1998-2018	JB23W	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
JIMNY	2018-	JB64W	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
JIMNY SIERRA	2002-2018	JB43W	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
JIMNY SIERRA	2018-	JB74W	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
JIMNY WIDE	1998-2001	JB33W, JB43W	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
KEI	1998-2003	HN11S, HN12S, HN21S, HN22S	DDP-019R/L	DDP-016R/L	DDS-019R/L	DDS-016R/L
KEI	2003-2006	HN22S	DDP-019R/L	DDP-016R/L	DDS-019R/L	DDS-016R/L
KEI	2006-2009	HN22S	DDP-019R/L	DDP-016R/L	DDS-019R/L	DDS-016R/L
KIZASHI	2009-	RE91S, RF91S	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
LANDY (INCL. HYBRID)	2007-2010	SC25, SNC25	DDP-026R/L	*2	DDS-026R/L	*2
LANDY (INCL. HYBRID)	2010-2013	SC26, SNC26	DDP-026R/L	*2	DDS-026R/L	*2
LANDY (INCL. HYBRID)	2014-2016	SC26, SNC26, SHC26	DDP-026R/L +Side clip	DDP-014R/L +Side clip	DDS-026R/L +Side clip	DDS-014R/L +Side clip

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
SUZUKI						
LANDY (INCL. HYBRID)	2016-2022	SC27, SGC27, SGNC27	*7 DDP-024R/L +Side clip	DDP-014R/L +Side clip	*7 DDS-024R/L +Side clip	DDS-014R/L +Side clip
LANDY (INCL. HYBRID)	2022-	MZRA90C, MZRA95C, ZWR90C, ZWR95C	DDP-028R/L	DDP-014R/L	*7 DDS-026R/L	DDS-014R/L
LAPIN	2002-2003	HE21S	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
LAPIN	2003-2008	HE21S	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
LAPIN	2008-2015	HE22S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
LAPIN	2015-2022	HE33S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
LAPIN	2022-	HE33S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
MR WAGON	2001-2004	MF21S	*7 DDP-020R/L	*2	DDS-021L	*2
MR WAGON	2004-2005	MF21S	*7 DDP-020R/L	*2	DDS-021L	*2
MR WAGON	2006-2010	MF22S	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
MR WAGON	2011-2016	MF33S	DDP-020R/L	DDP-017R/L	DDS-020R/L	DDS-017R/L
PALLET	2008-2010	MK21S	DDP-021L	DDP-016R/L	DDS-021L	DDS-016R/L
PALLET	2010-2013	MK21S	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2005-2010	MA34S	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2011-2015	MA15S	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2015-2020	MA26S, MA36S, MA46S	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2020-2024	MA27S, MA37S	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2025-	MAD47S	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
SPACIA (INCL. HYBRID)	2013-2017	MK32S, MK42S	*1 DDP-020R/L	DDP-017R/L	*1 DDS-020R/L	DDS-017R/L
SPACIA (INCL. HYBRID)	2017-2020	MK53S	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
SPACIA (INCL. HYBRID)	2020-2023	MK53S	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
SPACIA (INCL. HYBRID)	2023-	MK54S, MK94S	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
SPACIA BASE	2022-	MK33V	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
SPLASH	2008-2014	XB32S	DDP-022R/L	*1 DDP-016R/L	DDS-022R/L	*1 DDS-016R/L
SWIFT (INCL. HYBRID)	2017-2023	ZC13S, ZC43S, ZC53S, ZC83S, ZD53S, ZD83S	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
SUZUKI						
SWIFT (INCL. HYBRID)	2023-	ZCED5, ZDEDS, ZCDDS, ZDDDS	*1 DDP-020R/L	DDP-019R/L	*1 DDS-020R/L	*1 DDS-019R/L
SWIFT SPORTS	2017-	ZC33S	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2000-2003	HT51S	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2003-2006	HT51S, HT81S	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2004-2010	ZC11S, ZC21S, ZC31S, ZC71S, ZD11S, ZD21S	DDP-021L	*1 DDP-018R/L	DDS-021L	*1 DDS-018R/L
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2010-2016	ZC32S, ZC72S, ZD72S	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
SX4	2006-2014	YA11S, YA41S, YB11S, YB41S, YC11S	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
SX4 S CROSS	2015-2020	YA22S, YB22S	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
TWIN	2003-2005	EC22S, EC22S改	DDP-018R/L	DDP-016R/L	DDS-018R/L	DDS-016R/L
WAGON R SMILE (INCL. HYBRID)	2021-2024	MX81S, MX91S	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
WAGON R SMILE (INCL. HYBRID)	2024-	MX81S, MX91S	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
WAGON R SOLIO	1999-2000	MA63S	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
WAGON R SOLIO	2000-2005	MA34S, MA64S	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	1999-2003	MC11S, MC12S, MC21S, MC22S	DDP-018R/L	*7 DDP-014R/L	DDS-018R/L	*7 DDS-014R/L
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2003-2007	MH21S, MH22S	DDP-019R/L	DDP-016R/L	DDS-019R/L	DDS-016R/L
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2007-2008	MH22S	DDP-019R/L	DDP-016R/L	DDS-019R/L	DDS-016R/L
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2008-2012	MH23S	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2012-2017	MH34S, MH44S	DDP-020R/L	*7 DDP-014R/L	DDS-020R/L	*7 DDS-014R/L
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2017-2022	MH35S, MH55S, MH85S, MH95S	DDP-021L	*7 • *9 DDP-014R/L	DDS-021L	*7 • *9 DDS-014R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
SUZUKI						
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2022-	MH55S, MH85S, MH95S	DDP-022R/L	*2	DDS-022R/L	*2
XBEE (INCL. HYBRID)	2017-2020	MN71S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
XBEE (INCL. HYBRID)	2020-	MN71S	DDP-018R/L	DDP-018R/L	DDS-018R/L	DDS-018R/L
TOYOTA						
86	2012-2021	ZN6	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
86	2021-	ZN8	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
86 (WITH EYESIGHT)	2021-	ZN8	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
ALEX	2001-2006	NZE121, NZE124, ZZE122, ZZE123, ZZE124	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
ALLION	2001-2007	AZT240, NZT240, ZZT240, ZZT245	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
ALLION	2007-2021	NZT260, ZRT260, ZRT261, ZRT265	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
ALPHARD (INCL. HYBRID)	2002-2008	ANH10W, ANH15W, ATH10W, MNH10W, MNH15W	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
ALPHARD (INCL. HYBRID)	2008-2014	ANH20W, ANH25W, ATH20W, GGH20W, GGH25W	DDP-030R/L	DDP-014R/L	*2	DDS-014R/L
ALPHARD (INCL. HYBRID)	2015-2017	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
ALPHARD (INCL. HYBRID)	2018-2023	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	DDP-030R/L	DDP-014R/L	*2	DDS-014R/L
ALPHARD (INCL. HYBRID)	2023-	AAHH40W, AAHH45W, AGH40W, AGH45W, AAHP45W	DDP-030R/L	DDP-014R/L	*2	DDS-014R/L
ALTEZA	1998-2005	SXE10, GXE10	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
ALTEZA JETA	2001-2005	GXE10W, GXE15W, JCE10W, JCE15W	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
AQUA	2011-2021	NHP10	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
AQUA	2021-	MXPK10, MXPK11, MXPK15, MXPK16	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
ARIST	1997-2004	JZS160, JZS161	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
AURIS (INCL. HYBRID)	2006-2012	NZE151H, NZE154H, ZRE152H, ZRE154H	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
AURIS (INCL. HYBRID)	2012-2018	ZRE186H, ZWE186H, NZE181H, NZE184H, NRE185H	DDP-026R/L	*3	DDS-026R/L	*3
AVALONE	1995-2000	MCX10	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
AVENSIS SEDAN	2003-2008	AZT250, AZT251, AZT255	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
AVENSIS WAGON	2003-2008	AZT250W, AZT251W, AZT255W	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
AVENSIS WAGON	2011-2018	ZRT272W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
BB (INCL. OPEN DECK)	2000-2005	NCP30, NCP31, NCP34, NCP35	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
BB (INCL. OPEN DECK)	2005-2016	QNC20, QNC21, QNC25	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
BELTA	2005-2012	KSP92, SCP92, NCP96	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
BLADE	2006-2012	AZE154H, AZE156H, GRE156H	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
BZ4X	2022-	XEAM10, YEAM15	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
CALDINA	1997-2002	AT211G, CT216G, ST210G, ST215G, ST215W	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
CALDINA	2002-2007	AZT241W, AZT246W, ST246W, ZZT241W	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
CAMI	1999-2000	J100E	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
CAMI	2000-2006	J102E, J122E	DDP-022R/L	*2	DDS-022R/L	*2
CAMRY (INCL. HYBRID)	1996-2001	CV40, CV43, SV40, SV41, SV42, SV43	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
CAMRY (INCL. HYBRID)	2001-2005	ACV30, ACV35	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
CAMRY (INCL. HYBRID)	2006-2011	ACV40, ACV45	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L
CAMRY (INCL. HYBRID)	2011-2017	AVV50	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
CAMRY (INCL. HYBRID)	2017-2023	AXVH70, AXVH75	DDP-026R/L	DDP-020R/L	DDS-026R/L	DDS-020R/L
CAMRY GRACIA WAGON	1996-2001	MCV21W, MCV25W, SXV20W, SXV25W	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
CARINA	1996-2001	AT210, AT211, AT212, CT210, CT211, CT215, CT216	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
CAVARIER COUP/ SEDAN	1996-2000	TJG00	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
CELICA	1999-2006	ZZT230, ZZT231	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
CELSIOR	1994-2000	UCF20, UCF21	*2	*3	*2	*3

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
CELSIOR	2000-2006	UCF30, UCF31	*2	DDP-016R/L	*2	DDS-016R/L
CENTURY	1997-2017	GZG50	DDP-022R/L	*7 DDP-020R/L	DDS-022R/L	DDS-021L
CENTURY HYBRID SEDAN	2018-	UWG60	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
CENTURY HYBRID SUV	2023-	GRG75	DDP-026R/L	DDP-020R/L	DDS-026R/L	DDS-020R/L
CHASER	1996-2001	GX100, GX105, JZX100, JZX101, JZX105, LX100, SX100	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
C-HR (INCL. HYBRID)	2016-2018	ZYX10, NGX50	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
C-HR (INCL. HYBRID)	2018-2023	NGX10, NGX50, ZYX10, ZYX11	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
COASTER	1993-2004	BB4#, HZB4#, HDB5#, HZB5#	*7 DDP-020R/L	*7 DDP-020R/L	DDS-021L	DDS-021L
COASTER	2004-2016	XZB40, XZB46V, XZB50, XZB51, BZB40, BZB50	*7 DDP-020R/L	*7 DDP-020R/L	DDS-021L	DDS-021L
COASTER	2017-	XZB60, XZB70	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
COPEN GR SPORT	2019-	LA400A	DDP-017R/L	DDP-018R/L	DDS-017R/L	DDS-018R/L
COROLLA (INCL. HYBRID)	2019-	MZE117, NRE210, ZRE212, ZWE211, ZWE214, ZWE215, ZWE219	DDP-028R/L	DDP-014R/L+Side clip	*2	DDS-014R/L+Side clip
COROLLA AXIO (INCL. HYBRID)	2006-2012	NZE141, NZE144, ZRE142, ZRE144	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
COROLLA AXIO (INCL. HYBRID)	2012-2025	NKE165, NRE160, NRE161, NZE161, NZE164	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
COROLLA CROSS (INCL. HYBRID)	2021-	ZSG10, ZVG11, ZVG15	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
COROLLA FIELDER (INCL. HYBRID)	2000-2006	NZE121G, NZE124G, ZZE122G, ZZE123G, ZZE124G, CE121G	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
COROLLA FIELDER (INCL. HYBRID)	2006-2012	NZE141G, NZE144G, ZRE142G, ZRE144G	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
COROLLA FIELDER (INCL. HYBRID)	2012-2025	NKE165G, NRE161, NZE161G, NZE164G, ZRE162G	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
COROLLA LEVIN/SPRINTER TRUENO	1997-2000	AE110, AE111	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
COROLLA LUMION	2007-2015	NZE151N, ZRE152N, ZRE154N	*1 DDP-022R/L	DDP-020R/L	*1 DDS-022R/L	DDS-020R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
COROLLA RUNX	2001-2006	NZE121, NZE124, ZZE122, ZZE123, ZZE124	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
COROLLA SPACIO	1997-2001	AE111N, AE115N	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
COROLLA SPACIO	2001-2007	NZE121N, ZZE122N, ZZE124N	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
COROLLA SPORTS (INCL. HYBRID)	2018-	NRE210H, NRE214H, ZWE211H, ZWE213H, ZWE219H, MZEA12H	DDP-028R/L	DDP-014R/L +Side clip	*2	DDS-014R/L +Side clip
COROLLA/SPRINTER	1997-2000	AE110, AE111, AE114, CE110, CE113, CE114, CE116, EE111	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
COROLLA/SPRINTER	2000-2006	NZE120, NZE121, NZE124, ZZE122, ZZE124, CE121	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
COROLLA TOURING (INCL. HYBRID)	2019-	MZEA12W, MZEA17W, NRE210W, ZRE212W, ZWE211W, ZWE214W, ZWE215W, ZWE219W	DDP-028R/L	DDP-014R/L +Side clip	*2	DDS-014R/L +Side clip
COROLLA WAGON	1997-2000	AE100G, AE101G, AE104G, CE101G, CE102G, EE104G	DDP-020R/L	*3	DDS-020R/L	*3
CORONA PREMIO	1996-2001	AT210, AT211, CT211, CT216, ST210, ST215	*7 DDP-020R/L	DDP-018R/L	DDS-021L	DDS-018R/L
CRESTA	1996-2001	GX100, GX105, JZV100, JZX101, JZX105, LX100	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
CROWN (ROYAL/ATHLETE/HYBRID)	1999-2001	GS171, JZS171, JZS173, JZS175, JZS179	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
CROWN (ROYAL/ATHLETE/HYBRID)	2001-2003	GS171, JKS175, JZS171, JZS173, JZS175, JZS179	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
CROWN (ROYAL/ATHLETE/HYBRID)	2003-2008	GRS180, GRS181, GRS182, GRS183, GRS184	DDP-024R/L	DDP-018R/L	*1 DDS-024R/L	DDS-018R/L
CROWN (ROYAL/ATHLETE/HYBRID)	2008-2012	GRS200, GRS201, GRS202, GRS203, GRS204, GWS204	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
CROWN (ROYAL/ATHLETE/HYBRID)	2012-2018	GRS210, GRS211, GRS214, AWS210, AWS211, ARS210	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
CROWN (ROYAL/ATHLETE/HYBRID)	2018-2022	ARS220, AZSH20, AZSH21, GWS224	*3	DDP-018R/L	*3	DDS-018R/L
CROWN COMFORT	1995-2001	GXS10, YXS10	*2	*2	*2	*2
CROWN COMFORT	2001-2018	GXS10, YXS10, TSS10	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
CROWN CROSSOVER	2022-	AZSH35, TZSH35	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
CROWN ESTATE	2001-2007	GS171W, JZS171W, JZS173W, JZS175W	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
CROWN MAJESTA (INCL. HYBRID)	1999-2004	JZS177, UZS171, UZS173, UZS175	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
CROWN MAJESTA (INCL. HYBRID)	2004-2009	UZS186, UZS187	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
CROWN MAJESTA (INCL. HYBRID)	2009-2013	URS206, UZS207	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
CROWN MAJESTA (INCL. HYBRID)	2013-2018	AWS215, GWS214	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
CROWN SEDAN	1995-2001	JZS, GS	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
CROWN SEDAN	2023-	AZSH32 KZSM30	*3	*3	*3	*3
CROWN SPORTS	2023-	AZSH36W, AZSH37W	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
DUET	1998-2004	M100A, M101A, M110A, M111A	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
DYNA/TOYOACE	1999-2001	N/A	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
DYNA/TOYOACE	2001-2011	TRY2##, KDY2##, RZY2##, RZU3##, XZU3##, XZU4##, XZU5##, TRU3##, TRU5##, BZU3##	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
DYNA/TOYOACE (STANDARD)	2011-	BZU6#, TRC6#, TRU6#, XKC6#, XKU6#, XZC6#, XZU6#, KDY2#, TRY2#	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
DYNA/TOYOACE (WIDE - WITH ADAS)	2017-	XKU7#, XZC7#, XZU7#	DDP-022R/L	DDP-022R/L	DDS-022R/L	DDS-022R/L
DYNA/TOYOACE (WIDE - WITHOUT ADAS)	2011-	XKU7#, XZC7#, XZU7#	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
ESQUIRE (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZWR80G	DDP-028R/L	DDP-014R/L	*2	DDS-014R/L
ESTIMA (INCL. HYBRID)	2000-2005	ACR30W, ACR40W, AHR10W, MCR30W, MCR40W	*2	DDP-018R/L	*2	DDS-018R/L
ESTIMA (INCL. HYBRID)	2006-2019	ACR50W, ACR55W, AHR20W, GSR50W, GSR55W	DDP-028R/L	DDP-016R/L	*2	DDS-016R/L
FJ CRUISER	2010-2018	GSJ15W	DDP-016R/L	DDP-014R/L x 2	DDS-016R/L	DDS-014R/L x 2
FUN CARGO	1999-2002	NCP20, NCP21, NCP25	*3	DDP-016R/L	*3	DDS-016R/L
FUN CARGO	2002-2005	NCP20, NCP21, NCP25	*3	DDP-016R/L	*3	DDS-016R/L
GAIA	1998-2002	ACM10G, CXM10G, SXM10G, SXM15G	DDP-026R/L	*1 DDP-014R/L	DDS-026R/L	*1 DDS-014R/L
GAIA	2002-2004	ACM10G, ACM15G, CXM10G	DDP-026R/L	*1 DDP-014R/L	DDS-026R/L	*1 DDS-014R/L
GRANACE	2019-2024	GDH303W	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
GRAND HIACE	1999-2002	KCH10W, KCH16W, VCH10W, VCH16W	DDP-024R/L	*7 DDP-020R/L	DDS-024R/L	DDS-021L
GRANVIA	1998-2002	KCH10W, KCH16W, VCH10W, VCH16W	DDP-024R/L	*7 DDP-020R/L	DDS-024R/L	DDS-021L
HARRIER (INCL. HYBRID)	1997-2003	ACU10W, ACU15W, MCU10W, MCU15W, SXU10W, SXU15W	DDP-024R/L	*7 DDP-020R/L	DDS-024R/L	DDS-021L
HARRIER (INCL. HYBRID)	2003-2013	ACU30W, ACU35W, GSU30W, GSU31W, GSU35W, GSU36W, MCU30W, MCU31W, MCU35W, MCU36W, MHU38W	DDP-026R/L	DDP-022R/L	DDS-026R/L	DDS-022R/L
HARRIER (INCL. HYBRID)	2013-2020	AVU65W, ZSU60W, ZSU65W, ASU60W, ASU65W	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
HARRIER (INCL. HYBRID)	2020-	AXUH80, AXUH85, AXUP85, MXUA80, MXUA85,	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
HIACE VAN/WAGON	1996-2004	KZH1##, RZH1##, TRH1##	DDP-019R/L	*3	DDS-019R/L	*3
HIACE VAN/WAGON (STANDARD)	2004-	GDH20##, KDH20##, TRH20##	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
HIACE VAN/WAGON (WIDE)	2004-	GDH21##, GDH22##, KDH21##, KDH22##, TRH21##, TRH22##	DDP-022R/L	DDP-022R/L	DDS-022R/L	DDS-022R/L
HIACE LEGIAS	1998-2002	KCH40G, KCH40W, KCH46G, KCH46W, RCH41W, RCH47W	DDP-026R/L	DDP-018R/L	DDS-026R/L	DDS-018R/L
HIACE TRUCK	1995-2001	LY1##, YY1##	DDP-017R/L	DDP-017R/L	DDS-017R/L	DDS-017R/L
HILUX	2017-	GUN125	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
HILUX PICKUP	1997-2004	LN165, LN165H, LN167, LN170H, LN172H, RZN147, RZN152H, RZN167, RZN169H, RZN174H	DDP-018R/L	DDP-019R/L	DDS-018R/L	DDS-019R/L
HILUX SURF	1995-2002	KDN185W, KZN185G, KZN185W, RZN180W, RZN185W, VZN185W	DDP-018R/L	DDP-019R/L	DDS-018R/L	DDS-019R/L
HILUX SURF	2002-2009	GRN215W, KDN215W, RZN210W, RZN215W, TRN210W, TRN215W, VZN210W, VZN215W	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
IPSUM	1998-2001	SXM10G, SXM15G, CXM10G	DDP-024R/L	*1 DDP-014R/L	DDS-024R/L	*1 DDS-014R/L
IPSUM	2001-2009	ACM21W, ACM26W	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
IQ	2008-2016	KGJ10, NGJ10	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
ISIS	2004-2017	"ANM10G, ANM15G, ANM10W, ANM15W, ZGM10G, ZGM11G, ZGM15G, ZGM10W, ZGM11W, ZGM15W, ZNM10G, ZNM10W"	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
IST	2002-2007	NCP60, NCP61, NCP65	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
IST	2007-2016	NCP110, NCP115, ZSP110	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
JPN TAXI	2017-	NTP10	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
KLUGAR	2000-2007	ACU20W, ACU25W, MCU20W, MCU25W, MHU28W	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
LACTIS	2010-	NCP120, NCP122, NCP125, NSP120, NSP122	DDP-028R/L			
LAND CRUISER (70)	1994-2004	J70, J71, J73, J74, J76, J77	DDP-017R/L	DDP-016or019R/L	DDS-017R/L	DDS-016or019R/L
LAND CRUISER (100)	1999-2007	HDJ101K, UZJ100W	DDP-024R/L	DDP-022R/L	DDS-024R/L	DDS-022R/L
LAND CRUISER (200)	2007-2021	UZJ200W, URJ202W	DDP-024R/L	DDP-022R/L	DDS-024R/L	DDS-022R/L
LAND CRUISER (250)	2024-	GDJ250W, TRJ250W	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
LAND CRUISER (300)	2021-	FJA300W, VJA300W	DDP-024R/L	DDP-022R/L	DDS-024R/L	DDS-022R/L
LAND CRUISER PRADO (90)	1996-2002	KDJ90W, KDJ95W, KZJ90W, KZJ95W, RZJ90W, RZJ95W, VZJ90W, VZJ95W	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L
LAND CRUISER PRADO (120)	2002-2009	GRJ120W, GRJ121W, KDJ120W, KDJ121W, KDJ125W, TRJ120W, TRJ125W, VZJ120W, VZJ121W, VZJ125W	DDP-022R/L	DDP-021L	DDS-022R/L	DDS-021L
LAND CRUISER PRADO (150)	2009-	GDJ150W, GDJ151W, GRJ150W, GRJ151W, TRJ150W	DDP-026R/L	DDP-020R/L	DDS-026R/L	DDS-020R/L
LEGIUS ACE (STANDARD)	2004-2020	GDH20##, KDH20##, TRH20##	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
LEGIUS ACE (WIDE)	2004-2020	GDH21##, GDH22##, KDH21##, KDH22##, TRH21##, TRH22##	DDP-022R/L	DDP-022R/L	DDS-022R/L	DDS-022R/L
MARK X	2004-2009	GRX120, GRX121, GRX125	DDP-022R/L	DDP-020R/L	DDS-022R/L	DDS-020R/L
MARK X	2009-2012	GRX130, GRX133, GRX135	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
MARK X	2012-2019	GRX130, GRX133, GRX135	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
MARK X GIO	2007-2013	ANA10, ANA15, GGA10	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
MARK II	1996-2000	GX100, GX105, JZX100, JZX101, JZX105, LX100	DDP-022R/L	DDP-019R/L	DDS-022R/L	DDS-019R/L
MARK II	2000-2004	GX110, GX115, JZX110, JZX115	DDP-022R/L	*1 DDP-018R/L	DDS-022R/L	*1 DDS-018R/L
MARK II BRIT	2002-2007	GX110W, GX115W, JZX110W, JZX115W	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
MARK II WAGON QUALIS	1997-2002	MCV20W, MCV21W, MCV25W, SXV20W, SXV25W	*7 DDP-020R/L	DDP-019R/L	DDS-021L	DDS-019R/L
MEGA CRUISER	1996-2002	BXD20V	DDP-016R/L x 2	*2	DDS-016R/L x 2	*2
MIRAI	2020-	JPD20	*3	*2	*3	DDS-020R/L
MR-S	1999-2007	ZZW30	DDP-020R/L	DDP-019R/L	DDS-020R/L	DDS-019R/L
NADIA	1998-2003	ACN10, ACN10H, ACN15, ACN15H, SXN10, SXN10H, SXN15, SXN15H	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
NOAH (INCL. HYBRID)	2001-2007	AZR60G, AZR65G	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
NOAH (INCL. HYBRID)	2007-2013	ZRR70G, ZRR75G, ZRR70W, ZRR75W	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
NOAH (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZRR80W, ZRR85W, ZWR80G	DDP-028R/L	DDP-014R/L	*2	DDS-014R/L
NOAH (INCL. HYBRID)	2022-	ZWR90W, ZWR92W, ZWR95W, MZRA90W, MZRA92W, MZRA95W, MZRA97W	DDP-028R/L	DDP-014R/L	*2	DDS-014R/L
OPA	2000-2005	ACT10, ZCT10, ZCT15	DDP-026R/L	DDP-017R/L	DDS-026R/L	DDS-017R/L
PASSO	2004-2010	KGC10, KGC15, QNC10	DDP-020R/L	DDP-016R/L	DDS-020R/L	DDS-016R/L
PASSO	2010-2016	NGC30, KGC30, KGC35	DDP-021L	DDP-017R/L	DDS-021L	DDS-017R/L
PASSO	2016-2018	M700A, M710A	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
PASSO	2018-2023	M700A, M710A	DDP-022R/L	DDP-016R/L	DDS-022R/L	DDS-016R/L
PASSO SETTE	2008-2012	M502E, M512E	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
PIXIS EPOCH	2012-2017	LA300A, LA310A	*1 DDP-020R/L	DDP-014R/L	*1 DDS-020R/L	DDS-014R/L
PIXIS JOY	2016-2017	LA250A, LA260A	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
PIXIS JOY	2017-2023	LA250A, LA260A	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
PIXIS SPACE	2011-2017	L575A, L585A	DDP-018R/L	*1 DDP-018R/L	DDS-018R/L	*1 DDS-018R/L
PIXIS TRUCK	2011-2014	S201U, S211U	DDP-016R/L	*1 DDP-016R/L	DDS-016R/L	*1 DDS-016R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
PIXIS TRUCK	2014-2018	S500U, S510U	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
PIXIS TRUCK	2018-	S500U, S510U	DDP-016R/L	DDP-016R/L	DDS-016R/L	DDS-016R/L
PIXIS VAN	2011-2017	S321M, S331M	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
PIXIS VAN	2017-2021	S321M, S331M	DDP-020R/L	*1 DDP-014R/L	DDS-020R/L	*1 DDS-014R/L
PIXIS VAN	2021-	S700M, S710M	DDP-020R/L	DDP-014R/L	DDS-020R/L	DDS-014R/L
PIXIX MEGA	2015-2017	LA700A, LA710A	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
PIXIX MEGA	2018-2022	LA700A, LA710A	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
PLATZ	1999-2005	SCP11, NCP12, NCP16	*7 DDP-020R/L	DDP-014R/L	DDS-021L	DDS-014R/L
PORTE	2004-2012	NNP10, NNP11, NNP15	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
PORTE	2012-2020	NCP141, NCP145, NSP140, NSP141	*3	DDP-014R/L	*3	DDS-014R/L
PREMIO	2001-2007	AZT240, NZT240, ZZT240, ZRT245	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
PREMIO	2007-2021	NZT260, ZRT260, ZRT261, ZRT265	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
PREVIS	2001-2007	JCG10, JCG11, JCG15	DDP-024R/L	DDP-018R/L	DDS-024R/L	DDS-018R/L
PRIUS	1997-2003	NHW10, NHW11	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L
PRIUS	2003-2009	NHW20	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
PRIUS	2009-2015	ZVW30	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
PRIUS	2015-2017	ZVW50, ZVW51, ZVW55	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
PRIUS	2017-2022	ZVW50, ZVW51, ZVW55	DDP-028R/L	DDP-016R/L	*2	DDS-016R/L
PRIUS	2023-	MXWH60 MXWH65 ZVW60 ZVW65 MXWH61	DDP-028R/L	DDP-014R/L	*2	DDS-014R/L
PRIUS PHV	2012-2016	ZVW35	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
PRIUS PHV	2017-2019	ZVW52	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
PRIUS PHV	2017-2019	ZVW52	DDP-028R/L	DDP-016R/L	*2	DDS-016R/L
PRIUS PHV	2017-2017	ZVW52	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
PRIUS PHV	2019-2022	ZVW52	DDP-028R/L	DDP-016R/L	*2	DDS-016R/L
PRIUS α	2011-2021	ZVW40W, ZVW41W	DDP-028R/L	DDP-014R/L	*2	DDS-014R/L
PROBOX (INCL. HYBRID)	2002-2014	NCP50V, NCP51V, NCP52V, NCP55V, NCP58G, NCP59G, NLP51V	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
PROBOX (INCL. HYBRID)	2014-	NSP160V, NCP160V, NCP165V, NHP160V	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
PROGRE	1998-2007	JCG10, JCG11, JCG15	*1 DDP-024R/L	DDP-017R/L	*1 DDS-024R/L	DDS-017R/L
PRONARD	2000-2003	MCX20	*3	DDP-016R/L	*3	DDS-016R/L
RACTIS	2005-2010	NCP100, NCP105, SCP100	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L
RACTIS	2010-2016	NCP120, NCP122, NCP125, NSP120, NSP122	DDP-028R/L	-	*2	-
RAIZE	2019-	A200A, A201A, A202A, A210A	DDP-021L	*2	DDS-021L	*2
RAUM	1997-2003	EXZ10, EXZ15	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
RAUM	2003-2011	NCZ20, NCZ25	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L
RAV4 (INCL. HYBRID)	1996-2000	SXA10C, SXA10G, SXA10W, SXA11G, SXA11W, SXA15G, SXA16G	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
RAV4 (INCL. HYBRID)	2000-2005	ACA20W, ACA21W, ZCA25W, ZCA26W	DDP-024R/L	DDP-019R/L	DDS-024R/L	DDS-019R/L
RAV4 (INCL. HYBRID)	2005-2016	ACA31W, ACA36W	DDP-024R/L	DDP-017R/L	DDS-024R/L	*1 DDS-017R/L
RAV4 (INCL. HYBRID)	2019-	AXAH52, AXAH54, AXAP54, MXAA52, MXAA54	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
ROOMY (INCL. CUSTOM)	2016-2018	M900A, M910A	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
ROOMY (INCL. CUSTOM)	2018-	M900A, M910A	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
RUSH	2006-2016	J200E, J210E	DDP-021L	DDP-018R/L	DDS-021L	DDS-018R/L
SAI	2009-2017	AZK10	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
SAI (WITH ADAS)	2009-2017	AZK10	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L
SIENTA (INCL. HYBRID)	2003-2015	NCP81G, NCP85G	DDP-022R/L	DDP-017R/L	DDS-022R/L	DDS-017R/L
SIENTA (INCL. HYBRID)	2015-2018	NCP175G, NHP170G, NSP170G, NSP172G	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
SIENTA (INCL. HYBRID)	2018-2022	NCP175G, NHP170G, NSP170G, NSP172G	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
SIENTA (INCL. HYBRID)	2022-	MXPC10G, MXPL10G, MXPL15G, MXPC12G, MXPL12G	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L
SOARER	1991-2001	JZZ30, JZZ31, UZZ31, UZZ32	*7 DDP-020R/L	*2	DDS-021L	*2
SOARER	2001-2005	UZZ40	DDP-024R/L	DDP-020R/L	DDS-024R/L	DDS-020R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
TOYOTA						
SPADE	2012-2020	NCP141, NCP145, NSP140, NSP141	*3	DDP-014R/L	*3	DDS-014R/L
SPARKY	2000-2003	S221E, S231E	DDP-019R/L	*7 DDP-014R/L	DDS-019R/L	*7 DDS-014R/L
SPRINTER CARIB	1997-2002	AE111G, AE114G, AE115G	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
SUCCEED (INCL. HYBRID)	2002-2014	NCP58G, NCP59G, NCP51V, NCP55V, NLP51V	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
SUCCEED (INCL. HYBRID)	2014-2020	NCP160V, NCP165V, NHP160V	DDP-020R/L	DDP-018R/L	DDS-020R/L	DDS-018R/L
SUPRA	1993-2002	JZA80	*7 DDP-020R/L	DDP-020R/L	DDS-021L	DDS-020R/L
SUPRA	2019-2025	DB22, DB42, DB82	*2	*2	*2	*2
TANK (INCL. CUSTOM)	2016-2018	M900A, M910A	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
TANK (INCL. CUSTOM)	2018-2020	M900A, M910A	DDP-021L	DDP-019R/L	DDS-021L	DDS-019R/L
TOURING HIACE	1999-2002	KCH40W, KCH46W, RCH41W, RCH47W	DDP-026R/L	*3	DDS-026R/L	*3
TOWNACE/LITEACE VAN/TRUCK	2008-2009	S402M, S412M, S402U, S412U	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
TOWNACE/LITEACE VAN/TRUCK	2009-2020	S402M, S412M, S402U, S412U	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
TOWNACE/LITEACE TRUCK	1999-2007	KM, CM7#, 8#	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L
TOWNACE/LITEACE VAN	1998-2001	KR4#V, CR4#V, CR5#V	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
TOWNACE NOAH/LITEACE NOAH	1998-2001	CR40G, CR50G, SR40G, SR50G	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
TOWNACE TRUCK	2020-	S403U, S413U	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
TOWNACE VAN	2020-	S403M, S413M	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
VANGUARD	2007-2013	ACA33W, ACA38W, GSA33W	DDP-024R/L	DDP-017R/L	DDS-024R/L	DDS-017R/L
VELFIRE (INCL. HYBRID)	2008-2014	ANH20W, ANH25W, ATH20W, GGH20W, GGH25W	DDP-030R/L	DDP-014R/L	*2	DDS-014R/L
VELFIRE (INCL. HYBRID)	2015-2017	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
VELFIRE (INCL. HYBRID)	2018-2023	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	DDP-030R/L	DDP-014R/L	*2	DDS-014R/L
VELFIRE (INCL. HYBRID)	2023-	AAHH40W, AAHH45W, TAHA40W, TAHA45W, AAHP45W	DDP-030R/L	DDP-014R/L	*2	DDS-014R/L

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS		
			Driver	Passenger	Driver	Passenger	
			P/N	P/N	P/N	P/N	
TOYOTA							
VEROSSA	2001-2004	GX110, GX115, JZX110	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L	
VISTA	1998-2003	AZV50, AZV55, SV50, SV55, ZZV50	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L	
VISTA ALDEO	1998-2003	AZV50G, AZV55G, SV50G, SV55G, ZZV50G	DDP-024R/L	*1 DDP-014R/L	DDS-024R/L	*1 DDS-014R/L	
VITZ (INCL. HYBRID)	1999-2005	NCP10, NCP13, NCP15, SCP10, SCP13	*7 DDP-020R/L	DDP-014R/L	DDS-021L	DDS-014R/L	
VITZ (INCL. HYBRID)	2005-2010	KSP90, NCP91, NCP95, SCP90	DDP-024R/L	DDP-014R/L	DDS-024R/L	DDS-014R/L	
VITZ (INCL. HYBRID)	2010-2020	KSP130, NCP131, NHP130, NSP130, NSP135	DDP-028R/L	-	*2	-	
VOLTZ	2002-2004	ZZE136, ZZE137, ZZE138	*7 DDP-020R/L	DDP-017R/L	DDS-021L	DDS-017R/L	
VOXY (INCL. HYBRID)	2001-2007	AZR60G, AZR65G	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L	
VOXY (INCL. HYBRID)	2007-2013	ZRR70G, ZRR75G, ZRR70W, ZRR75W	DDP-026R/L	DDP-016R/L	DDS-026R/L	DDS-016R/L	
VOXY (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZRR80W, ZRR85W, ZWR80G	DDP-028R/L	DDP-014R/L	*2	DDS-014R/L	
VOXY (INCL. HYBRID)	2022-	ZWR90W, ZWR92W, ZWR95W, MZRA90W, MZRA92W, MZRA95W	DDP-028R/L	DDP-014R/L	*2	DDS-014R/L	
WILL CYPHA	2002-2005	NCP70, NCP75	DDP-022R/L	DDP-014R/L	DDS-022R/L	DDS-014R/L	
WILL VI	2000-2001	NCP19	DDP-019R/L	DDP-018R/L	DDS-019R/L	DDS-018R/L	
WILL VS	2001-2004	NZE127, ZZE127, ZZE128, ZZE129	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L	
WINDOM	1996-2001	MCV20, MCV21	DDP-022R/L	DDP-018R/L	DDS-022R/L	DDS-018R/L	
WINDOM	2001-2006	MCV30	*2	*2	*2	*2	
WISH	2003-2005	ANE10G, ANE11W, ZNE10G, ZNE14G	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L	
WISH	2005-2009	ANE10G, ANE11W, ZNE10G, ZNE14G	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L	
WISH	2009-2017	ZGE20G, ZGE21G, ZGE25G, ZGE20W, ZGE21W, ZGE22W, ZGE25W	DDP-026R/L	DDP-014R/L	DDS-026R/L	DDS-014R/L	
YARIS (INCL. HYBRID)	2020-	KSP210, MXPA10, MXPA15, MXP10, MXP15	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L	
YARIS (INCL. HYBRID)	2020-	GXPA16, MXPA12	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L	
YARIS CROSS (INCL. HYBRID)	2020-	MXPB10, MXPB15, MXPJ10, MXPJ15	DDP-024R/L	DDP-016R/L	DDS-024R/L	DDS-016R/L	

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Design Blade Series



MODEL	YEAR	MODEL CODE	DDP		DDS	
			Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N
UD TRUCKS						
BIG THUMB	1992-2005	All	DDP-022R/L	DDP-020R/L (DDP-022R/L)	DDS-022R/L	DDS-020R/L (DDS-022R/L)
CONDOR	1993-2011	LK, MK, PK, PW	DDP-020R/L	DDP-020R/L (DDP-020R/L)	DDS-020R/L	DDS-020R/L (DDS-020R/L)
CONDOR	2010-2016	LK, MK, PK, PW	DDP-022R/L	*2	DDS-022R/L	*2
CONDOR	2017-2023	MK, LK	DDP-022R/L	*2	DDS-022R/L	*2
CONDOR	2017-2023	PK, PW	DDP-020R/L	DDP-020R/L (DDP-019R/L)	DDS-020R/L	DDS-020R/L (DDS-019R/L)
CONDOR (STANDARD)	1995-2014	N/A	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
CONDOR (WIDE)	1995-2014	N/A	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
FINE CONDOR	1992-2011	N/A	*2	*2	*2	*2
FINE CONDOR	1992-2011	N/A	DDP-026R/L	*2	DDS-026R/L	*2
KAZET	2015-2023	FED	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
KAZET (STANDARD)	2014-2023	FBA, FDA, FEA	DDP-019R/L	DDP-019R/L	DDS-019R/L	DDS-019R/L
KAZET (WIDE)	2014-2023	FEB, FEC, FED	DDP-020R/L	DDP-020R/L	DDS-020R/L	DDS-020R/L
QUON	2004-2017	CD, CG, CV, CW, CX, CZ, GK, GW, GX	*2	*2 (*2)	*2	*2 (*2)

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Note

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
AUDI								
A3	1996-2003				DCS-G021	DCS-G019	DCV-021	DCV-019
A3	2004-2012				DCS-G024	DCS-G019	DCV-024	DCV-019
A4	1994-2001				DCS-G021	DCS-G021	DCV-021	DCV-021
A4	2004-				DCS-G022	DCS-G022	DCV-022	DCV-022
A4	2008-				DCS-G024	DCS-G020	DCV-024	DCV-020
A6	1994-2005				DCS-G022	DCS-G022	DCV-022	DCV-022
A8	1994-2002				DCS-G022	DCS-G022	DCV-022	DCV-022
BMW								
MINI	2001-				DCS-G018	DCS-G018	DCV-018	DCV-018
CHEVROLET								
AVEO	2004-2010				DCS-G022	DCS-G018	DCV-022	DCV-018
BLAZER	1995-2004				DCS-G020	DCS-G020	DCV-020	DCV-020
COROLADO	2003-				DCS-G022	DCS-G019	DCV-022	DCV-019
CRUZE	2012-				DCS-G022	DCS-G018	DCV-022	DCV-018
OPTRA	2003-				DCS-G022	DCS-G019	DCV-022	DCV-019
OPTRA	2004-2007				DCS-G022	DCS-G019	DCV-022	DCV-019
ZAFIRA	2000-				DCS-G024	DCS-G024	DCV-024	DCV-024
CHRYSLER								
CHEROKEE	1990-2001				DCS-G018	DCS-G018	DCV-018	DCV-018
GRAND CHEROKEE	2002-2010				DCS-G021	DCS-G021	DCV-021	DCV-021
WRANGLER	1987-1995				DCS-G012	DCS-G016	DCV-012	DCV-G016
WRANGLER	1996-2004				DCS-G013	DCS-G013	DCV-013	DCV-013
WRANGLER	2005-2006				DCS-G013	DCS-G017	DCV-013	DCV-G017
WRANGLER	2007				DCS-G015	DCS-G015	DCV-015	DCV-015
WRANGLER	2008-2010				DCS-G014	DCS-G014	DCV-014	DCV-014
DAIHATSU								
ALTIS	2001-2005	ACV30N, ACV35N	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
ALTIS	2006-2010	ACV40N, ACV45N	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
DAIHATSU								
ALTIS	2012-2017	AVV50N	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
ALTIS	2017-2023	AXVH70N, AXVH75N	DCP-026R/L	DCP-020R/L	DCS-G026	DCS-G020	DCV-026	DCV-020
APPLAUSE	1998-2000	A101S, A111S	DCP-019R/L +Screw clip	DCP-017R/ L+Screw clip	DCS-G019 +Screw clip	DCS-G017 +Screw clip	DCV-019 +Screw clip	DCV-017 +Screw clip
ATLEY	1999-2005	S220G, S220V, S230G, S230V	DCP-019R/L	DCP-015R/L	DCS-G019	DCS-G015	DCV-019	DCV-015
ATLEY	2005-2021	S321G, S331G, S321G, S331G	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
ATLEY	2021-	S700V, S710V, S700W, S710W	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
ATLEY 7	2000-2004	S221G, S231G	DCP-019R/L	DCP-015R/L	DCS-G019	DCS-G015	DCV-019	DCV-015
BE-GO	2006-2016	J200G, J210G	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
BOON	2004-2010	M300S, M301S, M310S, M312S	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
BOON	2010-2016	M600S, M601S, M610S	DCP-021R/L	DCP-017R/L	DCS-G021	DCS-G017	DCV-021	DCV-017
BOON	2016-2018	M700S, M710S	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
BOON LUMINAS	2008-2012	M502G, M512G	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
CAST	2015-2023	LA250S, LA260S	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
CERIA	2001				DCS-G018	DCSG-016	DCV-018	DCV-016
CHARADE	1990				DCS-G016	DCS-G016	DCV-016	DCV-016
CHARADE	1991				DCS-G018	DCS-G017	DCV-018	DCV-017
CHARADE	1993-2000	G200S, G201S, G203S, G213S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
COO	2006-2013	M401S, M402S, M411S	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
COPEN	2002-2012	L880K	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
COPEN	2014-	LA400K	DCP-017R/L	DCP-018R/L	DCS-G017	DCS-G018	DCV-017	DCV-018
COPEN GR SPORT	2019-	LA400K	DCP-017R/L	DCP-018R/L	DCS-G017	DCS-G018	DCV-017	DCV-018
DELTA VAN/ WAGON	1998-2001	CR40N, CR50N, SR40N	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
ESPASS	1995-1996				DCS-G017	DCS-G015	DCV-017	DCV-015

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
DAIHATSU								
ESSE	2005-2011	L235S, L245S	DCP-018R/L	*1 DCP-018R/L	DCS-G018	*1 DCS-G018	DCV-018	*1 DCV-G018
FEROZA	1988				DCS-G017	DCS-G016	DCV-017	DCV-016
GRAN MAX (CARGO)	2020-2024	S403V, S413V	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
GRAN MAX (TRUCK)	2020-2024	S403P, S413P	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
HIJET CADDIE	2016-2017	LA700V, LA710V	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
HIJET TRUCK	1999-2014	S200P, S210P, S201P, S211P	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
HIJET TRUCK	2014-	S500P, S510P	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
HIJET VAN/ CARGO	1999-2004	S200V, S210V	DCP-019R/L	DCP-015R/L	DCS-G019	DCS-G015	DCV-019	DCV-015
HIJET VAN/ CARGO	2004-2017	S320V, S321V, S330V, S331V	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
HIJET VAN/ CARGO	2017-2021	S321V, S331V, S321W, S331W	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
HIJET VAN/ CARGO	2021-	S700V, S710V, S700W, S710W	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
MAX	2001-2005	L950S, L952S, L960S, L962S	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
MEBIUS	2013-2021	ZVW41N	*2	DCP-014R/L	*2	DCS-G014	*2	DCV-014
MIDGET II	1999-2001	K100C, K100P	DCP-019R/L	-	DCS-G019	-	DCV-019	-
MIRA	1998-2000	L700S, L700V, L710S, L710V	DCP-018R/L	DCP-015R/L	DCS-G018	DCS-G015	DCV-018	DCV-015
MIRA	2002-2006	L250S, L250V, L260S, L260V	DCP-021R/L	DCP-012R/L	DCS-G021	DCS-G012	DCV-021	DCV-012
MIRA	2006-2018	L275S, L285S, L275V, L285V	DCP-022R/L	DCP-012R/L	DCS-G022	DCS-G012	DCV-022	DCV-012
MIRA AVY	2002-2006	L250S, L250V, L260S, L260V	DCP-021R/L	DCP-012R/L	DCS-G021	DCS-G012	DCV-021	DCV-012
MIRA COCOA	2009-2018	L675S, L685S	DCP-018R/L	DCP-018R/L	DCS-G018	*1 DCS-G018	DCV-018	*1 DCV-G018
MIRA E:S	2011-2017	LA300S, LA310S	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
MIRA E:S	2017-	LA350S, LA360S	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
MIRA GINO	1999-2004	L700S, L710S	DCP-018R/L	DCP-015R/L	DCS-G018	DCS-G015	DCV-018	DCV-015
MIRA GINO	2004-2009	L650S, L660S	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
DAIHATSU								
MIRA GINO 1000	2002-2004	L701S, L711S	DCP-018R/L	DCP-015R/L	DCS-G018	DCS-G015	DCV-018	DCV-015
MIRA IS	2011-	LA300S, LA310S	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
MIRA TOCOT	2018-2023	LA550S, LA560S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
MOVE (INCL. CUSTOM)	1999-2002	L900S, L902S, L910S, L912S	DCP-019R/L	DCP-017R/L	DCS-G019	DCS-G017	DCV-019	DCV-017
MOVE (INCL. CUSTOM)	2002-2006	L150S, L152S, L160S	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
MOVE (INCL. CUSTOM)	2006-2010	L175S, L185S	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
MOVE (INCL. CUSTOM)	2010-2014	LA100S, LA110S	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
MOVE (INCL. CUSTOM)	2014-	LA150S, LA160S	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
MOVE CANVAS	2016-2022	LA800S, LA810S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
MOVE CANVAS	2022-	LA850S, LA860S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
MOVE CONTE	2008-2017	L575S, L585S	DCP-018R/L	DCP-018R/L	DCS-G018	*1 DCS-G018	DCV-018	*1 DCV-G018
MOVE TERA	2004-2009	L550S, L560S	DCP-019R/L	DCP-017R/L	DCS-G019	DCS-G017	DCV-019	DCV-017
NAKED	1999-2004	L750S, L760S	DCP-018R/L	DCP-017R/L	DCS-G018	DCS-G017	DCV-018	DCV-017
OPTI	1998-2002	L800S, L802S, L810S	DCP-018R/L	DCP-015R/L	DCS-G018	DCS-G015	DCV-018	DCV-015
PYZAR	1998-2002	G301G, G303G, G311G, G313G	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
ROCKY	2019-	A200S, A201S, A202S, A210S	DCP-021R/L	[*1:DCP-015R/L]	DCS-G021 +Side clip	DCS-G015 +Side clip	DCV-021 +Side clip	DCV-015 +Side clip
SONICA	2006-2009	L405S, L415S	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
STORIA	1998-2004	M100S, M101S, M110S, M111S, M112S	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
TAFT	2020-	LA900S, LA910S	DCP-016R/L	DCP-017R/L	DCS-G016	DCS-G017	DCV-016	DCV-017
TAFT GT					DCS-G016	DCS-G016	DCV-016	DCV-016
TANTO (INCL. CUSTOM)	2003-2007	L350S, L360S	DCP-020R/L	*1 DCP-017R/L	DCS-G020	*1 DCS-G017	DCV-020	*1 DCV-G017
TANTO (INCL. CUSTOM)	2007-2013	L375S, L385S	DCP-020R/L	*1 DCP-017R/L	DCS-G020	*1 DCS-G017	DCV-020	*1 DCV-G017

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
DAIHATSU								
TANTO (INCL. CUSTOM)	2013-2019	LA600S, LA610S	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
TANTO (INCL. CUSTOM)	2016-	LA600S, LA610S	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
TANTO EXE	2009-2014	L455S, L465S	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
TANTO FUN CROSS	2022-	LA650S, LA660S	DCP-019R/L	DCP-019R/L	DCS-G019	*1	DCV-019	*1
TARUNA	1999-2001				DCS-G021	DCS-G018	DCV-021	DCV-018
TERIOS	2006				DCS-G022	DCS-G018	DCV-022	DCV-018
TERIOS	2000-2005	J102G, J122G	DCP-022R/L	DCP-012R/L	DCS-G022	DCS-G012	DCV-022	DCV-012
TERIOS	1997-2000	J100G	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
TERIOS KID	1998-2000	J111G, J131G	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
TERIOS KID/ LUCIA	2000-2012	J111G, J131G	DCP-022R/L	DCP-012R/L	DCS-G022	DCS-G012	DCV-022	DCV-012
THOR (INCL. CUSTOM)	2016-	M900S, M910S	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
WAKE	2014-2022	LA700S, LA710S	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
XENIA	2003-2004				DCS-G020	DCS-G016	DCV-020	DCV-016
YRV	2000				DCS-G020	DCS-G014	DCV-020	DCV-014
YRV	2000-2005	M200G, M201G, M211G	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
ZEBRA	1995-1996				DCS-G015	DCS-G015	DCV-015	DCV-015
FORD								
ESCAPE	2002				DCS-G020	DCS-G017	DCV-020	DCV-017
ESCAPE	2005-2007				DCS-G020	DCS-G018	DCV-020	DCV-018
ESCAPE	2008-2011				DCS-G020	DCS-G020	DCV-020	DCV-020
EVEREST	2003				DCS-G018	DCS-G018	DCV-018	DCV-018
FOCUS	2000				DCS-G019	DCS-G019	DCV-019	DCV-019
LASER	1988-1990				DCG-G018	DCG-G018	DCV-018	DCV-018
LYNX	1994-2001				DCS-G021	DCS-G018	DCV-021	DCV-018
RANGER	2012-				DCS-G024	DCS-G016	DCV-024	DCV-016

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

*1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 *2 No applicable item is available
 *3 No applicable item is available because of contact with the car body or wiper arm
 *4 Please take off the plastic part put on the wiper arm
 *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 *7 Shorter than OEM wiper
 *8 Possible to make contact with the mole when the wiper is operated at high speed
 *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HINO								
DUTRO	1999-2011	N/A	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
DUTRO	2011-	XKU7#, XZC7#, XZU7#	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
DUTRO (STANDARD)	2011-	BZU6#, TRC6#, TRU6#, XKC6#, XKU6#, XZC6#, XZU6#	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
DUTRO (WIDE - WITH ADAS)	2017	XKU7#, XZC7#, XZU7#	DCP-022R/L	DCP-022R/L	DCS-G022	DCS-G022	DCV-022	DCV-022
DUTRO (WIDE - WITHOUT ADAS)	2011-	XKU7#, XZC7#, XZU7#	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
DUTRO 125	2002-2004				DCS-G019	DCS-G019	DCV-019	DCV-019
RANGER	1989-2001	All	*2	*2	*2	*2	*2	*2
RANGER	2011-2017	N/A	DCP-026R/L	DCP-026R/LL	DCS-G026	DCS-G026	DCV-026	DCV-026
RANGER	2017-	FC, FD, FE, FJ, FX, GC, GD, GX	DCP-026R/L	DCP-026R/LL	DCS-G026	DCS-G026	DCV-026	DCV-026
RISING RANGER	2001-		DCP-026R/L	DCP-026R/L	DCS-G026	DCS-G026	DCV-026	DCV-026
SUPER DOLPHIN PROFIA/PROFIA	1992-2003	N/A	*2	*2	*2	*2	*2	*2
SUPER DOLPHIN PROFIA/PROFIA	2003-2017	N/A	DCP-022 x 2	DCP-022R/L	DCS-G022 x 2	DCS-G022	DCV-022 x 2	DCV-022
SUPER DOLPHIN PROFIA/PROFIA	2017-	FH, FN, FQ, FR, FS, FW, SH, SS	DCP-022 x 2	DCP-022R/L	DCS-G022 x 2	DCS-G022	DCV-022 x 2	DCV-022
HONDA								
ACCORD	1998-2002				DCS-G024	DCS-G019	DCV-024	DCV-019
ACCORD	2003-2007				DCS-G026	DCS-G018	DCV-026	DCV-018
ACCORD	2008-2015				DCS-G026	DCS-G019	DCV-026	DCV-019
ACCORD (INCL. HYBRID)	1997-2002	CF3, CF4, CF5, CL1, CL3	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
ACCORD (INCL. HYBRID)	2002-2005	CL7, CL8, CL9	DCP-026R/L	DCP-015R/L	DCS-G026	DCS-G015	DCV-026	DCV-015
ACCORD (INCL. HYBRID)	2005-2008	CL7, CL8, CL9	DCP-026R/L +Side clip	DCP-015R/L +Side clip	DCS-G026 +Side clip	DCS-G015 +Side clip	DCV-026 +Side clip	

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HONDA								
ACCORD (INCL. HYBRID)	2008-2013	CU1, CU2	*3	DCP-022R/L	*3	DCS-G022	*3	
ACCORD (INCL. HYBRID)	2013-2020	CR5, CR6	*7 DCP-024R/L +Side clip	DCP-019R/L +Side clip	*7 DCS-G024 +Side clip	DCS-G019 +Side clip	*7 DCV-024 +Side clip	DCV-019 +Side clip
ACCORD (INCL. HYBRID)	2020-2023	CV3	*3	DCP-016R/L	*3	DCS-G016	*3	DCV-016
ACCORD (INCL. HYBRID)	2024-	CY2	*3	*3	*3	*3	*3	*3
ACCORD (INCL. HYBRID) (WITH ADAS)	2013-2020	CR5, CR6, CR7	*7 DCP-024R/L +Side clip	DCP-019R/L +Side clip	*7 DCS-G024 +Side clip	DCS-G019 +Side clip	*7 DCV-024 +Side clip	DCV-019 +Side clip
ACCORD MAESTRO					DCS-G024	DCS-G019	DCV-024	DCV-019
ACCORD PRESTIGE	2003				DCS-G019	DCS-G019	DCV-019	DCV-019
ACCORD TOURER	2008-2013	CW1, CW2	*3	DCP-022R/L	*3	DCS-G022	*3	DCV-022
ACCORD WAGON	1997-2002	CF6, CF7, CH9, CL2	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
ACCORD WAGON	2002-2005	CM1, CM2, CM3	DCP-026R/L	DCP-015R/L	DCS-G026	DCS-G015	DCV-026	DCV-015
ACCORD WAGON	2005-2008	CM1, CM2, CM3	DCP-026R/L +Side clip	DCP-015R/L +Side clip	DCS-G026 +Side clip	DCS-G015 +Side clip	DCV-026 +Side clip	DCV-015 +Side clip
ACTY	1999-2018	HH5, HH6	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
ACTY (TRUCK)	1999-2009	HA6, HA7	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
ACTY (TRUCK)	2009-2021	HA8, HA9	DCP-018R/L	DCP-017R/L	DCS-G018	DCS-G017	DCV-018	DCV-017
AIRWAVE	2005-2008	GJ1, GJ2	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
AIRWAVE	2008-2010	GJ1, GJ2	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
AVANCIER	1999-2003	TA1, TA2, TA3, TA4	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
BRIO					DCS-G022	DCS-G014	DCV-022	DCV-014
CAPA	1998-2002	GA4, GA6	DCP-019R/L	DCP-017R/L	DCS-G019	DCS-G017	DCV-019	DCV-017
CITY	1997				DCS-G020	DCS-G019	DCV-020	DCV-019
CITY	1999				DCS-G019	DCS-G018	DCV-019	DCV-018

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

*1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 *2 No applicable item is available
 *3 No applicable item is available because of contact with the car body or wiper arm
 *4 Please take off the plastic part put on the wiper arm
 *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 *7 Shorter than OEM wiper
 *8 Possible to make contact with the mole when the wiper is operated at high speed
 *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HONDA								
CITY	2002-2004				DCS-G020	DCS-G018	DCV-020	DCV-018
CITY	2003-				DCS-G024	DCS-G014	DCV-024	DCV-014
CITY	2005				DCS-G024	DCS-G014	DCV-024	DCV-014
CITY	2014-				DCS-G026	DCS-G014	DCV-026	DCV-014
CIVIC	1990-1991				DCS-G020	DCS-G019	DCV-020	DCV-019
CIVIC	1992-1995				DCS-G022	DCS-G018	DCV-022	DCV-018
CIVIC	2001-2005				DCS-G021	DCS-G019	DCV-021	DCV-019
CIVIC	2006-2007				DCS-G028	DCS-G024	DCV-028	DCV-024
CIVIC	2008-2010				DCS-G026	DCS-G022	DCV-026	DCV-022
CIVIC	2012-				DCS-G026	DCS-G022	DCV-026	DCV-022
CIVIC FERIO (INCL. HYBRID) (4 DOOR)	1995-2000	EK2, EK3, EK4, EK5, EK8	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
CIVIC FERIO (INCL. HYBRID) (4 DOOR)	2000-2005	ES1, ES2, ES3, ES9, ET2	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CIVIC GENIO	1991				DCS-G020	DCS-G018	DCV-020	DCV-018
CIVIC HATCHBACK (INCL. HYBRID)	1995-2000	EK2, EK3, EK4	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
CIVIC HATCHBACK (INCL. HYBRID/TYPE R)	2017-2021	FK7, FK8	DCP-026R/L	DCP-018R/L	DCS-G026 +Side clip	DCS-G018 +Side clip	DCV-026 +Side clip	DCV-018 +Side clip
CIVIC (INCL. HYBRID)	2005-2007	FD1, FD2, FD3	*2	*2	*2	*2	*2	*2
CIVIC (INCL. HYBRID)	2007-2010	FD1, FD2, FD3	*3	*2	*3	*3	*3	*3
CIVIC (INCL. HYBRID/TYPE R)	2021-	FL1, FL4, FL5	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
CIVIC SEDAN (INCL. HYBRID)	2017-2020	FC1	DCP-026R/L	DCP-018R/L	DCS-G026 +Side clip	DCS-G018 +Side clip	DCV-026 +Side clip	DCV-018 +Side clip
CIVIC TYPE R (INCL. HYBRID) (EXCL. 5 DOOR)	2000-2003	EU1, EU2, EU3, EU4	DCP-024R/L	DCP-015R/L	DCS-G024	DCS-G015	DCV-024	DCV-015

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HONDA								
CIVIC TYPE R (INCL. HYBRID) (EXCL. 5 DOOR)	2003-2005	EU3, EU4	DCP-024R/L	DCP-015R/L	DCS-G024	DCS-G015	DCV-024	DCV-015
CIVIC WONDER					DCS-G019	DCS-G018	DCV-019	DCV-018
CLARITY PHEV	2018-2021	ZC5	*3	*3	*3	*3	*3	*3
CROSSROAD	2007-2010	RT1, RT2, RT3, RT4	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
CR-V	1997-2001				DCS-G020	DCS-G019	DCV-020	DCV-019
CR-V	2002-2006				DCS-G021	DCS-G020	DCV-021	DCV-020
CR-V	2007				DCS-G026	DCS-G016	DCV-026	DCV-016
CR-V	2008				DCS-G024	DCS-G017	DCV-024	DCV-017
CR-V	2009-2010				DCS-G026	DCS-G017	DCV-026	DCV-017
CR-V	2014-				DCS-G026	DCS-G016	DCV-026	DCV-016
CR-V (ALL NEW)	2008				DCS-G024	DCS-G018	DCV-024	DCV-018
CR-V (INCL. HYBRID)	1995-2001	RD1, RD2	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
CR-V (INCL. HYBRID)	2001-2006	RD4, RD5, RD6, RD7	DCP-021R/L	DCP-020R/L	DCS-G021	DCS-G020	DCV-021	DCV-020
CR-V (INCL. HYBRID)	2006-2011	RE3, RE4	DCP-026R/L +Side clip	DCP-017R/L +Side clip	DCS-G026 +Side clip	DCS-G017 +Side clip	DCV-026 +Side clip	DCV-017 +Side clip
CR-V (INCL. HYBRID)	2011-2016	RM1, RM4	DCP-026R/L +Side clip	DCP-016R/L +Side clip	DCS-G026 +Side clip	DCS-G016 +Side clip	DCV-026 +Side clip	DCV-016 +Side clip
CR-V (INCL. HYBRID)	2018-2020	RT5, RT6, RW1, RW2	DCP-026R/L +Side clip	DCP-016R/L +Side clip	DCS-G026 +Side clip	DCS-G016 +Side clip	DCV-026 +Side clip	DCV-016 +Side clip
CR-V (INCL. HYBRID)	2020-2022	RT5, RT6, RW1, RW2	*3	DCP-016R/L +Side clip	*3	DCS-G016 +Side clip	*3	DCV-016 +Side clip
CR-V (NEW)	2009-2010				DCS-G026	DCS-G017	DCV-026	DCV-017
CR-Z	2010-2017	ZF1, ZF2	DCP-026R/L	DCP-020R/L	DCS-G026	DCS-G020	DCV-026	DCV-020
DOMANI	1997-2000	MB3, MB4, MB5	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
E	2020-2024	ZC7	*3	DCP-018R/L	*3	DCS-G018	*3	DCV-018
EDIX	2004-2009	BE1, BE2, BE3, BE4, BE8	DCP-026R/L	DCP-019R/L	DCS-G026	DCS-G019	DCV-026	DCV-019

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HONDA								
ELEMENT	2003-2005	YH2	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
ELYSION	2004-2013	RR1, RR2, RR3, RR4, RR5, RR6	DCP-026R/L	DCP-024R/L	DCS-G026	DCS-G024	DCV-026	DCV-024
FIT (INCL. HYBRID)	2001-2007	GD1, GD2, GD3, GD4	DCP-020R/L	DCP-015R/L	DCS-G020	DCS-G015	DCV-020	DCV-015
FIT (INCL. HYBRID)	2007-2013	GE6, GE7, GE8, GE9, GP1, GP4	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
FIT (INCL. HYBRID)	2013-2020	GK3, GK4, GK5, GK6, GP5, GP6	DCP-026R/L +Side clip	DCP-014R/L	DCS-G026 +Side clip	DCS-G014	DCV-026 +Side clip	DCV-014
FIT (INCL. HYBRID)	2020-	GR1, GR2, GR3, GR4, GR5, GR6, GR7, GR8	*8 DCP-026R/L +Side clip	DCP-015R/L	*8 DCS-G026 +Side clip	DCS-G015	*8 DCV-026 +Side clip	DCV-015
FIT ARIA	2002-2009	GD6, GD7, GD8, GD9	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
FIT SHUTTLE (INCL. HYBRID)	2011-2015	GG7, GG8, GP2	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
FREED	2024-	GT1, GT2, GT3, GT4, GT5, GT6, GT7, GT8	*8 DCP-026R/L +Side clip	DCP-015R/L	*8 DCS-G026 +Side clip	DCS-G015	*8 DCV-026 +Side clip	DCV-015
FREED (INCL. HYBRID)	2016-2024	GB5, GB6, GB7, GB8	DCP-026R/L	DCP-015R/L	DCS-G026 +Side clip	DCS-G015	DCV-026 +Side clip	DCV-015
FREED/FREED SPIKE (INCL. HYBRID)	2008-2016	GB3, GB4, GP3	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
GRACE	2014-2017	GM4, GM5, GM6, GM9	DCP-026R/L +Side clip	DCP-014R/L	DCS-G026 +Side clip	DCS-G014	DCV-026 +Side clip	DCV-014
GRACE	2017-2020	GM4, GM5, GM6, GM9	DCP-026R/L +Side clip	DCP-014R/L	DCS-G026 +Side clip	DCS-G014	DCV-026 +Side clip	DCV-014
HR-V	1998-2006	GH1, GH2, GH3, GH4	DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
HR-V	2014-				DCS-G026	DCS-G016	DCV-026	DCV-016
INSIGHT	2009-2011	ZE2	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
INSIGHT	2011-2014	ZE2, ZE3	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HONDA								
INSIGHT	2018-2022	ZE4	*8 DCP-026R/L +Side clip	DCP-018R/L +Side clip	*8 DCS-G026 +Side clip	DCS-G018 +Side clip	*8 DCV-026 +Side clip	DCV-018 +Side clip
INSPIRE	1998-2003	UA4, UA5	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
INSPIRE	2003-2007	UC1	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
INSPIRE	2007-2010	CP3	*3	*3	*3	*3	*3	*3
INTEGRA	1993-2001	DB6, DB7, DB8, DB9, DC1, DC2	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
INTEGRA	2001-2006	DC5	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
INTEGRA SJ	1996-2001	EK3	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
JADE (INCL. HYBRID)	2015-2020	FR4, FR5	*7 DCP-026R/L +Side clip	*3	*7 DCS-G026 +Side clip	*3	*7 DCV-026 +Side clip	*3
JADE (INCL. HYBRID) (WITH ADAS)	2015-2020	FR4, FR5	*9	*3	*9	*3	*9	*3
JAZZ	2002				DCS-G024	DCS-G014	DCV-024	DCV-014
JAZZ	2003-				DCS-G024	DCS-G014	DCV-024	DCV-014
JAZZ	2007-2008				DCS-G024	DCS-G016	DCV-024	DCV-016
JAZZ	2009-2010				DCS-G024	DCS-G014	DCV-024	DCV-014
JAZZ	2014-				DCS-G026	DCS-G014	DCV-026	DCV-014
LAGREAT	1999-2004	RL1	DCP-024R/L	DCP-021R/L	DCS-G024	DCS-G021	DCV-024	DCV-021
LEGEND	1990-2004	KA7, KA8, KA9	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
LEGEND	2004-2012	KB1, KB2	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
LEGEND	2015-2022	KC2	*3	DCP-020R/L	*3	DCS-G020	*3	DCV-020
LIFE	1998-2003	JB1, JB2	DCP-019R/L	DCP-014R/L	DCS-G019	DCS-G014	DCV-019	DCV-014
LIFE	2003-2008	JB5, JB6, JB7, JB8	DCP-021R/L	DCP-012R/L	DCS-G021	DCS-G012	DCV-021	DCV-012
LIFE	2008-2014	JC1, JC2	DCP-021R/L	DCP-012R/L	DCS-G021	DCS-G012	DCV-021	DCV-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HONDA								
LIFE DUNK	2000-2003	JB3, JB4	DCP-019R/L	DCP-014R/L	DCS-G019	DCS-G014	DCV-019	DCV-014
LOGO	1999-2001	GA3, GA5	DCP-019R/L	DCP-017R/L	DCS-G019	DCS-G017	DCV-019	DCV-017
MDX	2003-2006	YD1	DCP-024R/L	DCP-021R/L	DCS-G024	DCS-G021	DCV-024	DCV-021
MOBILIO	2001-2008	GB1, GB2	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
MOBILIO SPIKE	2002-2008	GK1, GK2	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
N-BOX	2011-2017	JF1, JF2	DCP-018R/L	DCP-017R/L	DCS-G018	DCS-G017	DCV-018	DCV-017
N-BOX	2017-2023	JF3, JF4	DCP-019R/L	DCP-017R/L	DCS-G019	DCS-G017	DCV-019	DCV-017
N-BOX	2023-	JF5, JF6	DCP-019R/L	DCP-017R/L	DCS-G019	DCS-G017	DCV-019	DCV-017
N-BOX SLASH (INCL. CUSTOM)	2014-2020	JF1, JF2	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
N-BOX+ (INCL. CUSTOM)	2012-2018	JF1, JF2	DCP-018R/L	DCP-017R/L	DCS-G018	DCS-G017	DCV-018	DCV-017
N-ONE	2012-2020	JG1, JG2	DCP-019R/L	DCP-015R/L	DCS-G019	*1 DCS-G015	DCV-019	*1 DCV-015
N-ONE	2020-	JG3, JG4	DCP-019R/L	DCP-015R/L	DCS-G019	DCS-G015	DCV-019	DCV-015
NSX	2017-2022	NC1	N/A	N/A	N/A	N/A	N/A	N/A
N-VAN (LOW ROOF)	2018-2021	JJ1, JJ2	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
N-VAN (HIGH ROOF)	2018-	JJ1, JJ2	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
N-WGN (INCL. CUSTOM)	2013-2019	JH1, JH2	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
N-WGN (INCL. CUSTOM)	2019-	JH3, JH4	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
ODYSSEY	2000-2001				DCS-G024	DCS-G021	DCV-024	DCV-021
ODYSSEY (INCL. HYBRID)	1999-2003	RA6, RA7, RA8, RA9	DCP-024R/L	DCP-024R/LL	DCS-G024	DCS-G024	DCV-024	DCV-024
ODYSSEY (INCL. HYBRID)	2003-2008	RB1, RB2	*2 700mm	DCP-014R/L	*2 700mm	DCS-G014	*2 700mm	DCV-014
ODYSSEY (INCL. HYBRID)	2008-2013	RB3, RB4	*7 DCP-024R/L +Side clip	*6 DCP-017R/L +Side clip	*7 DCS-G024 +Side clip	*6 DCS-G017 +Side clip	*7 DCV-024 +Side clip	*6 DCV-017 +Side clip
ODYSSEY (INCL. HYBRID)	2013-2022	RC1, RC2, RC4	*7 DCP-026R/L +Side clip	*6 DCP-015R/L +Side clip	*7 DCS-G026 +Side clip	*6 DCS-G015 +Side clip	*7 DCV-026 +Side clip	*6 DCV-015 +Side clip

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HONDA								
ODYSSEY (INCL. HYBRID)	2023-	RC5	*2	*3	*2	*3	*2	*3
ODYSSEY (NEW)	2002-2010				DCS-G026	DCS-G022	DCV-026	DCV-022
ORTHIA	1996-2002	EL1, EL2, EL3	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
PARTNER	1996-2006	EY6, EY7, EY8, EY9	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
PARTNER	2006-2010	GJ3, GJ4	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
PRELUDE	1996-2000	BB5, BB6, BB7, BB8	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
S2000	1999-2009	AP1, AP2	DCP-016R/L	DCP-020R/L	DCS-G016	*1 DCS-G020	DCV-016	*1 DCV-020
S660	2015-2022	JW5	*7 DCP-019R/L +Side clip	*3	*7 DCS-G019 +Side clip	*3	*7 DCV-019 +Side clip	*3
SAVER	1998-2003	UA4, UA5	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
SHUTTLE (INCL. HYBRID)	2015-2022	GK8, GK9, GP7, GP8	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
S-MX	1996-2002	RH1, RH2	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
STEP WAGON (INCL. HYBRID)	1996-2001	RF1, RF2	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
STEP WAGON (INCL. HYBRID)	2003-2005	RF3, RF4, RF5, RF6, RF7, RF8	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
STEP WAGON (INCL. HYBRID)	2005-2007	RG1, RG2, RG3, RG4	*3	DCP-014R/L +Side clip	*3	DCS-G014 +Side clip	*3	DCV-014 +Side clip
STEP WAGON (INCL. HYBRID)	2007-2009	RG1, RG2, RG3, RG4	DCP-026R/L +Side clip	DCP-014R/L +Side clip	DCS-G026 +Side clip	DCS-G014 +Side clip	DCV-026 +Side clip	DCV-014 +Side clip
STEP WAGON (INCL. HYBRID)	2009-2015	RK1, RK2, RK3, RK4, RK5, RK6, RK7	*7 DCP-026R/L +Side clip	*6 DCP-015R/L +Side clip	*7 DCS-G026 +Side clip	*6 DCS-G015 +Side clip	*7 DCV-026 +Side clip	*6 DCV-015 +Side clip
STEP WAGON (INCL. HYBRID)	2015-2022	RP1, RP2, RP3, RP4, RP5	*7 • *8 DCP-026R/L +Side clip	DCP-014R/L	*7 • *8 DCS-G026 +Side clip	*6 DCS-G014 +Side clip	*7 • *8 DCV-026 +Side clip	*6 DCV-014 +Side clip
STEP WAGON (INCL. HYBRID)	2021-2023	RF3, RF4	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
STEP WAGON (INCL. HYBRID)	2022-	RP6, RP7, RP8	*3	*3	*3	*3	*3	*3
STREAM	2000-2006	RN1, RN2, RN3, RN4, RN5	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
STREAM	2002-				DCS-G024	DCS-G014	DCV-024	DCV-014

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HONDA								
STREAM	2006-2014	RN6, RN7, RN8, RN9	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
STREAM 1.7	2000-2003				DCS-G024	DCS-G014	DCV-024	DCV-014
STREAM 2.0	2000-2003				DCS-G024	DCS-G014	DCV-024	DCV-014
STREAM 2.0	2001				DCS-G026	DCS-G014	DCV-026	DCV-014
THAT'S	2002-2007	JD1, JD2	DCP-019R/L	DCP-014R/L	DCS-G019	DCS-G014	DCV-019	DCV-014
TORNEO	1997-2002	CF3, CF4, CF5, CL1, CL3	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
VAMOS	1999-2003	HM1, HM2	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
VAMOS	2003-2018	HM1, HM2	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
VAMOS HOBIO	2003-2018	HM3, HM4, HJ1, HJ2	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
VEZEL (INCL. HYBRID)	2013-2021	RU1, RU2, RU3, RU4	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
VEZEL (INCL. HYBRID)	2021-	RV3, RV4, RV5, RV6	*3	DCP-019R/L	*3	DCS-G019	*3	DCV-019
WR-V	2024-	DG5	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
Z	1998-2022	PA1	DCP-019R/L	DCP-014R/L	DCS-G019	DCS-G014	DCV-019	DCV-014
ZEST	1996-2012	JE1, JE2	DCP-021R/L	DCP-015R/L	DCS-G021	DCS-G015	DCV-021	DCV-015
ZR-V	2023-	RZ3, RZ4, RZ5, RZ6	*2	*2	*2	*2	*2	*2
HYUNDAI								
ACCENT	1999				DCS-G020	DCS-G018	DCV-020	DCV-018
ATOZ	2000				DCS-G020	DCS-G016	DCV-020	DCV-016
ELANTRA	1995-1996				DCS-G020	DCS-G018	DCV-020	DCV-018
EXCEL	1994				DCS-G020	DCS-G018	DCV-020	DCV-018
GETZ	2002				DCS-G022	DCS-G016	DCV-022	DCV-016
GETZ	2004				DCS-G020	DCS-G014	DCV-020	DCV-014
MATRIX	2001				DCS-G022	DCS-G016	DCV-022	DCV-016
SANTA FE	2000-2006				DCS-G022	DCS-G019	DCV-022	DCV-019
SONATA	2001				DCS-G022	DCS-G019	DCV-022	DCV-019
SONATA	2005				DCS-G024	DCS-G016	DCV-024	DCV-016

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
HYUNDAI								
SONATA	2006				DCS-G024	DCS-G020	DCV-024	DCV-020
TRAJET	2000				DCS-G026	DCS-G020	DCV-026	DCV-020
ISUZU								
ASKA	1997-2001	CJ2, CJ3	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
COMO	2001-2012	E25	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
COMO	2012-	E26	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
D-MAX	2001				DCS-G021	DCS-G019	DCV-021	DCV-019
D-MAX	2002-				DCS-G022	DCS-G019	DCV-022	DCV-019
ELF	1995-2001				DCS-G018	DCS-G018	DCV-018	DCV-018
ELF (STANDARD)	1993-2023	NHR, NHS, NJR, NJS, NKR, NKS, NLR, NLS, NMR, NMS	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ELF (STANDARD)	2007-2018	NHR, NHS, NJR, NJS, NKR, NKS, NLR, NLS, NMR, NMS	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ELF (STANDARD)	2018-2023	NHR, NHS, NJR, NJS, NKR, NKS, NLR, NLS, NMR, NMS	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ELF (WIDE)	1993-2023	NNR, NNS, NPR, NPS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
ELF (WIDE)	2006-2018	NNR, NNS, NPR, NPS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
ELF (WIDE)	2018-2023	NNR, NNS, NPR, NPS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
FARGO (LD)	1995-2001	All	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
FARGO (LT)	1995-2001	All	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
FILLY	1997-2002	JALE50, JALWE50, JAPE50, JAPWE50, JATE50, JATWE50, JAVE50, JAVWE50	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
FORWARD	1995-2007		DCP-020R/L	DCP-019R/L (DCP-019R/L)	DCS-G020	DCS-G019 (DCS-G019)	DCV-020	DCV-019 (DCV-019)
FORWARD	1995-2007		DCP-022R/L	DCP-022R/L	DCS-G022	DCS-G022	DCV-022	DCV-022
FORWARD	2007	FRR, FSR, FTR	DCP-022R/L	DCP-022R/L	DCS-G022	DCS-G022	DCV-022	DCV-022

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
ISUZU								
FORWARD	2007-2023	FRR, FSR, FTR	DCP-020R/L	DCP-020R/L (CP-019R/L)	DCS-G020	CS-G020 (DCS-G019)	DCV-020	DCV-020 (DCV-019)
GEMINI	1995-2000	MJ4, MJ5, MJ6	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
GIGA	1994-2016	CV#, CX#, CY#, EX#	DCP-022R/L	DCP-020R/L (DCP-020R/L)	DCS-G022	DCS-G020 (DCS-G020)	DCV-022	DCV-020 (DCV-020)
GIGA	2015-	CYL, CYJ, CXG, CXZ	DCP-020R/L	DCP-020R/L (DCP-019R/L)	DCS-G020	DCS-G020 (DCS-G019)	DCV-020	DCV-020 (DCV-019)
GIGA (TRACTOR)	2016-	EXD, EXY, EXZ	DCP-020R/L	DCP-020R/L (DCP-019R/L)	DCS-G020	DCS-G020 (DCS-G019)	DCV-020	DCV-020 (DCV-019)
MOCO	2001-2012	E25	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
MOCO (EXCL. WIDE)	2012-	E26	DCP-022R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
MU/WIZARD	1998-2002	UES25EW, UES73EW	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
MU-7	2002-				DCS-G022	DCS-G019	DCV-022	DCV-019
PANTHER	2001				DCS-G021	DCS-G017	DCV-021	DCV-017
RODEO BIGHORN	1995-2002	UBS25DW, UBS26DW, UBS26GW, UBS69DW, UBS69GW, UBS73DW, UBS73GW	DCP-020R/L	DCP-022R/L	DCS-G020	DCS-G022	DCV-020	DCV-022
TFR					DCS-G018	DCS-G018	DCV-018	DCV-018
THAIRUNG ADVENTURE MASTER					DCS-G022	DCS-G019	DCV-022	DCV-019
VEHICROSS	1997-2000	UGS25DW	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
KIA								
CARENS	2000				DCS-G024	DCS-G019	DCV-024	DCV-019
CARENS	2001				DCS-G021	DCS-G019	DCV-021	DCV-019
CARNIVAL	1999				DCS-G024	DCS-G024	DCV-024	DCV-024
PREGIO	2003				DCS-G021	DCS-G018	DCV-021	DCV-018
SPORTAGE	1995				DCS-G020	DCS-G020	DCV-020	DCV-020
SPORTAGE	1998				DCS-G020	DCS-G018	DCV-020	DCV-018

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

*1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 *2 No applicable item is available
 *3 No applicable item is available because of contact with the car body or wiper arm
 *4 Please take off the plastic part put on the wiper arm
 *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 *7 Shorter than OEM wiper
 *8 Possible to make contact with the mole when the wiper is operated at high speed
 *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
KIA								
SPORTAGE	2005				DCS-G024	DCS-G016	DCV-024	DCV-016
VISTO	1999				DCS-G020	DCS-G016	DCV-020	DCV-016
LEXUS								
CT	2011-2022	ZWA10	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
ES	2018-	AXZH10, AXZH11	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
GS (INCL. HYBRID)	2005-2011	GRS191, GRS196, GWS191, URS190, UZS190	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
GS (INCL. HYBRID)	2012-2020	ARL10, AWL10, GRL10, GRL11, GRL12, GRL15, GRL16, GWL10	DCP-026R/L	DCP-018R/L	*3	DCS-G018	*3	DCV-018
HS	2009-2018	ANF10	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
IS (INCL. HYBRID)	2005-2013	GSE20, GSE21, GSE25	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
IS (INCL. HYBRID)	2013-	ASE30, AVE30, AVE35, GSE30, GSE31, GSE35	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LBX	2023-	MAYH10, MAYH15, GAYA16	*3	*3	*3	*3	*3	*3
LC (INCL. HYBRID)	2017-	GWZ100, URZ100	*3	DCP-018R/L	*3	DCS-G018	*3	DCV-018
LM	2023-	TAWH15W	*2	DCP-014R/L	*2	DCS-G014	*2	DCV-014
LS (INCL. HYBRID)	2006-2017	USF40, USF41, USF45, USF46, UVF45, UVF46	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
LS (INCL. HYBRID)	2017-	GVF50, GVF55, VXFA50VX FA55	*3	DCP-020R/L	*3	*3	*3	*3
LX	2015-2021	URJ201W	DCP-024R/L	DCP-022R/L	DCS-G024	DCS-G022	DCV-024	DCV-022
LX	2022-	VJA310W, VJH310W	DCP-024R/L	DCP-022R/L	DCS-G024	DCS-G022	DCV-024	DCV-022
NX (INCL. HYBRID)	2014-2018	AGZ10, AGZ15, AYZ10, AYZ15	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
NX (INCL. HYBRID)	2018-2021	AGZ10, AGZ15, AYZ10, AYZ15	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
NX (INCL. HYBRID)	2021-	AAZA20, AAZA25, AAZH20, AAZH25, AAZH26, TAZA25	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
LEXUS								
RC (INCL. HYBRID)	2014-2025	ASC10, AVC10, GSC10	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
RX	2022-	AALH16, TALA10, TALA15, TALH17, AALH10, AALH15	*3	*3	*3	*3	*3	*3
RX (INCL. HYBRID)	2009-2015	AGL10W, GGL10W, GGL15W, GGL16W, GYL10W, GYL15W, GYL16W	DCP-026R/L	DCP-022R/L	DCS-G026	DCS-G022	DCV-026	DCV-022
RX (INCL. HYBRID)	2015-2022	AGL20W, AGL25W, GYL20W, GYL25W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
RX (INCL. HYBRID)	2017-2022	GYL26W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
RZ	2023-	XEBM15	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
SC	2005-2006	UZZ40	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
SC	2006-2010	UZZ40	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
MAZDA								
2	2011-				DCS-G024	DCS-G014	DCV-024	DCV-014
2	2015-				DCS-G022	DCS-G017	DCV-022	DCV-017
2	2019-	DJ5AS, DJ5FS, DJLFS, DJLAS	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
3	2004				DCS-G021	DCS-G019	DCV-021	DCV-019
3	2011-				DCS-G024	DCS-G019	DCV-024	DCV-019
3	2015-				DCS-G024	DCS-G018	DCV-024	DCV-018
3 FASTBACK	2019-	BP5P, BP8P, BPEP, BPFJ3P, BPF, BP5R, BP8R, BPFJ3R, BPEK3R	*3	*3	*3	*3	*3	*3
3 SEDAN	2019-	BP5P, BP8P, BPEP, BPFJ3P, BPF, BP5R, BP8R, BPFJ3R, BPEK3R	*3	*3	*3	*3	*3	*3
5	2006				DCS-G024	DCS-G016	DCV-024	DCV-016
6	2004				DCS-G021	DCS-G018	DCV-021	DCV-018
6 SEDAN	2019-2024	GJFEP, GJ2AP, GJ2FP, GJ5FP	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MAZDA								
6 WAGON	2019-2024	GJEFW, GJ2AW, GJ2FW, GJ5FW	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
323 INTERPLAY					DCS-G021	DCS-G018	DCV-021	DCV-018
323 TRENDY					DCS-G018	DCS-G018	DCV-018	DCV-018
ASTINA	1991				DCS-G021	DCS-G018	DCS-G021	DCS-G018
ATENZA SEDAN	2008-2012	GHEFP, GH5AP, GH5FP	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
ATENZA SEDAN	2012-2014	GJEFP, GJ2FP, GJ5FP	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
ATENZA SEDAN	2015-2018	GJEFP, GJ2AP, GJ2FP, GJ5FP	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
ATENZA SEDAN	2016-2018	GJEFP, GJ2AP, GJ2FP, GJ5FP	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
ATENZA SEDAN	2018-2019	GJEFP, GJ2AP, GJ2FP, GJ5FP	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
ATENZA SPORTS	2002-2007	GG3S, GGES	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
ATENZA SPORTS	2008-2012	GHEFS, GH5AS, GH5FS	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
ATENZA WAGON (INCL. SPORTS WAGON)	2002-2007	GYEW, GY3W	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
ATENZA WAGON (INCL. SPORTS WAGON)	2008-2012	GHEFW, GH5AW, GH5FW	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
ATENZA WAGON (INCL. SPORTS WAGON)	2012-2014	GJEFW, GJ2FW, GJ5FW	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
ATENZA WAGON (INCL. SPORTS WAGON)	2015-2018	GJEFW, GJ2AW, GJ2FW, GJ5FW	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
ATENZA WAGON (INCL. SPORTS WAGON)	2016-2018	GJEFW, GJ2AW, GJ2FW, GJ5FW	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
ATENZA WAGON (INCL. SPORTS WAGON)	2018-2019	GJEFW, GJ2AW, GJ2FW, GJ5FW	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
AXELA SEDAN (INCL. HYBRID)	2003-2009	BK3P, BK5P, BKEP	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MAZDA								
AXELA SEDAN (INCL. HYBRID)	2009-2013	BL5FP, BLEFP, BLEAP, BLFFP	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
AXELA SEDAN (INCL. HYBRID)	2013-2016	BM5FP, BM5AP, BM6FJ, BYEFP	DCP-024R/L	DCP-018R/L	DCS-G024	*3	DCV-024	*3
AXELA SEDAN (INCL. HYBRID)	2016-2019	BM2AP, BM2FP, BM5FP, BM5AP, BM6FJ, BMLFP, BYEFP	DCP-024R/L	DCP-018R/L	DCS-G024	*3	DCV-024	*3
AXELA SPORTS	2003-2009	BK3P, BK5P, BKEP	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
AXELA SPORTS	2009-2013	BL5FW, BLEFW, BLEAW, BL3PW, BL6FJ, BLFFW, BL3FW	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
AXELA SPORTS	2013-2016	BM2FS, BM5FS, BM5AS, BMEFS	DCP-024R/L	DCP-018R/L	DCS-G024	*3	DCV-024	*3
AXELA SPORTS	2016-2019	BM2AS, BM2FS, BM5FS, BM5AS, BMEFS, BMLFS	DCP-024R/L	DCP-018R/L	DCS-G024	*3	DCV-024	*3
AZ OFFROAD	1998-2014	JM23W	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
AZ WAGON	1999-2003	MD11S, MD12S, MD21S, MD22S	DCP-018R/L	DCP-015R/L	DCS-G018	DCS-G015	DCV-018	DCV-015
AZ WAGON	2003-2007	MJ21S, MJ22S	DCP-019R/L	DCP-016R/L	DCS-G019	DCS-G016	DCV-019	DCV-016
AZ WAGON	2007-2008	MJ22S	DCP-019R/L	DCP-016R/L	DCS-G019	DCS-G016	DCV-019	DCV-016
AZ WAGON	2008-2012	MJ23S	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
BIANTE	2008-2018	CC3FW, CCEAW, CCEFW, CCFFW	DCP-026RL +Side clip	DCP-015R/L	DCS-G026 +Side clip	DCS-G015	DCV-026 +Side clip	DCV-015
BONGO	1999-2020	SK82V, SKF2V, SK-P2V, SKP2M, SLP2L, SLP2M, SLP2T, SLP2V	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
BONGO (TRUCK)	2020-	S403F, S413F	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
BONGO (VAN)	2020-	S403Z, S413Z	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
BONGO BRAWNY	1999-2010	SKE6V, SKF6V	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
BONGO BRAWNY (VAN)	2019-	GDH206M, TRH200M, GDH201M	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MAZDA								
BONGO FRIENDEE	1995-2005	SG5W, SGEW, SGE3, SGL3, SGL5, SGLR, SGLW	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
BT50	2013-				DCS-G024	DCS-G016	DCV-024	DCV-016
BT50					DCS-G018	DCS-G018	DCV-018	DCV-018
CAPELLA	1997-2002	GF8P, GFEP, GFER, GFFP	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CAPELLA	1997-2002	GF8P, GFEP, GFER, GFFP	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CAPELLA WAGON	1997-2002	GW5R, GW8W, GWER, GWEW, GWFW	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CAPELLA WAGON (CAPELLA CARGO)	1997-2002	GW5R, GW8W, GWER, GWEW, GWFW	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CAROL (INCL. HYBRID)	1998-2004	HB12S, HB22S, HB23S	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
CAROL (INCL. HYBRID)	2004-2009	HB24S	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
CAROL (INCL. HYBRID)	2009-2014	HB25S, HB35S	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
CAROL (INCL. HYBRID)	2015-2021	HB36S	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
CAROL (INCL. HYBRID)	2022-	HB37S, HB97S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
CRONOS	1992-1994				DCS-G022	DCS-G018	DCV-022	DCV-018
CX-3	2015-2016	DK5AW, DK5FW	DCP-022R/L	DCP-018R/L	*8 DCS-G022 +Side clip	DCS-G018	*8 DCV-022 +Side clip	DCV-018
CX-3	2016-	DK5##, DK8##, DKE##, DKL##	DCP-022R/L	DCP-018R/L	*8 DCS-G022 +Side clip	DCS-G018	*8 DCV-022 +Side clip	DCV-018
CX-30	2019-	DMEP, DMFP, DM8P, DMEJ3P	*3	*3	*3	*3	*3	*3
CX-5	2012-2017	KEEAW, KEEFW, KE2AW, KE2FW, KE5AW, KE5FW	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
CX-5	2015-2017	KEEAW, KEEFW, KE2AW, KE2FW, KE5AW, KE5FW	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MAZDA								
CX-5	2017-	KF2P, KF5P, KFEP	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
CX-60	2022-2024	KH3P, KH5P, KH3R3P, KH5S3P	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
CX-60	2024-	KH3P, KH5P, KH3R3P, KH5S3P	*3	*3	*3	*3	*3	*3
CX-7	2006-2011	ER3P	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
CX-8	2017-2023	KG2P, KG5P	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
CX-80	2024-	KL3P, KL3R3P, KL5S3P	*3	*3	*3	*3	*3	*3
DEMIO	1999-2002	DW3W, DW5W	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
DEMIO	2002-2007	DY3R, DY3W, DY5R, DY5W	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
DEMIO	2007-2014	DE3AS, DE3FS, DE5FS, DEJFS	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
DEMIO	2014-2016	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
DEMIO	2016-2017	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
DEMIO	2017-2019	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS, DJLAS	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
FAMILIA	1998-2003	BJ3P, BJ5P, BJEP, BJLS	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
FAMILIA S-WAGON	1999-2003	BJ5W, BJ8W, BJFW	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
FAMILIA VAN	1999-2008	#Y11	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
FAMILIA VAN	2007-2018	BVY12, BVAY12, BVJY12, BVZNY12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
FAMILIA VAN	2018-	NCP160M, NCP165M	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
FLAIR (INCL. HYBRID)	2012-2017	MJ34S, MJ44S	DCP-020R/L	DCP-015R/L	DCS-G020	*3	DCV-020	*3
FLAIR (INCL. HYBRID)	2017-2022	MJ55S, MJ95S	DCP-021R/L	DCP-015R/L	DCS-G021	DCS-G015	DCV-021	DCV-015
FLAIR (INCL. HYBRID)	2022-	MJ55S, MJ95S	DCP-022R/L	DCP-015R/L	DCS-G022	DCS-G015	DCV-022	DCV-015

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MAZDA								
FLAIR CROSSOVER (INCL. HYBRID)	2014-2015	MS31S, MS41S	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
FLAIR CROSSOVER (INCL. HYBRID)	2015-2018	MS41S	DCP-016R/L	DCP-017R/L	DCS-G016	DCS-G017	DCV-016	DCV-017
FLAIR CROSSOVER (INCL. HYBRID)	2020-	MS52S, MS92S	DCP-016R/L	DCP-017R/L	DCS-G016	DCS-G017	DCV-016	DCV-017
FLAIR WAGON (INCL. HYBRID)	2012-2013	MM21S	DCP-020R/L	*1 DCP-016R/L	*3	DCS-G016	*3	DCV-016
FLAIR WAGON (INCL. HYBRID)	2013-2018	MM32S, MM42S	*1 DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
FLAIR WAGON (INCL. HYBRID)	2018-2023	MM53S	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
FLAIR WAGON (INCL. HYBRID)	2020-2023	MM53S	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
FLAIR WAGON (INCL. HYBRID)	2023-	MM94S, MM54S	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
LAPUTA	1999-2006	HP11S, HP12S, HP21S, HP22S	DCP-019R/L	DCP-016R/L	DCS-G019	DCS-G016	DCV-019	DCV-016
MILLENIA/EUNOS 800	1993-2003	TA3A, TA3P, TA3Y, TA3Z, TA5A, TA5P, TA5Y, TAFP	DCP-021R/L	DCP-020R/L	DCS-G021	DCS-G020	DCV-021	DCV-020
MPV	1999-2006	LW3W, LW5W, LW5W, LWFW	DCP-024R/L	DCP-024R/LL	DCS-G024	DCS-G024	DCV-024	DCV-024
MPV	2006-2016	LY3P	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
MX-30	2020-	DREJ3P, DRH3P	*3	*3	*3	*3	*3	*3
PREMACY	1999-2005	CP8W, CPEW	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
PREMACY	2005-2010	CR3W, CREW	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
PREMACY	2010-2018	CWEAW, CWEFW, CWFFW	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
PROTÉGÉ					DCS-G021	DCS-G019	DCV-021	DCV-019
ROADSTER	1998-2005	NB6C, NB8C	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
ROADSTER	2005-2015	NCEC	DCP-018R/L	*1 DCP-018R/L	DCS-G018	*1 DCS-G018	DCV-018	*1 DCV-G018
ROADSTER	2015-	ND5RC, NDERC, ND5RE, NDERE	DCP-018R/L	DCP-019R/L	DCS-G018	DCS-G019	DCV-018	DCV-019

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

*1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 *2 No applicable item is available
 *3 No applicable item is available because of contact with the car body or wiper arm
 *4 Please take off the plastic part put on the wiper arm
 *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 *7 Shorter than OEM wiper
 *8 Possible to make contact with the mole when the wiper is operated at high speed
 *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MAZDA								
RX-7	1991-2003	FD3S	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
RX-8	2003-2012	SE3P	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
SCRUM	1999-2005	DG52V, DG52W, DH52V, DH52W, DG62W, DG62V	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
SCRUM	2005-2015	DG64V, DG64W	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
SCRUM	2015-	DG17V, DG17W	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
SCRUM TRUCK	2005-2013	DG63T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
SCRUM TRUCK	2013-	DG16T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
SENTIA	1995-2000	HEEA, HEEP	DCP-021R/L	DCP-020R/L	DCS-G021	DCS-G020	DCV-021	DCV-020
SPIANO	2002-2003	HF21S	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
SPIANO	2003-2008	HF21S	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
TITAN	2007-2023	LNR, LNS, LPR, LPS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
TITAN	2019-2023	LNR, LNS, LPR, LPS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
TITAN (LHR)	2024-	LHR87AF	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
TITAN (STANDARD)	2007-2019	LJR, LJS, LKR, LKS, LLR, LLS, LMR, LMS	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
TITAN (STANDARD)	2019-	LHR, LHS, LJR, LJS, LKR, LKS, LLR, LLS, LMR, LMS	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
TITAN (STANDARD/HI)	2023-	LJR88AF, LKR88AF, LKR88C, LKR88AC, LMR88C, LLR88AC, LR88AC, LMR88C	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
TITAN (WIDE)	2007-2023	LNR, LNS, LPR, LPS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
TITAN (WIDE)	2019-2023	LNR, LNS, LPR, LPS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
TITAN (WIDE)	2023-	LPR88AC, LPR88YM, LNR88AC	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
TRIBUTE	2000-2005	EP3W, EPEW, EPFW	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
VANTREND					DCS-G015	DCS-G015	DCV-015	DCV-015
VERISA	2004-2015	DC5R, DC5W	DCP-022R/L	DCP-015R/L	DCS-G022	DCS-G015	DCV-022	DCV-015

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MAZDA (FORD JP)								
FESTIVA WAGON	1999-2003	DW3WF, DW5WF	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
FREDA	1995-2000	SG5WF, SGE3F, SGEWF, SGL3F, SGL5F, SGLRF, SGLWF	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IXION	1999-2001	CP8WF	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
LASER	1998-2001	BJ3PF, BJ5PF, BJ5WF, BJ8WF, BJEPF	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
MITSUBISHI								
AIRTREK	2001-2005	CU2W, CU4W, CU5W	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
ASPIRE	1998-2002	EA1A, EC1A, EA7A, EC7A	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
CANTER	1996				DCS-G020	DCS-G020	DCS-G020	DCS-G020
CANTER (STANDARD)	1993-2010	All	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
CANTER (STANDARD)	2010-	FEA, FBA, FDA, FGA	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
CANTER (WIDE)	1993-2010	All	DCP-021R/L	DCP-021R/L	DCS-G021	DCS-G021	DCV-021	DCV-021
CANTER (WIDE)	2010-	FEB, FEC, FGB	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
CHALLENGER	1996-2001	K94W, K94WG, K96W, K97WG, K99W	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
COLT	2002-2013	Z21A, Z22A, Z23A, Z24A, Z25A, Z26A, Z27A, Z27AG, Z28A	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
COLT DIESEL PS100	1989-1997				DCS-G018	DCS-G018	DCV-018	DCV-018
COLT L300	1988-2004				DCS-G017	DCS-G017	DCV-017	DCV-017
COLT PLUS	2004-2006	Z23W, Z24W, Z27W, Z27WG	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
COLT PLUS	2006-2012	Z21W, Z22W, Z23W, Z24W, Z27WG	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
COLT T120SS	1988-2004				DCS-G017	DCS-G017	DCV-017	DCV-017
DELICA D:2 (INCL. HYBRID)	2011-2015	MB15S	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MITSUBISHI								
DELICA D:2 (INCL. HYBRID)	2015-2020	MB36S, MB46S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
DELICA D:2 (INCL. HYBRID)	2020-2025	MB37S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
DELICA D:2 (INCL. HYBRID)	2025-	MBD7S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
DELICA D:3	2011-2019	BM20	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
DELICA D:5	2007-2019	CV1W, CV2W, CV4W, CV5W	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
DELICA D:5 (DIESEL)	2019-	CV1W	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
DELICA D:5 (GASOLINE)	2019	CV2W, CV5W	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
DELICA MINI	2023-	B34A B35A B37A B38A	DCP-020R/L	*1 DCP-015R/L	DCS-G020	*1 DCS-G015	DCV-020	*1 DCV-G015
DELICA SPACE GEAR	1994-2005	PA4W, PA5W, PB4W, PB5W, PB6W, PC4W, PC5W, PD4W, PD6W, PD8W, PE8W, PF6W, PF8W	*2	*2	*2	*2	*2	*2
DELICA SPACE GEAR	2005-2007	PD6W	*2	*2	*2	*2	*2	*2
DELICA VAN/ CARGO	1999-2011	SK22VM, SK22MM, SK82VM, SKF2VM, SKE6VM, SKF6VM	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
DELICA VAN/ CARGO	2011-2019	BVM20	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
DIAMANTE	1996-2005	F31A, F34A, F36A, F41A, F46A	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
DIAMANTE WAGON	1999-2001	F36W	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
DIGNITY	2012-2016	BHGY51	DCP-026R/L +Side clip	DCP-019R/L +Side clip	DCS-G026 +Side clip	DCS-G019 +Side clip	DCV-026 +Side clip	DCV-019 +Side clip
DION	2000-2002	CR6W, CR9W	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
DION	2002-2006	CR5W, CR6W, CR9W	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
ECLIPSE CROSS (INCL. PHEV)	2018-2020	GK1W, GK9W	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MITSUBISHI								
ECLIPSE CROSS (INCL. PHEV)	2020-	GK1W, GL3W	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
EK CROSS	2019-	B34W, B35W, B37W, B38W	DCP-024R/L	DCP-012R/L	DCS-G024	DCS-G012	DCV-024	DCV-012
EK CROSS EV	2022-	B5AW	DCP-024R/L	DCP-012R/L	DCS-G024	DCS-G012	DCV-024	DCV-012
EK CROSS SPACE	2020-2023	B34A, B35A, B37A, B38A	DCP-020R/L	*1 DCP-015R/L	DCS-G020	DCS-G015	DCV-020	DCV-015
EK SPACE	2014-2020	B11A	DCP-020R/L	*3	DCS-G020	*3	DCV-020	*3
EK SPACE	2020-	B34A, B35A, B37A, B38A	DCP-020R/L	*1 DCP-015R/L	DCS-G020	DCS-G015	DCV-020	DCV-015
EK WAGON (INCL. CUSTOM)	2001-2006	H81W	DCP-019R/L	DCP-014R/L	DCS-G019	DCS-G014	DCV-019	DCV-014
EK WAGON (INCL. CUSTOM)	2006-2013	H82W	DCP-019R/L	DCP-014R/L	DCS-G019	DCS-G014	DCV-019	DCV-014
EK WAGON (INCL. CUSTOM)	2013-2019	B11W	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
EK WAGON (INCL. CUSTOM) (WITH ADAS)	2014-2019	B11W	DCP-024R/L	DCP-012R/L	DCS-G024	DCS-G012	DCV-024	DCV-012
EK WAGON (INCL. CUSTOM)	2019-	B33W, B36W	DCP-024R/L	DCP-012R/L	DCS-G024	DCS-G012	DCV-024	DCV-012
FIGHTER	1992-	FK, FL, FM, FN	*2	*2	*2	*2	*2	*2
FIGHTER	2005-	FK, FL	DCP-026R/L	DCP-026R/LL	DCS-G026	DCS-G026	DCV-026	DCV-026
FUSO DIESEL	1990				DCS-G018	DCS-G018	DCV-018	DCV-018
GALANT	1993				DCS-G018	DCS-G017	DCV-018	DCV-017
GALANT	1996-2005	EA1A, EC1A, EA3A, EC3A, EC5A, EA7A, EC7A	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
GALANT	1997				DCS-G021	DCS-G019	DCV-021	DCV-019
GALANT	2000-2003				DCS-G024	DCS-G018	DCV-024	DCV-018
GALANT	2004-2005				DCS-G026	DCS-G020	DCV-026	DCV-020
GALANT FORTIS	2007-2015	CY3A, CY4A, CY6A	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
GRANDIS	1997-2003	N84W, N86W, N94W, N96W	*2	DCP-016R/L	*2	DCS-G016	*2	DCV-016

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MITSUBISHI								
GRANDIS	2003-2009	NA4W	*2 700mm	DCP-022R/L	*2 700mm	DCS-G022	*2 700mm	DCV-022
GTO	1990-2001	Z15A, Z16A	DCP-021R/L	DCP-020R/L	DCS-G021	DCS-G020	DCV-021	DCV-020
G-WAGON					DCS-G018	DCS-G018	DCV-018	DCV-018
I	2006-2007	HA1W	*3	-	*3	-	*3	-
I	2007-2009	HA1W	*3	-	*3	-	*3	-
I	2009-2013	HA1W	*2	-	*2	-	*2	-
I-MIEV	2009-2021	HA3W, HA4W, HD4W	*2	-	*2	-	*2	-
I-MIEV	2009	HA3W	*3	-	*3	-	*3	-
KUDA	1999-2003				DCS-G020	DCS-G020	DCV-020	DCV-020
LANCER	1997-2000	CK1A, CK2A, CK4A, CK6A, CK8A, CM2A, CM5A, CM8A	DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
LANCER	2002-2007				DCS-G024	DCS-G018	DCV-024	DCV-018
LANCER	2003-2010	CS2A, CS5A, CS6A	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LANCER	2008-2009				DCS-G026	DCS-G018	DCV-026	DCV-018
LANGER CARGO	2002-2008	CS2V	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LANCER CARGO	2008-2019	CVAY12, CVJY12, CVY12, CVZNY12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
LANCER CEDIA	2000-2003	CS2A, CS5A	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LANCER CEDIA WAGON	2000-2003	CS5W	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LANCER EVOLUTION (VII - IX)	2001-2007	CT9A	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LANCER EVOLUTION (X)	2007-2016	CZ4A	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
LANCER EVOLUTION WAGON	2005-2007	CT9W	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MITSUBISHI								
LANCER WAGON	2003-2008	CS2W, CS5W	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LEGNUM	1998-2002	EA1W, EA3W, EA4W, EA7W, EC1W, EC3W, EC5W, EC7W	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
LIBERO	1998-2002	CB2W, CB4W, CB5W, CB8W, CD5W	DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
L200 CYCLONE					DCS-G017	DCS-G017	DCV-017	DCV-017
MAVEN	2007				DCS-G018	DCS-G018	DCV-018	DCV-018
MINICA	1998-2011	H42A, H42V, H47A, H47V	DCP-018R/L	DCP-015R/L	DCS-G018	DCS-G015	DCV-018	DCV-015
MINICAB EV	2023-	U69V	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
MINICAB MIEV	2011-	U67V	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
MINICAB MIEV	2011-2023	U67V, U68V	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
MINICAB MIEV TRUCK	2012-2017	U68T	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
MINICAB MIEV TRUCK	2012-	U68T	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
MINICAB TRUCK	2014-	DS16T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
MINICAB/TOWN BOX (INCL. WIDE)	1999-2005	U61W, U62W, U63W, U64W, U65W, U66W, U6#V	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
MINICAB/TOWN BOX (INCL. WIDE)	2005-2014	U61W, U62W, U61V, U62V, U61T, U61TP, U62T, U62TP	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
MINICAB/TOWN BOX (INCL. WIDE)	2014-2015	DS64V, DS64W	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
MINICAB/TOWN BOX (INCL. WIDE)	2015-	DS17V, DS17W	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
MIRAGE	2012-2020	A03A, A05A	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
MIRAGE	2020-2023	A03A	DCP-022R/L	DCP-015R/L	DCS-G022	DCS-G015	DCV-022	DCV-015
MIRAGE DINGO	1998-2002	CQ1A, CQ2A, CQ5A	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MITSUBISHI								
MIRAGE SEDAN	1997-2000	CK1A, CK2A, CK4A, CK6A, CK8A, CM2A, CM5A, CM8A	DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
NEW TRITON	2015-				DCS-G022	DCS-G016	DCV-022	DCV-016
OUTLANDER	2005-2012	CW4W, CW5W, CW6W	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
OUTLANDER	2012-2013	GF7W, GF8W	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
OUTLANDER	2014-2020	GF7W, GF8W	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
OUTLANDER PHEV	2013-2021	GG2W, GG3W	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
OUTLANDER PHEV	2021-	GN0W	*3	*3	*3	*3	*3	*3
PAJERO	1982				DCS-G017	DCS-G017	DCV-017	DCV-017
PAJERO	1999-2006	V63W, V65W, V68W, V73W, V75W, V77W, V78W	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
PAJERO	2000				DCS-G018	DCS-G018	DCV-018	DCV-018
PAJERO	2006-2009	V83W, V87W, V93W, V97W, V98W	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
PAJERO	2009-2019	V83W, V87W, V88W, V93W, V97W, V98W	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
PAJERO IO	1998-2007	H61W, H62W, H66W, H67W, H71W, H72W, H76W, H77W	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
PAJERO MINI	1998-2008	H53A, H58A	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
PAJERO MINI	1998-2013	H53A, H58A	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
PAJERO SPORT					DCS-G022	DCS-G018	DCV-022	DCV-018
PROUDIA	2012-2016	BY51, BKY51, BKNY51	DCP-026R/L +Side clip	DCP-019R/L +Side clip	DCS-G026 +Side clip	DCS-G019 +Side clip	DCV-026 +Side clip	DCV-019 +Side clip
ROSA	1997-2019	BE6#, BG6#	DCP-022R/L	DCP-021R/L	DCS-G022	DCS-G021	DCV-022	DCV-021
ROSA	2019-	BE7#, BG7#	DCP-022R/L	DCP-021R/L	DCS-G022	DCS-G021	DCV-022	DCV-021

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
MITSUBISHI								
RVR	1997-2002	N61W, N64WG, N71W, N73WG, N74WG	*2	DCP-016R/L	*2	DCS-G016	*2	DCV-016
RVR	2010-2024	GA3W, GA4W	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
STRADA	2000				DCS-G018	DCS-G018	DCV-018	DCV-018
TOPPO	2008-2013	H82A	DCP-020R/L	*1 DCP-015R/L	DCS-G020	*1 DCS-G015	DCV-020	*1 DCV-G015
TOPPO BJ (INCL. WIDE)	1998-2001	H41A, H42A, H42V, H43A, H46A, H47A, H47V, H48A	DCP-020R/L	DCP-015R/L	DCS-G020	DCS-G015	DCV-020	DCV-015
TOPPO BJ (INCL. WIDE)	2001-2004	H41A, H42A, H42V, H46A, H47A, H47V	DCP-020R/L	DCP-015R/L	DCS-G020	DCS-G015	DCV-020	DCV-015
TRITON	2006				DCS-G021	DCS-G019	DCV-021	DCV-019
TRITON	2006-2011	KB9T	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
TRITON	2024-	LC2T	*2	*2	*2	*2	*2	*2
MITSUOKA								
GALUE I	1999-2001	HK30	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
GALUE II	1999-2005	HY34, MY34	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
GALUE III	2005-2010	Y50, PY50, PNY50	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
NOUERA	2003-2008	CL7, CL8, CL9	DCP-026R/L	DCP-015R/L	DCS-G026	DCS-G015	DCV-026	DCV-015
RAY	1996-2000	AC6P, AC6R, HB12S	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
TYPE-F	1996-2000	N/A	*2	*2	*2	*2	*2	*2
VIEWT	1996-2005	K11, K11, AK11, HK11	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
VIEWT	2005-2010	AK12, BNK12, YK12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
ZERO 1	1994-2000	MS01	*2	*2	*2	*2	*2	*2
NISSAN								
AD	2021-	VY12, VZNY12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
AD WAGON/ VAN/MAX	2004-2008	Y11	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
AD WAGON/ VAN/MAX	1999-2004	Y11	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
AD/AD EXPART	2006-2016	VAY12, VJY12, VY12, VZNY12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
ARIYA	2022-	FE0, SNFE0	*3	*3	*3	*3	*3	*3
ATLAS	1991-2007	H41 (STANDARD), F23	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
ATLAS (F24)	2007-2021	F24	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ATLAS (F25)	2019-2023	AHR, AHS	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ATLAS (F25) (STANDARD)	2021-2023	AJR, ALS, ALR, AJS, AKR, AMR, AKS, AMS	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ATLAS (F25) (WIDE)	2021-2023	ANR, APR, APS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
ATLAS (F26) (STANDARD)	2023-	AJR88AF, AKR88AF, AKR88C, AKR88AC, AMR88C, ALR88AC, AMR88AC, AJR88AT, AKR88AT	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ATLAS (F26) (WIDE)	2023-	ANR88AC, APR88AC	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
ATLAS (H42) (STANDARD)	1995-2006	AKR, AKS	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ATLAS (H42) (WIDE)	1995-2006	AKR, AKS	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
ATLAS (H43) (STANDARD)	2007-2012	STD WIDE	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ATLAS (H43) (WIDE)	2007-2012	WIDE	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
ATLAS MAX	1998-2001	AHR, AKR	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
AURA	2021-	FE13, FSNE13	DCP-026R/L +Side clip	DCP-014R/L	DCS-G026 +Side clip	DCS-G014	DCV-026 +Side clip	DCV-014
AVENIR	1998-2005	PW11, PNW11, RW11, RNW11, SW11, W11	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
BASSARA	1999-2000	JU30, JNU30, JHU30, JVU30, JVNU30	DCP-026R/L	DCP-021R/L	DCS-G026	DCS-G021	DCV-026	DCV-021

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
BASSARA	2000-2003	JTU30, JTNU30, JHU30, JU30, JNU30, JVU30, JVNU30	DCP-026R/L	DCP-021R/L	DCS-G026	DCS-G021	DCV-026	DCV-021
BLUEBIRD	1996-2000	EU14, ENU14, HU14, HNU14, SU14, QU14	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
BLUEBIRD SYLPHY	2000-2005	QG10, QNG10, FG10, TG10	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
BLUEBIRD SYLPHY	2005-2012	G11, NG11, KG11	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
CARAVAN (EXCL. WIDE)	2021-	###E26	DCP-022R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
CARAVAN/HOMY	1997-2001	KRE24, KRME24, KRGE24	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
CARAVAN/HOMY	2001-2003	CQGE25, CWGE25, CWMGE25, QGE25	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
CARAVAN/HOMY	2003-2012	SE25, SGE25, QE25, QGE25, VPE25, VWE25, VWME25	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
CEDRIC	1987-1999				DCS-G020	DCS-G019	DCV-020	DCV-019
CEDRIC/GLORIA	1999-2004	MY34, ENY34, HY34	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CEFIRO	1998-2003	A33, PA33	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
CEFIRO	2000-	A331			DCS-G024	DCS-G018	DCV-024	DCV-018
CEFIRO	2001				DCS-G024	DCS-G019	DCV-024	DCV-019
CEFIRO WAGON	1998-2003	WPA32, WHA32, WA32	DCP-022R/L	DCP-021R/L	DCS-G022	DCS-G021	DCV-022	DCV-021
CIMA	1998-2000	FGY33, FHY33, FGDY33, FGNY33	*3	*3	*3	*3	*3	*3
CIMA	2001-2010	GF50, GNF50, HF50	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
CIMA	2012-2022	HGY51	DCP-026R/L +Side clip	DCP-019R/L +Side clip	DCS-G026 +Side clip	DCS-G019 +Side clip	DCV-026 +Side clip	DCV-019 +Side clip
CIMA (WITH ADAS)	2012-2022	HGY51	DCP-026R/L +Side clip	DCP-019R/L +Side clip	DCS-G026 +Side clip	DCS-G019 +Side clip	DCV-026 +Side clip	DCV-019 +Side clip
CIVILIAN	1999-2021	ECW41, EVW41, DCW41, DVW41, EJW41, EHW41, DJW41, DHW41	DCP-024R/L	DCP-024R/L	DCS-G024	DCS-G024	DCV-024	DCV-024

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
CLIPPER EV	2024-	U79V	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
CLIPPER TRUCK (NT100)	2024-	DR16T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
CLIPPER VAN/ TRUCK	2003-2005	U71W, U72W, U71V, U72V, U71T, U71TP, U72T, U72TP	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
CLIPPER VAN/ TRUCK (INCL. RIO)	2006-2012	U71W, U72W, U71V, U72V, U71T, U71TP, U72T, U72TP	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
CLIPPER VAN/ WAGON (NV100)	2024-	DR17V, DR17W	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
CREW	1994-2009	HK30, SK30	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
CUBE/CUBE CUBIC	1999-2000	Z10, AZ10, ANZ10	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
CUBE/CUBE CUBIC	2000-2002	AZ10, ANZ10	DCP-022R/L	DCP-015R/L	DCS-G022	DCS-G015	DCV-022	DCV-015
CUBE/CUBE CUBIC	2002-2008	BZ11, BNZ11, YZ11, BGZ11, YGZ11, YGNZ11	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
CUBE/CUBE CUBIC	2008-2020	Z12, NZ12	*2	*2	*2	*2	*2	*2
DATSUN TRUCK	1999-2002	LFD22, LFMD22, LRMD22	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
DAYS	2013-2019	B21W	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
DAYS (WITH ADAS)	2014-2019	B21W	DCP-024R/L	DCP-012R/L	DCS-G024	DCS-G012	DCV-024	DCV-012
DAYS	2019-	B43W, B44W, B45W, B46W, B47W, B48W	DCP-024R/L	DCP-012R/L	DCS-G024	DCS-G012	DCV-024	DCV-012
DAYS ROOX	2014-2020	B21A	DCP-020R/L	*3	DCS-G020	*3	DCV-020	*3
DUALIS	2007-2014	J10, KJ10, NJ10, KNJ10	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
ELGRAND	1997-2002	ALE50, ALWE50, APE50, APWE50, ATE50, ATWE50, FLGE50, FLWGE50	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
ELGRAND	2002-2010	E51, ME51, MNE51, NE51	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
ELGRAND	2010-	PE52, PNE52, TE52, TNE52	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
EXPERT	1999-2006	VW11, VNW11, VEW11, VENW11	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
EXTRAIL (INCL. HYBRID)	2022-	SNT33, T33	*3	*3	*3	*3	*3	*3
FAIRLADY Z	1993-2000	Z32, GZ32, CZ32, GCZ32, HZ32	DCP-021R/L	DCP-021R/L	*3	*3	*3	*3
FAIRLADY Z	2002-2008	Z33, HZ33	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
FAIRLADY Z	2008-2012	Z34, HZ34	DCP-021R/L +Side clip	DCP-019R/L +Side clip	DCS-G021 +Side clip	DCS-G019 +Side clip	DCV-021 +Side clip	DCV-019 +Side clip
FAIRLADY Z	2008-2022	Z34, HZ34	DCP-021R/L +Side clip	DCP-019R/L +Side clip	DCS-G021 +Side clip	DCS-G019 +Side clip	DCV-021 +Side clip	DCV-019 +Side clip
FAIRLADY Z	2022-	RZ34	DCP-021R/L +Side clip	DCP-019R/L +Side clip	DCS-G021 +Side clip	DCS-G019 +Side clip	DCV-021 +Side clip	DCV-019 +Side clip
FRONTIER	2000				DCS-G018	DCS-G018	DCV-018	DCV-018
FRONTIER	2000-				DCS-G019	DCS-G019	DCV-019	DCV-019
FUGA (INCL. HYBRID)	2004-2009	Y50, PY50, GY50, PNY50	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
FUGA (INCL. HYBRID)	2009-2010	KNY51, KY51, Y51	*3	*3	*3	*3	*3	*3
FUGA (INCL. HYBRID)	2010-2022	HY51, KNY51, KY51, Y51	DCP-026R/L +Side clip	DCP-019R/L +Side clip	DCS-G026 +Side clip	DCS-G019 +Side clip	DCV-026 +Side clip	DCV-019 +Side clip
GRAND LIVINA	2007-2010				DCS-G024	DCS-G014	DCV-024	DCV-014
GT-R	2007-2025	R35	N/A	N/A	N/A	N/A	N/A	N/A
JUKE	2010-2020	YF15, F15, NF15	*7 i55G	*2	*2	*2	*2	*2
KICKS	2008-2012	H59A	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
KICKS E-POWER	2020-	P15	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
LAFESTA (INCL. JOY)	2004-2012	B30, NB30	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
LAFESTA HIGHWAY STAR	2011-2018	CWEAWN, CWEFWN, CWFFWN	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
LAFESTA/ LAFESTA JOY	2004-2012	B30, NB30	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
LATIO	2005				DCS-G022	DCS-G016	DCV-022	DCV-016

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
LATIO	2012-2016	N17	DCP-021R/L	DCP-014R/L	*1 DCS-G021	*1 DCS-G014	*1 DCV-G021	*1 DCV-G014
LAUREL	1997-2002	HC35, GC35, GNC35, GCC35, SC35	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
LEAF	2010-2017	ZE0, AZE0	DCP-026R/L +Side clip	DCP-016R/L	DCS-G026 +Side clip	DCS-G016	DCV-026 +Side clip	DCV-016
LEAF	2017-	ZE1	DCP-026R/L +Side clip	DCP-016R/L	DCS-G026 +Side clip	DCS-G016	DCV-026 +Side clip	DCV-016
MARCH					DCS-G018	DCS-G018	DCV-018	DCV-018
MARCH	1995-2002	K11, AK11, ANK11, HK11, FHK11	DCP-021R/L	DCP-018R/L	*3	*3	*3	*3
MARCH	2002-2003	K12, AK12, BK12, BNK12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
MARCH	2003-2010	AK12, BK12, BNK12, YK12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
MARCH	2010-2022	K13, NK13	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
MARCH	2012-				DCS-G021	DCS-G014	DCV-021	DCV-014
MICRA C+C	2007-2010	FHZK12	*2	*2	*2	*2	*2	*2
MOCO	2002-2004	MG21S	DCP-021R/L	DCP-012R/L	DCS-G021	DCS-G012	DCV-021	DCV-012
MOCO	2004-2006	MG21S	DCP-021R/L	DCP-012R/L	DCS-G021	DCS-G012	DCV-021	DCV-012
MOCO	2006-2011	MG22S	DCP-020R/L	DCP-014R/L	DCS-G020	*1 DCS-G014	DCV-020	*1 DCV-014
MOCO	2011-2016	MG33S	DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
MURANO	2004-2008	TZ50, PZ50, PNZ50	*3	DCP-018R/L +Side clip	*3	DCS-G018 +Side clip	*3	DCV-018 +Side clip
MURANO	2008-2015	TNZ51, PNZ51, TZ51	*3	DCP-016R/L +Side clip	*3	DCS-G016 +Side clip	*3	DCV-016 +Side clip
NAVARA	2003				DCS-G024	DCS-G019	DCV-024	DCV-019
NAVARA					DCS-G024	DCS-G020	DCV-024	DCV-020
NOTE (INCL. E-POWER)	2005-2012	E11, NE11, ZE11	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
NOTE (INCL. E-POWER) (E12)	2012-2021	E12, HE12, NE12, SNE12	DCP-026R/L +Side clip	DCP-012R/L +Side clip	DCS-G026 +Side clip	DCS-G012 +Side clip	DCV-026 +Side clip	DCV-012 +Side clip
NOTE (INCL. E-POWER) (E13)	2020-	E13, SNE13	DCP-026R/L +Side clip	DCP-014R/L	DCS-G026 +Side clip	DCS-G014	DCV-026 +Side clip	DCV-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
NT100 CLIPPER TRUCK	2012-2013	U71T, U71TP, U72T, U72TP	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
NT100 CLIPPER TRUCK	2013-2024	DR16T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
NT100 CLIPPER TRUCK	2019-2024	DR16T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
NT45 ATLAS (H44) (STANDARD)	2013-2021	FBA, FDA, FEA, FGA	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
NT45 ATLAS (H44) (WIDE)	2013-2021	FEB, FGB	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
NV100 CLIPPER (INCL. RIO)	2012-2013	U71V, U72V, U71W, U72W	DCP-017R/L	DCP-015R/L	DCS-G017	DCS-G015	DCV-017	DCV-015
NV100 CLIPPER (INCL. RIO)	2013-2015	DR64V, DR64W	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
NV100 CLIPPER (INCL. RIO)	2015-2024	DR17V, DR17W	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
NV100 CLIPPER (INCL. RIO)	2019-2024	DR17V, DR17W	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
NV150 AD	2016-2021	VY12, VZNY12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
NV200 VANNET	2009-	M20, VM20, VNM20	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
NV350 CARAVAN (EXCL. WIDE)	2012-2022	###E26	DCP-022R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
OTTI	2005-2006	H91W	DCP-019R/L	DCP-014R/L	DCS-G019	DCS-G014	DCV-019	DCV-014
OTTI	2006-2013	H92W	DCP-019R/L	DCP-014R/L	DCS-G019	DCS-G014	DCV-019	DCV-014
PINO	2007-2010	HC24S	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
PRAIRIE/LIBERTY	1998-2004	PM12, PNM12, RM12, RNM12	*7 DCP-026R/L	DCP-015R/L	*7 DCS-G026	DCS-G015	*7 DCV-026	DCV-015
PRESEA	1995-2000	R11, HR11, PR11	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
PRESAGE	1998-2000	U30, NU30, HU30, VU30, VNU30	DCP-026R/L	DCP-021R/L	DCS-G026	DCS-G021	DCV-026	DCV-021
PRESAGE	2000-2003	TU30, TNU30, HU30, U30, NU30, VU30, VNU30	DCP-026R/L	DCP-021R/L	DCS-G026	DCS-G021	DCV-026	DCV-021

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

*1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 *2 No applicable item is available
 *3 No applicable item is available because of contact with the car body or wiper arm
 *4 Please take off the plastic part put on the wiper arm
 *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 *7 Shorter than OEM wiper
 *8 Possible to make contact with the mole when the wiper is operated at high speed
 *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
PRESAGE	2003-2009	TU31, TNU31, PU31, PNU31	*7 DCP-026R/L	DCP-016R/L	*7 DCS-G026	DCS-G016	*7 DCV-026	DCV-016
PRIMER/ PRIMERA CAMINO	2001-2005	HP12, TP12, TNP12, QP12, RP12	DCP-026R/L	DCP-019R/L	DCS-G026	DCS-G019	DCV-026	DCV-019
PRIMER/ PRIMERA CAMINO	1995-2000	P11, FHP11, HP11, HNP11, QP11	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
PRIMERA WAGON/ PRIMERA CAMINO WAGON	2000-2000	WQP11, WHP11, WHNP11	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
PRIMERA WAGON/ PRIMERA CAMINO WAGON	2001-2005	WTP12, WTNP12, WRP12, WHP12	DCP-026R/L	DCP-019R/L	DCS-G026	DCS-G019	DCV-026	DCV-019
PULSAR					DCS-G020	DCS-G018	DCV-020	DCV-018
PULSAR/ LANGLEY HATCHBACK	1995-2000	FN15, FNN15, EN15, JN15, HN15	DCP-021R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
PULSAR/ LANGLEY SEDAN	1995-2000	FN15, FNN15, SN15, SNN15, EN15, JN15, HN15	DCP-021R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
PULSAR/ LANGLEY (5 DOOR)	1995-2000	N15	DCP-021R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
PULSAR SERIE S-RV	1996-2000	FN15, FNN15, JN15, HNN15	DCP-021R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
RASHEEN	1994-2000	RKNB14, RFNB14	DCP-021R/L	DCP-020R/L	*3	*3	*3	*3
R'NESSA	1998-2001	N30, NN30, PNN30	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
ROOX	2009-2010	ML21S	DCP-021R/L	*1 DCP-016R/L	DCS-G021	DCS-G016	DCV-021	DCV-016
ROOX	2010-2013	ML21S	DCP-020R/L	*1 DCP-016R/L	*3	DCS-G016	*3	DCV-016
ROOX	2020-	B44A, B45A, B47A, B48A	DCP-020R/L	*1 DCP-015R/L	DCS-G020	DCS-G015	DCV-020	DCV-015
SAFARI	1997-2007	WFGY61, WTY61, VRGY61, WGY61, WYY61	DCP-019R/L	DCP-020R/L	DCS-G019	DCS-G020	DCV-019	DCV-020

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
SAKURA	2022-		DCP-024R/L	DCP-012R/L	DCS-G024	DCS-G012	DCV-024	DCV-012
SENTRA	2000				DCS-G022	DCS-G016	DCV-022	DCV-016
SERENA (INCL. HYBRID)	1999-2001	PC24, PNC24, VC24, VNC24	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
SERENA (INCL. HYBRID)	2001-2005	TC24, TNC24, RC24	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
SERENA (INCL. HYBRID)	2005-2010	C25, NC25, CC25, CNC25	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
SERENA (INCL. HYBRID)	2010-2013	C26, FC26, NC26, FNC26, HC26, HFC26	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
SERENA (INCL. HYBRID)	2013-2016	C26, NC26, FNC26, HC26, HFC26	DCP-026R/L +Side clip	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
SERENA (INCL. HYBRID)	2016-2022	C27, GC27, GFC27, GFNC27, GNC27, HC27, HFC27	*7 DCP-024R/L +Side clip	DCP-014R/L +Side clip	*7 DCS-G024 +Side clip	DCS-G014 +Side clip	*7 DCV-024 +Side clip	DCV-014 +Side clip
SERENA (INCL. HYBRID)	2022-	C28 FC28 FNC28 GC28 GFC28 NC28 SFNC28 SNC28	*7 DCP-024R/L +Side clip	DCP-014R/L +Side clip	*7 DCS-G024 +Side clip	DCS-G014 +Side clip	*7 DCV-024 +Side clip	DCV-014 +Side clip
SERENA (NEW)	2005				DCS-G024	DCS-G014	DCV-024	DCV-014
SILVIA	1999-2002	S15	DCP-021R/L	DCP-020R/L	DCS-G021	DCS-G020	DCV-021	DCV-020
SKYLINE	1998-2000	ER34, BNR34, ENR34, HR34	DCP-021R/L	DCP-021R/L	*3	*3	*3	*3
SKYLINE	2000-2001	BNR34, HR34, ER34, ENR34	DCP-021R/L	DCP-021R/L	DCS-G021	DCS-G021	DCV-021	DCV-021
SKYLINE	2001-2006	V35, NV35, PV35, HV35	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
SKYLINE	2006-2010	V36, NV36, KV36, PV36	DCP-024R/L +Side clip	DCP-017R/L	DCS-G025 +Side clip	DCS-G017	DCV-024 +Side clip	DCV-017
SKYLINE	2011-2014	V36, NV36, KV36, PV36	DCP-024R/L +Side clip	DCP-017R/L	DCS-G025 +Side clip	DCS-G017	DCV-024 +Side clip	DCV-017
SKYLINE (INCL. HYBRID)	2014-	HV37, HNV37, ZV37	DCP-026R/L +Side clip	DCP-017R/L	DCS-G026 +Side clip	DCS-G017	DCV-026 +Side clip	DCV-017
SKYLINE (INCL. HYBRID) (WITH ADAS)	2014-	HV37, HNV37, RV37, YV37, ZV37	DCP-026R/L +Side clip	DCP-017R/L	DCS-G026 +Side clip	DCS-G017	DCV-026 +Side clip	DCV-017
SKYLINE COUPE	2003-2007	CPV35	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
SKYLINE COUPE	2007-2010	CKV36	DCP-024R/L +Side clip	*7 DCP-016R/L +Side clip	DCS-G025 +Side clip	*7 DCS-G016 +Side clip	DCV-024 +Side clip	*7 DCV-016 +Side clip
SKYLINE COUPE	2011-2016	CKV36	*3	*3	*3	*3	*3	*3
SKYLINE CROSSOVER	2009-2011	J50, NJ50	*7 DCP-022R/L +Side clip	*7 DCP-017R/L +Side clip	*7 DCS-G022 +Side clip	*7 DCS-G017 +Side clip	*7 DCV-022 +Side clip	*7 DCV-017 +Side clip
SKYLINE CROSSOVER	2011-2012	J50, NJ50	*7 DCP-022R/L +Side clip or *2	*7 DCP-017R/L +Side clip or *2	*7 DCS-G022 +Side clip or *2	*7 DCS-G017 +Side clip or *2	*7 DCV-022 +Side clip or *2	*7 DCV-017 +Side clip or *2
SKYLINE CROSSOVER	2012-2016	J50, NJ50	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
STAGEA	1999-2001	WHC34, WGC34, WGNC34	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
STAGEA	2001-2007	M35, NM35, PM35, PNM35	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
SUNNY	1998-2004	B15, FB15, FNB15, QB15, SB15, JB15	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
SUNNY	2000				DCS-G021	DCS-G016	DCV-021	DCV-016
SUNNY LUCINO HATCH	1995-2000	FN15, FNN15, EN15, JN15, HN15	DCP-021R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
SUNNY LUCINO S-RV	1996-2000	FN15, FNN15, JN15, HNN15	DCP-021R/L	DCP-019R/L	*3	DCS-G019	*3	DCV-019
SUNNY NEO/ALMERA	2000-				DCS-G022	DCS-G016	DCV-022	DCV-016
SUNNY/SENTRA	1998-2004	B15, FB15, FNB15, QB15, SB15, JB15	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
SYLPHY	2012-2021	TB17	*3	DCP-014R/L +Side clip	*3	DCS-G014 +Side clip	*3	DCV-014 +Side clip
SYLPHY	2013-				DCS-G024	DCS-G014	DCV-024	DCV-014
TEANA	2003-2008	J31, TNJ31, PJ31	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
TEANA	2008-2014	J32, TNJ32, PJ32	DCP-026R/L +Side clip	DCP-017R/L	DCS-G026 +Side clip	DCS-G017	DCV-026 +Side clip	DCV-017
TEANA	2014-2020	L33	DCP-026R/L +Side clip	DCP-016R/L +Side clip	DCS-G026 +Side clip	DCS-G016 +Side clip	DCV-026 +Side clip	DCV-016 +Side clip
TERRANO	1997-2001				DCS-G019	DCS-G019	DCV-019	DCV-019

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
NISSAN								
TERRANO (INCL. REGRAS)	1998-2002	TR50, LR50, LUR50, JTR50, JLUR50	DCP-022R/L	DCP-021R/L	DCS-G022	DCS-G021	DCV-022	DCV-021
TIIDA	2004-2012	C11, NC11, JC11	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
TIIDA LATIO	2004-2012	SC11, SNC11, SJC11	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
TINO	1998-2003	V10, HV10, PV10	DCP-026R/L	DCP-019R/L	DCS-G026	DCS-G019	DCV-026	DCV-019
VANNETTE	1999-2017	SK	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
WINGROAD	1999-2001	WFY11, WHNY11, WHY11, WPY11	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
WINGROAD	2001-2005	WFY11, WHNY11, WRY11	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
WINGROAD	2005-2018	Y12, NY12, JY12	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
X-TRAIL	2003-2007				DCS-G024	DCS-G015	DCV-024	DCV-015
X-TRAIL (INCL. HYBRID)	2000-2007	T30, NT30, PNT30	DCP-024R/L	DCP-015R/L	DCS-G024	DCS-G015	DCV-024	DCV-015
X-TRAIL (INCL. HYBRID)	2007-2010	DNT31, NT31, T31, TNT31	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
X-TRAIL (INCL. HYBRID)	2010-2013	DNT31, NT31, T31, TNT31	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
X-TRAIL (INCL. HYBRID)	2013-2022	HNT32, HT32, NT32, T32	DCP-026R/L +Side clip	DCP-017R/L +Side clip	DCS-G026 +Side clip	DCS-G017 +Side clip	DCV-026 +Side clip	DCV-017 +Side clip
PEUGEOT								
206	2000				DCS-G024	DCS-G020	DCV-024	DCV-020
306	1993-				DCS-G022	DCS-G020	DCV-022	DCV-020
406	1999-				DCS-G024	DCS-G022	DCV-024	DCV-022
PROTON								
GEN2	2004-2005				DCS-G021	DCS-G019	DCV-021	DCV-019
SAVVY	2005				DCS-G022	DCS-G016	DCV-022	DCV-016
ROVER								
FREELANDER	2001-				DCS-G022	DCS-G022	DCV-022	DCV-022
SEAT								
TOLEDO	2000-				DCS-G021	DCS-G019	DCV-021	DCV-019

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SSYANGYONG								
MUSSO	1995-				DCS-G020	DCS-G018	DCV-020	DCV-018
SUBARU								
BRZ	2012-2021	ZC6	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
BRZ	2021-	ZD8	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
CHIFFON (INCL. CUSTOM)	2016-2019	LA600F, LA610F	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
CHIFFON (INCL. CUSTOM)	2019-	LA650F, LA660F	DCP-019R/L	DCP-019R/L	DCS-G019	*1 DCS-G019	DCV-019	*1 DCV-G019
CROSTRECK	2022-	GUD, GUE, GUF	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
DEX	2008-2011	M401F, M411F	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
DIAS WAGON	2009-2017	S321N, S331N	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
DIAS WAGON	2017-2020	S321N, S331N	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
EXIGA	2008-2015	YA4, YA5, YA9, YAM	*3	DCP-018R/L	*3	DCS-G018	*3	DCV-018
FORESTER	2000-2002	SF5	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
FORESTER	2002-2003	SG5	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
FORESTER	2003-2005	SG5, SG9	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
FORESTER	2005-2007	SG5, SG9	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
FORESTER	2007-2012	SH5, SH9, SHJ	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
FORESTER	2017-2018	SJ5, SJG	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
FORESTER	2018-2025	SK5, SK9, SKE	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
FORESTER (2.0i)	2012-2017	SJ5	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
FORESTER (2.0i-L/2.0i-S)	2012-2015	SJ5	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
FORESTER (2.0i-L/2.0i-S)	2015-2017	SJ5	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
FORESTER (S/X/2.0XT)	2012-2015	SJ5, SJG	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
FORESTER (S/X/2.0XT)	2015-2017	SJ5, SJG	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
IMPREZA	2023-	GU6, GU7, GUD, GUE	*2	*2	*2	*2	*2	*2

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUBARU								
IMPREZA (1.5i)	2009-2011	GH2, GH3	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA (1.5i-S)	2009-2011	GH2, GH3	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA (5 DOOR)	2007-2009	GH2, GH3, GH6, GH7, GH8	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA (5 DOOR)	2009-2011	GH6, GH7, GH8	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA ANESIS	2008-2009	GE2, GE3, GE6, GE7	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA ANESIS	2009-2011	GE6, GE7	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA ANESIS (1.5i)	2009-2011	GE2, GE3	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA ANESIS (1.5-i-L)	2009-2011	GE2, GE3	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA G4	2011-2014	GJ2, GJ3, GJ6, GJ7	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
IMPREZA G4	2014-2016	GJ2, GJ3, GJ6, GJ7	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
IMPREZA G4	2016-2023	GK2, GK3, GK6, GK7	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
IMPREZA SEDAN	1992-2000	GC1, GC2, GC4, GC6, GC8	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
IMPREZA SEDAN	2000-2007	GD2, GD3, GD9, GDA, GDB, GDC, GDD	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
IMPREZA SPORT (INCL. HYBRID)	2011-2014	GP2, GP3, GP6, GP7, GPE	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
IMPREZA SPORT (INCL. HYBRID)	2014-2016	GP2, GP3, GP6, GP7, GPE	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
IMPREZA SPORT (INCL. HYBRID)	2016-2023	GT2, GT3, GT6, GT7, GTE	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
IMPREZA WAGON	1992-2000	GF1, GF2, GF3, GF4, GF5, GF6, GF8, GFA	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
IMPREZA WAGON	2000-2004	GG2, GG3, GG9, GGA, GGB	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
IMPREZA WAGON	2004-2007	GG2, GG3, GG9, GGA, GGB, GGC, GGD	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
IMPREZA WRX STI (4 DOOR)	2010-2014	GVB, GVF	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUBARU								
IMPREZA WRX STI (5 DOOR)	2007-2014	GRB, GRF	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IMPREZA XV	2010-2011	GH2, GH3, GH6, GH7	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
JUSTY (INCL. CUSTOM)	2016-2018	M900F, M910F	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
JUSTY (INCL. CUSTOM)	2018-	M900F, M910F	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
LEGACY AUTOBACK	2003-2009	BP9, BPE, BPH	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LEGACY AUTOBACK	2009-2014	BR9, BRF, BRM	DCP-026R/L	DCP-019R/L	DCS-G026	DCS-G019	DCV-026	DCV-019
LEGACY AUTOBACK	2014-2021	BS9	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
LEGACY AUTOBACK	2021-2025	BT5	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
LEGACY B4 SEDAN	1998-2001	BE5, BE9	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
LEGACY B4 SEDAN	2001-2003	BE5, BE9, BEE, BES	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
LEGACY B4 SEDAN	2003-2009	BL5, BL9, BLE	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LEGACY B4 SEDAN	2009-2014	BM9, BMG, BMM	DCP-026R/L	DCP-019R/L	DCS-G026	DCS-G019	DCV-026	DCV-019
LEGACY B4 SEDAN	2014-2015	BN9	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
LEGACY B4 SEDAN	2015-2020	BN9	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
LEGACY TOURING WAGON	1998-2003	BH5, BH9, BHC, BHE	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
LEGACY TOURING WAGON	2003-2009	BP5, BP9, BPE	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
LEGACY TOURING WAGON	2009-2014	BR9, BRG, BRM	DCP-026R/L	DCP-019R/L	DCS-G026	DCS-G019	DCV-026	DCV-019
LEONE VAN	1999-2001	Y11	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
LEVORG	2014-2020	VM4, VMG	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUBARU								
LEVORG	2020-	VN5, VNH	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
LUCRA	2010-2015	L455F, L465F	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
PREO	1998-2000	RA1, RA2, RV1, RV2	DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
PREO	2000-2010	RA1, RA2, RV1, RV2	DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
PREO	2010-2018	L275F, L285F	DCP-022R/L	DCP-012R/L	DCS-G022	DCS-G012	DCV-022	DCV-012
PREO PLUS	2012-2017	LA300F, LA310F	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
PREO PLUS	2017-	LA350F, LA360F	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
R1	2004-2010	RJ1, RJ2	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
R2	2003-2010	RC1, RC2	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
REX	2022-	A201F	DCP-021R/L	*1 DCP-015R/L	DCS-G021 +Side clip	DCS-G015 +Side clip	DCV-021 +Side clip	DCV-015 +Side clip
SAMBAR TRUCK	2012-2014	S201J, S211J	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
SAMBAR TRUCK	2014-2018	S500J, S510J	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
SAMBAR TRUCK (INCL. GRAND CAB)	2018-	S500J, S510J	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
SAMBAR TRY/DIAS	1999-2002	TV1, TV2, TW1	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
SAMBAR TRY/DIAS	2002-2003	TW1, TW2, TV1, TV2, TT1, TT2	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
SAMBAR TRY/DIAS	2003-2006	TW1, TW2, TV1, TV2, TT1, TT2	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
SAMBAR TRY/DIAS	2006-2012	TW1, TW2, TV1, TV2, TT1, TT2	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
SAMBAR TRY/DIAS	2012-2017	S321B, S331B, S321Q, S331Q	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
SAMBAR TRY/DIAS	2017-2021	S321B, S331B, S321Q, S331Q	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
SAMBAR VAN	2022-	S700B, S710B	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
SOLTERRA	2022-	XEAM10X, YEAM15X	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
STELLA (INCL. CUSTOM)	2006-2011	RN1, RN2	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUBARU								
STELLA (INCL. CUSTOM)	2011-2014	LA100F, LA110F	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
STELLA (INCL. CUSTOM)	2014-2017	LA150F, LA160F	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
STELLA (INCL. CUSTOM)	2017-	LA150F, LA160F	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
TRAVIQ	2000-2004	XM182, XM220	*2	*2	*2	*2	*2	*2
TREZIA	2010-2016	NSP120X, NCP120X, NCP125X	*2 700mm	-	*2 700mm	-	*2 700mm	-
WRX S4	2014-2016	VAG	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
WRX S4	2016-2021	VAG	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
WRX S4	2021-	VBH	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
WRX STI	2014-2016	VAB	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
WRX STI	2016-2020	VAB	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
XV (INCL. HYBRID)	2012-2014	GP7, GPE	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
XV (INCL. HYBRID)	2014-2017	GP7, GPE	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
XV (INCL. HYBRID)	2017-2022	GT3, GT7, GTE	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
SUZUKI								
AERIO	2001-2003	RA21S, RB21S, RC51S, RD51S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
AERIO	2003-2007	RA21S, RB21S, RC51S, RD51S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
ALTO (INCL. HYBRID)	1998-2004	HA12S, HA12V, HA22S, HA23S, HA23V	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
ALTO (INCL. HYBRID)	2004-2009	HA24S, HA24V	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
ALTO (INCL. HYBRID)	2009-2014	HA25S, HA25V, HA35S	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
ALTO (INCL. HYBRID)	2014-2021	HA36S, HA36V	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUZUKI								
ALTO (INCL. HYBRID)	2021-	HA37S, HA97S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
APV	2004				DCS-G017	DCS-G017	DCV-017	DCV-017
BALENO	2016-2020	WB32S, WB42S	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
BALENO	2020-				DCS-G020	DCS-G018	DCV-020	DCV-018
CARRY	1990-2005				DCS-G017	DCS-G017	DCV-017	DCV-012
CARRY (INCL. SUPER CARRY)	2013-2019	DA16T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
CARRY (INCL. SUPER CARRY)	2019-	DA16T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
CARRY/EVERY	1999-2002	DA52V, DA52W, DA62V, DA62W, DB52V, DA62T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
CARRY/EVERY	2002-2005	DA62V, DA62W, DA63T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
CARRY/EVERY	2005-2013	DA64V, DA64W, DA63T, DA65T	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
CERVO	2006-2009	HG21S	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
CHEVROLET CRUISE	2001-2008	HR51S, HR52S, HR81S, HR82S	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
CHEVROLET MW	2000-2010	ME34S, ME63S, ME64S	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
CULTUS CRESCENT WAGON	1997-2002	GC21W, GC41W, GD31W	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
ELIO	2001-2004	RA21S, RB21S, RC51S, RD51S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
ELIO	2004-2007	RA21S, RB21S, RC51S, RD51S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
ESCUDO	1994-				DCS-G019	DCS-G018	DCV-019	DCV-019
ESCUDO	2001				DCS-G017	DCS-G017	DCV-017	DCV-017
ESCUDO	2003				DCS-G019	DCS-G019	DCV-019	DCV-019
ESCUDO (INCL. HYBRID)	1997-2005	TA02W, TA52W, TD02W, TD32W, TD62W, TL52W	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUZUKI								
ESCUDO (INCL. HYBRID)	2005-2015	TA74W, TDA4W, TDB4W, TD54W, TD94W	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ESCUDO (INCL. HYBRID)	2015-2024	YD21S, YE21S, YEA1S, YEH1S	*8 DCP-024R/L +Side clip	DCP-016R/L	*8 DCS-G024 +Side clip	*3	*8 DCV-024 +Side clip	*3
ESCUDO 2.4	2015-2017	TDA4W	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ESCUDE 2.4	2015-	TDA4W	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
ESTEEM					DCS-G020	DCS-G018	DCV-020	DCV-018
EVERY	2013-2015	DA64V, DA64W	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
EVERY	2015-2019	DA17V, DA17W	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
EVERY	2019-	DA17V, DA17W	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
EVERY PLUS/ LANDY	1999-2005	DA32W	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
FRONX	2024-	WDB3S WEB3S	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
HUSSLER (INCL. HYBRID)	2014-2015	MR31S, MR41S	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
HUSSLER (INCL. HYBRID)	2015-2019	MR31S, MR41S	DCP-016R/L	DCP-017R/L	DCS-G016	DCS-G017	DCV-016	DCV-017
HUSSLER (INCL. HYBRID)	2015-2019	MR41S	DCP-016R/L	DCP-017R/L	DCS-G016	DCS-G017	DCV-016	DCV-017
HUSSLER (INCL. HYBRID)	2020-	MR52S, MR92S	DCP-016R/L	DCP-017R/L	DCS-G016	DCS-G017	DCV-016	DCV-017
IGNIS (INCL. HYBRID)	2016-	FF21S	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
JIMNY	1995-1998	JA12C, JA12V, JA12W, JA22W	DCP-014R/L	DCP-014R/L	DCS-G014	DCS-G014	DCV-014	DCV-014
JIMNY	1998-2018	JB23W	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
JIMNY	2018-	JB64W	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
JIMNY					DCS-G012	DCS-G012	DCV-012	DCV-012
JIMNY SIERRA	2002-2018	JB43W	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
JIMNY SIERRA	2018-	JB74W	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
JIMNY WIDE	1998-2001	JB33W, JB43W	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
KARIMUN	1998-				DCS-G018	DCS-G018	DCV-018	DCV-018
KATANA					DCS-G012	DCS-G012	DCV-012	DCV-012

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUZUKI								
KEI	1998-2003	HN11S, HN12S, HN21S, HN22S	DCP-019R/L	DCP-016R/L	DCS-G019	DCS-G016	DCV-019	DCV-016
KEI	2003-2006	HN22S	DCP-019R/L	DCP-016R/L	DCS-G019	DCS-G016	DCV-019	DCV-016
KEI	2006-2009	HN22S	DCP-019R/L	DCP-016R/L	DCS-G019	DCS-G016	DCV-019	DCV-016
KIZASHI	2009-	RE91S, RF91S						
LANDY (INCL. HYBRID)	2007-2010	SC25, SNC25	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
LANDY (INCL. HYBRID)	2010-2013	SC26, SNC26	DCP-026R/L	DCP-012R/L	DCS-G026	DCS-G012	DCV-026	DCV-012
LANDY (INCL. HYBRID)	2014-2016	SC26, SNC26, SHC26	DCP-026R/L +Side clip	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
LANDY (INCL. HYBRID)	2016-2022	SC27, SGC27, SGNC27	*7 DCP-024R/L +Side clip	DCP-014R/L +Side clip	*7 DCS-G024 +Side clip	DCS-G014 +Side clip	*7 DCV-024 +Side clip	DCV-014 +Side clip
LANDY (INCL. HYBRID)	2022-	MZRA90C, MZ-RA95C, ZWR90C, ZWR95C	*7:DCP-026R/L	DCP-014R/L	*7 DCS-G026	DCS-G014	*7:DCV-026	DCV-014
LAPIN	2002-2003	HE21S	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
LAPIN	2003-2008	HE21S	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
LAPIN	2008-2015	HE22S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
LAPIN	2015-2022	HE33S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
LAPIN	2022-	HE33S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
MR WAGON	2001-2004	MF21S	DCP-021R/L	DCP-012R/L	DCS-G021	DCS-G012	DCV-021	DCV-012
MR WAGON	2004-2005	MF21S	DCP-021R/L	DCP-012R/L	DCS-G021	DCS-G012	DCV-021	DCV-012
MR WAGON	2006-2010	MF22S	DCP-020R/L	DCP-014R/L	DCS-G020	*1 DCS-G014	DCV-020	*1 DCV-014
MR WAGON	2011-2016	MF33S	DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
PALLET	2008-2010	MK21S	DCP-021R/L	*1 DCP-016R/L	DCS-G021	DCS-G016	DCV-021	DCV-016
PALLET	2010-2013	MK21S	DCP-020R/L	*1 DCP-016R/L	*3	DCS-G016	*3	DCV-016
SIDE KICK	1995-				DCS-G018	DCS-G018	DCV-018	DCV-018

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUZUKI								
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2005-2010	MA34S	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2011-2015	MA15S	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2015-2020	MA26S, MA36S, MA46S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2020-2024	MA27S, MA37S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2025-	MAD47S	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
SPACIA (INCL. HYBRID)	2013-2017	MK32S, MK42S	*1 DCP-020R/L	DCP-017R/L	DCS-G020	DCS-G017	DCV-020	DCV-017
SPACIA (INCL. HYBRID)	2017-2020	MK53S	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
SPACIA (INCL. HYBRID)	2020-2023	MK53S	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
SPACIA (INCL. HYBRID)	2023-	MK54S, MK94S	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
SPACIA BASE	2022-	MK33V	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
SPLASH	2008-2014	XB32S	DCP-022R/L	*8 DCP-016R/L	DCS-G022	*2	DCV-022	*2
SWIFT	2008				DCS-G022	DCS-G019	DCV-022	DCV-019
SWIFT	2009				DCS-G021	DCS-G018	DCV-021	DCV-018
SWIFT	2000-2001				DCS-G020	DCS-G019	DCV-020	DCV-019
SWIFT (INCL. HYBRID)	2017-2023	ZC13S, ZC43S, ZC53S, ZC83S, ZD53S, ZD83S	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
SWIFT (INCL. HYBRID)	2023-	ZCEDs, ZDEDs, ZCDDs, ZDDDs	DCP-020R/L	DCP-019R/L	*1 DCS-G020	*1 DCS-G019	*1 DCV-020	*1 DCV-019
SWIFT SPORTS	2017-	ZC33S	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2000-2003	HT51S	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUZUKI								
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2003-2006	HT51S, HT81S	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2004-2010	ZC11S, ZC21S, ZC31S, ZC71S, ZD11S, ZD21S	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2010-2016	ZC32S, ZC72S, ZD72S	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
SX4	2006-2014	YA11S, YA41S, YB11S, YB41S, YC11S	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
SX4 S CROSS	2015-2020	YA22S, YB22S	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
TWIN	2003-2005	EC22S, EC22S改	DCP-018R/L	DCP-016R/L	DCS-G018	DCS-G016	DCV-018	DCV-016
WAGON R SMILE (INCL. HYBRID)	2021-2024	MX81S, MX91S	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
WAGON R SMILE (INCL. HYBRID)	2024-	MX81S, MX91S	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
WAGON R SOLIO	1999-2000	MA63S	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
WAGON R SOLIO	2000-2005	MA34S, MA64S	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
WAGON R/ WAGON R STINGLEY (INCL. HYBRID)	1999-2003	MC11S, MC12S, MC21S, MC22S	DCP-018R/L	DCP-015R/L	DCS-G018	DCS-G015	DCV-018	DCV-015
WAGON R/ WAGON R STINGLEY (INCL. HYBRID)	2003-2007	MH21S, MH22S	DCP-019R/L	DCP-016R/L	DCS-G019	DCS-G016	DCV-019	DCV-016
WAGON R/ WAGON R STINGLEY (INCL. HYBRID)	2007-2008	MH22S	DCP-019R/L	DCP-016R/L	DCS-G019	DCS-G016	DCV-019	DCV-016
WAGON R/ WAGON R STINGLEY (INCL. HYBRID)	2008-2012	MH23S	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
WAGON R/ WAGON R STINGLEY (INCL. HYBRID)	2012-2017	MH34S, MH44S	DCP-020R/L	DCP-015R/L	DCS-G020	*3	DCV-020	*3

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
SUZUKI								
WAGON R/ WAGON R STINGLEY (INCL. HYBRID)	2017-2022	MH35S, MH55S, MH85S, MH95S	DCP-021R/L	DCP-015R/L	DCS-G021	DCS-G015	DCV-021	DCV-015
WAGON R/ WAGON R STINGLEY (INCL. HYBRID)	2022-	MH55S, MH85S, MH95S	DCP-022R/L	DCP-015R/L	DCS-G022	DCS-G015	DCV-022	DCV-015
XBEE (INCL. HYBRID)	2017-2020	MN71S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
XBEE (INCL. HYBRID)	2020-	MN71S	DCP-018R/L	DCP-018R/L	DCS-G018	DCS-G018	DCV-018	DCV-018
TIMOR								
TIMOR					DCS-G016	DCS-G016	DCV-016	DCV-016
TOYOTA								
86	2012-2021	ZN6	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
86	2021-	ZN8	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
86 (WITH EYESIGHT)	2021-	ZN8	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
ALEX	2001- 2006	NZE121, NZE124, ZZE122, ZZE123, ZZE124	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
ALLION	2001-2007	AZT240, NZT240, ZZT240, ZZT245	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
ALLION	2007-2021	NZT260, ZRT260, ZRT261, ZRT265	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
ALPHARD (INCL. HYBRID)	2002- 2008	ANH10W, ANH15W, ATH10W, MNH10W, MNH15W	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
ALPHARD (INCL. HYBRID)	2008- 2014	ANH20W, ANH25W, ATH20W, GGH20W, GGH25W	*2 750mm	DCP-014R/L	*2 750mm	DCS-G014	*2 750mm	DCV-014
ALPHARD (INCL. HYBRID)	2015-2017	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
ALPHARD (INCL. HYBRID)	2018-2023	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	*2 750mm	*3	*2 750mm	*3	*2 750mm	*3

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
ALPHARD (INCL. HYBRID)	2023-	AAHH40W, AAHH45W, AGH40W, AGH45W, AAHP45W	*2 750mm	DCP-014R/L	*2 750mm	DCS-G014	*2 750mm	DCV-014
ALTEZA	1998-2005	SXE10, GXE10	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
ALTEZA JETA	2001-2005	GXE10W, GXE15W, JCE10W, JCE15W	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
AQUA	2011-2021	NHP10	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
AQUA	2021-	MXP10, MXP11, MXP15, MXP16	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
ARIST	1997-2004	JZS160, JZS161	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
AURIS (INCL. HYBRID)	2006-2012	NZE151H, NZE154H, ZRE152H, ZRE154H	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
AURIS (INCL. HYBRID)	2012-2018	ZRE186H, ZWE186H, NZE181H, NZE184H, NRE185H	*3	DCP-014R/L	*3	DCS-G014	*3	DCV-014
AVALONE	1995-2000	MCX10	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
AVANZA	2003-2004				DCS-G020	DCS-G016	DCV-020	DCV-016
AVANZA	2005-				DCS-G020	DCS-G016	DCV-020	DCV-016
AVENSIS SEDAN	2003-2008	AZT250, AZT251, AZT255	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
AVENSIS WAGON	2003-2008	AZT250W, AZT251W, AZT255W	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
AVENSIS WAGON	2011-2018	ZRT272W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
BB (INCL. OPEN DECK)	2000-2005	NCP30, NCP31, NCP34, NCP35	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
BB (INCL. OPEN DECK)	2005-2016	QNC20, QNC21, QNC25	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
BELTA	2005-2012	KSP92, SCP92, NCP96	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
BLADE	2006-2012	AZE154H, AZE156H, GRE156H	*3	DCP-016R/L	*3	DCS-G016	*3	DCV-016
BZ4X	2022-	XEAM10, YEAM15	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
CALDINA	1997-2002	AT211G, CT216G, ST210G, ST215G, ST215W	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
CALDINA	2002-2007	AZT241W, AZT246W, ST246W, ZZT241W	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
CAMI	1999-2000	J100E	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
CAMI	2000-2006	J102E, J122E	DCP-022R/L	DCP-012R/L	DCS-G022	DCS-G012	DCV-022	DCV-012
CAMRY (INCL. HYBRID)	1996-2001	CV40, CV43, SV40, SV41, SV42, SV43	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CAMRY (INCL. HYBRID)	2001-2005	ACV30, ACV35	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
CAMRY (INCL. HYBRID)	2006-2011	ACV40, ACV45	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
CAMRY (INCL. HYBRID)	2011-2017	AVV50	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
CAMRY (INCL. HYBRID)	2017-2023	AXVH70, AXVH75	DCP-026R/L	DCP-020R/L	DCS-G026	DCS-G020	DCV-026	DCV-020
CAMRY GRACIA WAGON	1996-2001	MCV21W, MCV25W, SXV20W, SXV25W	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CARINA	1996-2001	AT210, AT211, AT212, CT210, CT211, CT215, CT216	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
CAVARIER COUP/ SEDAN	1996-2000	TJG00	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
CELICA	1999-2006	ZZT230, ZZT231	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
CELSIOR	1994-2000	UCF20, UCF21	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
CELSIOR	2000-2006	UCF30, UCF31	*2	DCP-016R/L	*2	DCS-G016	*2	DCV-016
CENTURY	1997-2017	GZG50	DCP-022R/L	DCP-021R/L	DCS-G022	DCS-G021	DCV-022	DCV-021
CENTURY HYBRID SEDAN	2018-	UWG60	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
CENTURY HYBRID SUV	2023-	GRG75	DCP-026R/L	DCP-020R/L	DCS-G026	DCS-G020	DCV-026	DCV-020

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
CHASER	1996-2001	GX100, GX105, JZX100, JZX101, JZX105, LX100, SX100	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
C-HR (INCL. HYBRID)	2016-2018	ZYX10, NGX50	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
C-HR (INCL. HYBRID)	2018-2023	NGX10, NGX50, ZYX10, ZYX11	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
COASTER	1993-2004	BB4#, HZB4#, HDB5#, HZB5#	DCP-021R/L	DCP-021R/L	DCS-G021	DCS-G021	DCV-021	DCV-021
COASTER	2004-2016	XZB40, XZB46V, XZB50, XZB51, BZB40, BZB50	DCP-021R/L	DCP-021R/L	DCS-G021	DCS-G021	DCV-021	DCV-021
COASTER	2017-	XZB60, XZB70	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
COMMUTER					DCS-G022	DCS-G020	DCV-022	DCV-020
COPEN GR SPORT	2019-	LA400A	DCP-017R/L	DCP-018R/L	DCS-G017	DCS-G018	DCV-017	DCV-018
COROLLA	1994-1999				DCS-G020	DCS-G018	DCV-020	DCV-018
COROLLA	2000				DCS-G020	DCS-G018	DCV-020	DCV-018
COROLLA (INCL. HYBRID)	2019-	MZEA17, NRE210, ZRE212, ZWE211, ZWE214, ZWE215, ZWE219	*7 DCP-026R/L	DCP-014R/L	*7 DCS-G026	DCS-G014 +Side clip	*7 DCV-026	DCV-014 +Side clip
COROLLA AE'82	1982-				DCS-G020	DCS-G018	DCV-018	DCV-017
COROLLA AE'92					DCS-G020	DCS-G018	DCV-020	DCV-018
COROLLA ALTIS	1993-2001				DCS-G020	DCS-G018	DCV-020	DCV-018
COROLLA ALTIS	2002-2008				DCS-G024	DCS-G018	DCV-024	DCV-018
COROLLA ALTIS	2006				DCS-G026	DCS-G016	DCV-026	DCV-016
COROLLA ALTIS	2009-				DCS-G026	DCS-G016	DCV-026	DCV-016
COROLLA AXIO (INCL. HYBRID)	2006-2012	NZE141, NZE144, ZRE142, ZRE144	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
COROLLA AXIO (INCL. HYBRID)	2012-2025	NKE165, NRE160, NRE161, NZE161, NZE164	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
COROLLA CROSS (INCL. HYBRID)	2021-	ZSG10, ZVG11, ZVG15	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
COROLLA FIELDER (INCL. HYBRID)	2000-2006	NZE121G, NZE124G, ZZE122G, ZZE123G, ZZE124G, CE121G	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
COROLLA FIELDER (INCL. HYBRID)	2006-2012	NZE141G, NZE144G, ZRE142G, ZRE144G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
COROLLA FIELDER (INCL. HYBRID)	2012-2025	NKE165G, NRE161G, NZE161G, NZE164G, ZRE162G	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
COROLLA LEVIN/SPRINTER TRUENO	1997-2000	AE110, AE111	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
COROLLA LUMION	2007-2015	NZE151N, ZRE152N, ZRE154N	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
COROLLA RUNX	2001-2006	NZE121, NZE124, ZZE122, ZZE123, ZZE124	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
COROLLA SPACIO	1997-2001	AE111N, AE115N	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
COROLLA SPACIO	2001-2007	NZE121N, ZZE122N, ZZE124N	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
COROLLA SPORTS (INCL. HYBRID)	2018-	NRE210H, NRE214H, ZWE211H, ZWE213H, ZWE219H, MZEA12H	*7 DCP-026R/L	DCP-014R/L	*7 DCS-G026	DCS-G014 +Side clip	*7 DCV-026	DCV-014 +Side clip
COROLLA/SPRINTER	1997-2000	AE110, AE111, AE114, CE110, CE113, CE114, CE116, EE111	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
COROLLA/SPRINTER	2000-2006	NZE120, NZE121, NZE124, ZZE122, ZZE124, CE121	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
COROLLA TOURING (INCL. HYBRID)	2019-	MZEA12W, MZEA17W, NRE210W, ZRE212W, ZWE211W, ZWE214W, ZWE215W, ZWE219W	*7 DCP-026R/L	DCP-014R/L	*7 DCS-G026	DCS-G014+ Side clip	*7 DCV-026	DCV-014 +Side clip
COROLLA WAGON	1997-2000	AE100G, AE101G, AE104G, CE101G, CE102G, EE104G	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
CORONA ABSOLUTE	1992				DCS-G020	DCS-G018	DCV-020	DCV-018
CORONA PREMIO	1996-2001	AT210, AT211, CT211, CT216, ST210, ST215	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
CORONA 1.6	1992				DCS-G020	DCS-G018	DCV-020	DCV-018
CORONA 2.0	1992				DCS-G021	DCS-G018	DCV-021	DCV-018
CRESSIDA	1985-1988				DCS-G019	DCS-G018	DCV-019	DCV-018
CRESSIDA	1989-1992				DCS-G020	DCS-G018	DCV-020	DCV-018
CRESTA	1996-2001	GX100, GX105, JZV100, JZX101, JZX105, LX100	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
CROWN	1995				DCS-G021	DCS-G018	DCV-021	DCV-018
CROWN (ROYAL/ATHLETE/HYBRID)	1999-2001	GS171, JZS171, JZS173, JZS175, JZS179	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
CROWN (ROYAL/ATHLETE/HYBRID)	2001-2003	GS171, JKS175, JZS171, JZS173, JZS175, JZS179	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
CROWN (ROYAL/ATHLETE/HYBRID)	2003-2008	GRS180, GRS181, GRS182, GRS183, GRS184	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
CROWN (ROYAL/ATHLETE/HYBRID)	2008-2012	GRS200, GRS201, GRS202, GRS203, GRS204, GWS204	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
CROWN (ROYAL/ATHLETE/HYBRID)	2012-2018	GRS210, GRS211, GRS214, AWS210, AWS211, ARS210	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
CROWN (ROYAL/ATHLETE/HYBRID)	2018-2022	ARS220, AZSH20, AZSH21, GWS224	*3	*3	*3	*3	*3	*3
CROWN COMFORT	1995-2001	GXS10, YXS10	DCP-020R/L +Screw clip	DCP-020R/L +Screw clip	DCS-G020 +Screw clip	DCS-G020 +Screw clip	DCV-020 +Screw clip	DCV-020 +Screw clip
CROWN COMFORT	2001-2018	GXS10, YXS10, TSS10	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
CROWN CROSSOVER	2022-	AZSH35, TZSH35	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
CROWN ESTATE	2001-2007	GS171W, JZS171W, JZS173W, JZS175W	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
CROWN MAJESTA (INCL. HYBRID)	1999-2004	JZS177, UZS171, UZS173, UZS175	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
CROWN MAJESTA (INCL. HYBRID)	2004-2009	UZS186, UZS187	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
CROWN MAJESTA (INCL. HYBRID)	2009-2013	URS206, UZS207	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
CROWN MAJESTA (INCL. HYBRID)	2013-2018	AWS215, GWS214	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
CROWN SEDAN	1995-2001	JZS, GS	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
CROWN SEDAN	2023-	AZSH32 KZSM30	*3	*3	*3	*3	*3	*3
CROWN SPORTS	2023-	AZSH36W AZSH37W	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
DUET	1998-2004	M100A, M101A, M110A, M111A	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
DYNA	2002				DCS-G017	DCS-G017	DCV-017	DCV-017
DYNA/TOYOACE	1999-2001	N/A	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
DYNA/TOYOACE	2001-2011	TRY2##, KDY2##, RZY2##, RZU3##, XZU3##, XZU4##, XZU5##, TRU3##, TRU5##, BZU3##	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
DYNA/TOYOACE (STANDARD)	2011-	BZU6#, TRC6#, TRU6#, XK6#, XKU6#, XZC6#, XZU6#, KDY2#, TRY2#	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
DYNA/TOYOACE (WIDE - WITH ADAS)	2017-	XKU7#, XZC7#, XZU7#	DCP-022R/L	DCP-022R/L	DCS-G022	DCS-G022	DCV-022	DCV-022
DYNA/TOYOACE (WIDE - WITHOUT ADAS)	2011-	XKU7#, XZC7#, XZU7#	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
ESQUIRE (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZWR80G	*2 700mm	DCP-014R/L	*2 700mm	DCS-G014	*2 700mm	DCV-014
ESTIMA (INCL. HYBRID)	2000-2005	ACR30W, ACR40W, AHR10W, MCR30W, MCR40W	*2 700mm	DCP-018R/L	*2 700mm	DCS-G018	*2 700mm	DCV-018

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
ESTIMA (INCL. HYBRID)	2006-2019	ACR50W, ACR55W, AHR20W, GSR50W, GSR55W	*2 700mm	DCP-016R/L	*2 700mm	DCS-G016	*2 700mm	DCV-016
FJ CRUISER	2010-2018	GSJ15W	DCP-016R/L	DCP-014R/L x 2	*2 700mm	DCS-G014 x 2	DCV-016	DCV-014 x 2
FORTUNER	2004-				*2 700mm	DCS-G019	DCV-021	DCV-019
FORTUNER 2.5 DIESEL	2005					DCS-G021	DCS-G019	DCV-021
FORTUNER 2.7	2005					DCS-G020	DCS-G018	DCV-020
FUN CARGO	1999-2002	NCP20, NCP21, NCP25	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
FUN CARGO	2002-2005	NCP20, NCP21, NCP25	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
GAIA	1998-2002	ACM10G, CXM10G, SXM10G, SXM15G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
GAIA	2002-2004	ACM10G, ACM15G, CXM10G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
GRANACE	2019-2024	GDH303W	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
GRAND HIACE	1999-2002	KCH10W, KCH16W, VCH10W, VCH16W	DCP-024R/L	DCP-021R/L	DCS-G024	DCS-G021	DCV-024	DCV-021
GRANVIA	1998-2002	KCH10W, KCH16W, VCH10W, VCH16W	DCP-024R/L	DCP-021R/L	DCS-G024	DCS-G021	DCV-024	DCV-021
HARRIER (INCL. HYBRID)	1997-2003	ACU10W, ACU15W, MCU10W, MCU15W, SXU10W, SXU15W	DCP-024R/L	DCP-021R/L	DCS-G024	DCS-G021	DCV-024	DCV-021
HARRIER (INCL. HYBRID)	2003-2013	ACU30W, ACU35W, GSU30W, GSU31W, GSU35W, GSU36W, MCU30W, MCU31W, MCU35W, MCU36W, MHU38W	DCP-026R/L	DCP-022R/L	DCS-G026	DCS-G022	DCV-026	DCV-022
HARRIER (INCL. HYBRID)	2013-2020	AVU65W, ZSU60W, ZSU65W, ASU60W, ASU65W	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
HARRIER (INCL. HYBRID)	2020-	AXUH80, AXUH85, AXUP85, MXUA80, MXUA85,	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
HIACE	1995-				DCS-G018	DCS-G018	DCV-018	DCV-018

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

*1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 *2 No applicable item is available
 *3 No applicable item is available because of contact with the car body or wiper arm
 *4 Please take off the plastic part put on the wiper arm
 *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 *7 Shorter than OEM wiper
 *8 Possible to make contact with the mole when the wiper is operated at high speed
 *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
HIACE VAN/ WAGON	1996-2004	KZH1##, RZH1##, TRH1##	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
HIACE VAN/ WAGON (STANDARD)	2004-	GDH20##, KDH20##, TRH20##	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
HIACE VAN/ WAGON (WIDE)	2004-	GDH21##, GDH22##, KDH21##, KDH22##, TRH21##, TRH22##	DCP-022R/L	DCP-022R/L	DCS-G022	DCS-G022	DCV-022	DCV-022
HIACE LEGIAS	1998-2002	KCH40G, KCH40W, KCH46G, KCH46W, RCH41W, RCH47W	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
HIACE TRUCK	1995-2001	LY1##, YY1##	DCP-017R/L	DCP-017R/L	DCS-G017	DCS-G017	DCV-017	DCV-017
HILUX	2004				DCS-G017	DCS-G017	DCV-017	DCV-017
HILUX	2005				DCS-G021	DCS-G019	DCV-021	DCV-019
HILUX	2017-	GUN125	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
HILUX PICKUP	1997-2004	LN165, LN165H, LN167, LN170H, LN172H, RZN147, RZN152H, RZN167, RZN169H, RZN174H	DCP-018R/L	DCP-019R/L	DCS-G018	DCS-G019	DCV-018	DCV-019
HILUX REVO	2015-				DCS-G022	DCS-G016	DCV-022	DCV-016
HILUX SURF	1995-2002	KDN185W, KZN185G, KZN185W, RZN180W, RZN185W, VZN185W	DCP-018R/L	DCP-019R/L	DCS-G018	DCS-G019	DCV-018	DCV-019
HILUX SURF	2002- 2009	GRN215W, KD- N215W, RZN210W, RZN215W, TRN210W, TRN215W, VZN210W, VZN215W	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
HILUX VIGO	2004-				DCS-G021	DCS-G019	DCV-021	DCV-019
INNOVA	2004-2015		DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
INNOVA	2016-		DCP-026	DCP-016	DCS-G026	DCS-G016	DCV-026	DCV-016
IPSUM	1998-2001	SXM10G, SXM15G, CXM10G	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
IPSUM	2001-2009	ACM21W, ACM26W	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
IQ	2008-2016	KGJ10, NGJ10	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
ISIS	2004-2017	ANM10G, ANM15G, ANM10W, ANM15W, ZGM10G, ZGM11G, ZGM15G, ZGM10W, ZGM11W, ZGM15W, ZNM10G, ZNM10W	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
IST	2002-2007	NCP60, NCP61, NCP65	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
IST	2007-2016	NCP110, NCP115, ZSP110	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
JPN TAXI	2017-	NTP10	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
KIJANG EFI	2000-2003				DCS-G018	DCS-G018	DCV-018	DCV-018
KIJANG KAPSUL	1997-1999				DCS-G018	DCS-G018	DCV-018	DCV-018
KIJANG KOTAK	1986-1995				DCS-G016	DCS-G016	DCV-016	DCV-016
KLUGAR	2000-2007	ACU20W, ACU25W, MCU20W, MCU25W, MHU28W	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
LAND CRUISER (70)	1994-2004	J70, J71, J73, J74, J76, J77	DCP-017R/L	DCP-016 or 019R/L	DCS-G017	DCS-G016 or 019	DCV-017	DCV-016 or 019
LAND CRUISER	1993-1997				DCS-G018	DCS-G018	DCV-018	DCV-018
LAND CRUISER	1998-1999				DCS-G020	DCS-G020	DCV-020	DCV-020
LAND CRUISER	2007-				DCS-G024	DCS-G019	DCV-024	DCV-019
LAND CRUISER (100)	1999-2007	HDJ101K, UZJ100W	DCP-024R/L	DCP-022R/L	DCS-G024	DCS-G022	DCV-024	DCV-022
LAND CRUISER (200)	2007-2021	UZJ200W, UR-J202W	DCP-024R/L	DCP-022R/L	DCS-G024	DCS-G022	DCV-024	DCV-022
LAND CRUISER (250)	2024-	GDJ250W, TRJ250W	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
LAND CRUISER (300)	2021-	FJA300W, VJA300W	DCP-024R/L	DCP-022R/L	DCS-G025 +Side clip	DCS-G022	DCV-024 +Side clip	DCV-022

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
LAND CRUISER PRADO (90)	1996-2002	KDJ90W, KDJ95W, KZJ90W, KZJ95W, RZJ90W, RZJ95W, VZJ90W, VZJ95W	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
LAND CRUISER PRADO (120)	2002-2009	GRJ120W, GRJ121W, KDJ120W, KDJ121W, KDJ125W, TRJ120W, TRJ125W, VZJ120W, VZJ121W, VZJ125W	DCP-022R/L	DCP-021R/L	DCS-G022	DCS-G021	DCV-022	DCV-021
LAND CRUISER PRADO (150)	2009-	GDJ150W, GD-J151W, GRJ150W, GRJ151W, TRJ150W	DCP-026R/L	DCP-020R/L	DCS-G026	DCS-G020	DCV-026	DCV-020
LEGIUS ACE (STANDARD)	2004-2020	GDH20##, KDH20##, TRH20##	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
LEGIUS ACE (WIDE)	2004-2020	GDH21##, GDH22##, KDH21##, KDH22##, TRH21##, TRH22##	DCP-022R/L	DCP-022R/L	DCS-G022	DCS-G022	DCV-022	DCV-022
MARK X	2004-2009	GRX120, GRX121, GRX125	DCP-022R/L	DCP-020R/L	DCS-G022	DCS-G020	DCV-022	DCV-020
MARK X	2009-2012	GRX130, GRX133, GRX135	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
MARK X	2012-2019	GRX130, GRX133, GRX135	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
MARK X GIO	2007-2013	ANA10, ANA15, GGA10	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
MARK II	1996-2000	GX100, GX105, JZX100, JZX101, JZX105, LX100	DCP-022R/L	DCP-019R/L	DCS-G022	DCS-G019	DCV-022	DCV-019
MARK II	2000-2004	GX110, GX115, JZX110, JZX115	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
MARK II BRIT	2002-2007	GX110W, GX115W, JZX110W, JZX115W	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
MARK II WAGON QUALIS	1997-2002	MCV20W, MCV21W, MCV25W, SXV20W, SXV25W	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
MEGA CRUISER	1996-2002	BXD20V	DCP-016R/L x 2	No DCP(G33)	DCS-G016 x 2	DCS-G013	DCV-016 x 2	DCV-013

- Notes:**
- Possible to make contact with the mole when the wiper is operated at high speed
 - No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - Please take off the plastic part put on the wiper arm
 - Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
MIRAI	2020-	JPD20	*3	*3	*3	*3	*3	*3
MR-S	1999-2007	ZZW30	DCP-020R/L	DCP-019R/L	DCS-G020	DCS-G019	DCV-020	DCV-019
NADIA	1998-2003	ACN10, ACN10H, ACN15, ACN15H, SXN10, SXN10H, SXN15, SXN15H	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
NEW FORTUNER					DCS-G022	DCS-G016	DCV-022	DCV-016
NEW VIOS	2007				DCS-G024	DCS-G014	DCV-024	DCV-014
NOAH (INCL. HYBRID)	2001-2007	AZR60G, AZR65G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
NOAH (INCL. HYBRID)	2007-2013	ZRR70G, ZRR75G, ZRR70W, ZRR75W	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
NOAH (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZRR80W, ZRR85W, ZWR80G	*2 700mm	DCP-014R/L	*2 700mm	DCS-G014	*2 700mm	DCV-014
NOAH (INCL. HYBRID)	2022-	ZWR90W, ZWR92W, ZWR95W, MZRA90W, MZRA92W, MZ- RA95W, MZRA97W	*2 700mm	DCP-014R/L	*2 700mm	DCS-G014	*2 700mm	DCV-014
OPA	2000- 2005	ACT10, ZCT10, ZCT15	DCP-026R/L	DCP-017R/L	DCS-G026	DCS-G017	DCV-026	DCV-017
PASSO	2004- 2010	KGC10, KGC15, QNC10	DCP-020R/L	DCP-016R/L	DCS-G020	DCS-G016	DCV-020	DCV-016
PASSO	2010-2016	NGC30, KGC30, KGC35	DCP-021R/L	DCP-017R/L	DCS-G021	DCS-G017	DCV-021	DCV-017
PASSO	2016-2018	M700A, M710A	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
PASSO	2018-2023	M700A, M710A	DCP-022R/L	DCP-016R/L	DCS-G022	DCS-G016	DCV-022	DCV-016
PASSO SETTE	2008-2012	M502E, M512E	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
PIXIS EPOCH	2012-2017	LA300A, LA310A	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
PIXIS EPOCH	2017-	LA350A, LA360A	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
PIXIS JOY	2016-2017	LA250A, LA260A	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
PIXIS JOY	2017-2023	LA250A, LA260A	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
PIXIS SPACE	2011-2017	L575A, L585A	DCP-018R/L	*1 DCP- 018R/L	DCS-G018	*1 DCS-G018	DCV-018	*1 DCV-018
PIXIS TRUCK	2011-2014	S201U, S211U	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
PIXIS TRUCK	2014-2018	S500U, S510U	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
PIXIS TRUCK	2018-	S500U, S510U	DCP-016R/L	DCP-016R/L	DCS-G016	DCS-G016	DCV-016	DCV-016
PIXIS VAN	2011-2017	S321M, S331M	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
PIXIS VAN	2017-2021	S321M, S331M	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
PIXIS VAN	2021-	S700M, S710M	DCP-020R/L	DCP-014R/L	DCS-G020	DCS-G014	DCV-020	DCV-014
PIXIX MEGA	2015-2017	LA700A, LA710A	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
PIXIX MEGA	2018-2022	LA700A, LA710A	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
PLATZ	1999-2005	SCP11, NCP12, NCP16	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
PORTE	2004-2012	NNP10, NNP11, NNP15	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
PORTE	2012-2020	NCP141, NCP145, NSP140, NSP141	DCP-026R/L	DCP-014R/L	*3	DCS-G014	*3	DCV-014
PRASSO	1999-2005	SCP11, NCP12, NCP16	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	
PREMIO	2001-2007	AZT240, NZT240, ZZT240, ZZT245	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	
PREMIO	2007-2021	NZT260, ZRT260, ZRT261, ZRT265	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	
PREVIS	2001-2007	JCG10, JCG11, JCG15	DCP-024R/L	DCP-018R/L	DCS-G024	DCS-G018	DCV-024	DCV-018
PRIUS	1997-2003	NHW10, NHW11	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
PRIUS	2003-2009	NHW20	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
PRIUS	2009-2015	ZVW30	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
PRIUS	2015-2017	ZVW50, ZVW51, ZVW55	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
PRIUS	2017-2022	ZVW50, ZVW51, ZVW55	*7 DCP-026R/L	DCP-016R/L	*7 DCS-G026	DCS-G016	*7 DCV-026	DCV-016
PRIUS	2023-	MXWH60, MXWH65, ZVW60, ZVW65, MXWH61	*2	DCP-014R/L	*2	DCS-G014	*2	DCV-014
PRIUS PHV	2012-2016	ZVW35	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
PRIUS PHV	2017-2019	ZVW52	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
PRIUS PHV	2017-2019	ZVW52	*7 DCP-026R/L	DCP-016R/L	*7 DCS-G026	DCS-G016	*7 DCV-026	DCV-016

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
PRIUS PHV	2017-2017	ZVW52	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
PRIUS PHV	2019-2022	ZVW52	*7 DCP-026R/L	DCP-016R/L	*7 DCS-G026	DCS-G016	*7 DCV-026	DCV-016
PRIUS α	2011-2021	ZVW40W, ZVW41W	*2	DCP-014R/L	*2	DCS-G014	*2	DCV-014
PROBOX (INCL. HYBRID)	2002-2014	NCP50V, NCP51V, NCP52V, NCP55V, NCP58G, NCP59G, NLP51V	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
PROBOX (INCL. HYBRID)	2014-	NSP160V, NCP160V, NCP165V, NHP160V	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
PROGRE	1998-2007	JCG10, JCG11, JCG15	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
PRONARD	2000-2003	MCX20	*3	DCP-016R/L	*3	DCS-G016	*3	DCV-016
RACTIS	2005-2010	NCP100, NCP105, SCP100	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
RACTIS	2010-2016	NCP120, NCP122, NCP125, NSP120, NSP122	*2 700mm	-	*2 700mm	-	*2 700mm	-
RAIZE	2019-	A200A, A201A, A202A, A210A	DCP-021R/L	*1 DCP-015R/L	DCS-G021+Side clip	DCS-G015+Side clip	DCV-021+Side clip	DCV-015+Side clip
RAUM	1997-2003	EXZ10, EXZ15	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
RAUM	2003-2011	NCZ20, NCZ25	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
RAV4 (INCL. HYBRID)	1996-2000	SXA10C, SXA10G, SXA10W, SXA11G, SXA11W, SXA15G, SXA16G	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
RAV4 (INCL. HYBRID)	2000-2005	ACA20W, ACA21W, ZCA25W, ZCA26W	DCP-024R/L	DCP-019R/L	DCS-G024	DCS-G019	DCV-024	DCV-019
RAV4 (INCL. HYBRID)	2005-2016	ACA31W, ACA36W	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
RAV4 (INCL. HYBRID)	2019-	AXAH52, AXAH54, AXAP54, MXAA52, MXAA54	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
RINO 115PS					DCS-G017	DCS-G017	DCV-017	DCV-017
ROOMY (INCL. CUSTOM)	2016-2018	M900A, M910A	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
ROOMY (INCL. CUSTOM)	2018-	M900A, M910A	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
 - *2 No applicable item is available
 - *3 No applicable item is available because of contact with the car body or wiper arm
 - *4 Please take off the plastic part put on the wiper arm
 - *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
 - *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
 - *7 Shorter than OEM wiper
 - *8 Possible to make contact with the mole when the wiper is operated at high speed
 - *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
RUSH	2006-2016	J200E, J210E	DCP-021R/L	DCP-018R/L	DCS-G021	DCS-G018	DCV-021	DCV-018
SAI	2009-2017	AZK10	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
SAI (WITH ADAS)	2009-2017	AZK10	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
SIENTA (INCL. HYBRID)	2003-2015	NCP81G, NCP85G	DCP-022R/L	DCP-017R/L	DCS-G022	DCS-G017	DCV-022	DCV-017
SIENTA (INCL. HYBRID)	2015-2018	NCP175G, NHP170G, NSP170G, NSP172G	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
SIENTA (INCL. HYBRID)	2018-2022	NCP175G, NHP170G, NSP170G, NSP172G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
SIENTA (INCL. HYBRID)	2022-	MXPC10G, MXPL10G, MXPL15G, MXPC12G, MXPL12G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
SOARER	1991-2001	JZZ30, JZZ31, UZZ31, UZZ32	DCP-021R/L	*2	DCS-G021	*2	DCV-021	*2
SOARER	2001-2005	UZZ40	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
SOLUNA	1997-2003				DCS-G018	DCS-G018	DCV-018	DCV-018
SOLUNA	2002				DCS-G020	DCS-G018	DCV-020	DCV-018
SOLUNA VIOS	2003-2008				DCS-G021	DCS-G014	DCV-021	DCV-014
SOLUNA VIOS	2008-				DCS-G024	DCS-G014	DCV-024	DCV-014
SPADE	2012-2020	NCP141, NCP145, NSP140, NSP141	DCP-026R/L	DCP-014R/L	*3	DCS-G014	*3	DCV-014
SPARKY	2000-2003	S221E, S231E	DCP-019R/L	DCP-015R/L	DCS-G019	DCS-G015	DCV-019	DCV-015
SPORT CRUISER					DCS-G017	DCS-G017	DCV-017	DCV-017
SPORT RAIDER					DCS-G017	DCS-G017	DCV-017	DCV-017
SPRINTER CARIB	1997-2002	AE111G, AE114G, AE115G	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
STARLET	1990				DCS-G018	DCS-G016	DCV-018	DCV-016
STARLET	1991				DCS-G020	DCS-G017	DCV-020	DCV-017
SUCCEED (INCL. HYBRID)	2002-2014	NCP58G, NCP59G, NCP51V, NCP55V, NLP51V	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018

- Notes:**
- * Possible to make contact with the mole when the wiper is operated at high speed
 - * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
 - * Please take off the plastic part put on the wiper arm
 - * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
SUCCEED (INCL. HYBRID)	2014-2020	NCP160V, NCP165V, NHP160V	DCP-020R/L	DCP-018R/L	DCS-G020	DCS-G018	DCV-020	DCV-018
SUPRA	1993-2002	JZA80	DCP-021R/L	DCP-020R/L	DCS-G021	DCS-G020	DCV-021	DCV-020
SUPRA	2019-2025	DB22, DB42, DB82	*2	*2	*2	*2	*2	*2
TANK (INCL. CUSTOM)	2016-2018	M900A, M910A	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
TANK (INCL. CUSTOM)	2018-2020	M900A, M910A	DCP-021R/L	DCP-019R/L	DCS-G021	DCS-G019	DCV-021	DCV-019
TOURING HIACE	1999-2002	KCH40W, KCH46W, RCH41W, RCH47W	DCP-026R/L	DCP-018R/L	DCS-G026	DCS-G018	DCV-026	DCV-018
TOWNACE/ LITEACE TRUCK	1999-2007	KM, CM7#, 8#	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
TOWNACE/ LITEACE VAN	1998-2001	KR4#V, CR4#V, CR5#V	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
TOWNACE/ LITEACE VAN/ TRUCK	2008-2009	S402M, S412M, S402U, S412U	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
TOWNACE/ LITEACE VAN/ TRUCK	2009-2020	S402M, S412M, S402U, S412U	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
TOWNACE NOAH/LITEACE NOAH	1998-2001	CR40G, CR50G, SR40G, SR50G	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
TOWNACE TRUCK	2020-	S403U, S413U	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
TOWNACE VAN	2020-	S403M, S413M	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
VANGUARD	2007-2013	ACA33W, ACA38W, GSA33W	DCP-024R/L	DCP-017R/L	DCS-G024	DCS-G017	DCV-024	DCV-017
VELFIRE (INCL. HYBRID)	2008-2014	ANH20W, AN-H25W, ATH20W, GGH20W, GGH25W	*2 750mm	DCP-014R/L	*2 750mm	DCS-G014	*2 750mm	DCV-014
VELFIRE (INCL. HYBRID)	2015-2017	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect	*2 Unique connect
VELFIRE (INCL. HYBRID)	2018-2023	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	*2 750mm	*3	*2 750mm	*3	*2 750mm	*3

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
VELFIRE (INCL. HYBRID)	2023-	AAHH40W, AAH-H45W, TAHA40W, TAHA45W, AAHP45W	*2 750mm	DCP-014R/L	*2 750mm	DCS-G014	*2 750mm	DCV-014
VEROSSA	2001-2004	GX110, GX115, JZX110	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
VIOS	2003				DCS-G020	DCS-G014	DCV-020	DCV-014
VISTA	1998-2003	AZV50, AZV55, SV50, SV55, ZZV50	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
VISTA ALDEO	1998-2003	AZV50G, AZV55G, SV50G, SV55G, ZZV50G	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
VITZ (INCL. HYBRID)	1999-2005	NCP10, NCP13, NCP15, SCP10, SCP13	DCP-021R/L	DCP-014R/L	DCS-G021	DCS-G014	DCV-021	DCV-014
VITZ (INCL. HYBRID)	2005-2010	KSP90, NCP91, NCP95, SCP90	DCP-024R/L	DCP-014R/L	DCS-G024	DCS-G014	DCV-024	DCV-014
VITZ (INCL. HYBRID)	2010-2020	KSP130, NCP131, NHP130, NSP130, NSP135	*2 700mm	-	*2 700mm	-	*2 700mm	-
VOLTZ	2002-2004	ZZE136, ZZE137, ZZE138	DCP-021R/L	DCP-017R/L	DCS-G021	DCS-G017	DCV-021	DCV-017
VOXY (INCL. HYBRID)	2001-2007	AZR60G, AZR65G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
VOXY (INCL. HYBRID)	2007-2013	ZRR70G, ZRR75G, ZRR70W, ZRR75W	DCP-026R/L	DCP-016R/L	DCS-G026	DCS-G016	DCV-026	DCV-016
VOXY (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZRR80W, ZRR85W, ZWR80G	*2 700mm	DCP-014R/L	*2 700mm	DCS-G014	*2 700mm	DCV-014
VOXY (INCL. HYBRID)	2022-	ZWR90W, ZWR92W, ZWR95W, MZRA90W, MZRA92W, MZRA95W	*2 700mm	DCP-014R/L	*2 700mm	DCS-G014	*2 700mm	DCV-014
WILL CYPHA	2002-2005	NCP70, NCP75	DCP-022R/L	DCP-014R/L	DCS-G022	DCS-G014	DCV-022	DCV-014
WILL VI	2000-2001	NCP19	DCP-019R/L	DCP-018R/L	DCS-G019	DCS-G018	DCV-019	DCV-018
WILL VS	2001-2004	NZE127, ZZE127, ZZE128, ZZE129	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016

Notes:

- * Possible to make contact with the mole when the wiper is operated at high speed
- * No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- * Please take off the plastic part put on the wiper arm
- * Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
TOYOTA								
WINDOM	1996-2001	MCV20, MCV21	DCP-022R/L	DCP-018R/L	DCS-G022	DCS-G018	DCV-022	DCV-018
WINDOM	2001-2006	MCV30	DCP-024R/L	DCP-020R/L	DCS-G024	DCS-G020	DCV-024	DCV-020
WISH	2003-2005	ANE10G, ANE11W, ZNE10G, ZNE14G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
WISH	2005-2009	ANE10G, ANE11W, ZNE10G, ZNE14G	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
WISH	2009-2017	ZGE20G, ZGE21G, ZGE25G, ZGE20W, ZGE21W, ZGE22W, ZGE25W	DCP-026R/L	DCP-014R/L	DCS-G026	DCS-G014	DCV-026	DCV-014
YARIS	2006-				DCS-G024	DCS-G014	DCV-024	DCV-014
YARIS	2007-2008				DCS-G024	DCS-G014	DCV-024	DCV-014
YARIS	2009				DCS-G026	DCS-G014	DCV-026	DCV-014
YARIS	2014-				DCS-G024	DCS-G014	DCV-024	DCV-014
YARIS (INCL. HYBRID)	2020-	KSP210, MXPA10, MXPA15, MXP10, MXP15	DCP-024R/L	DCP-016R/L	DCS-G024	DCS-G016	DCV-024	DCV-016
YARIS (INCL. HYBRID)	2020-	GXPA16, MXPA12	DCP-024R/L	DCP-016R/L	*3	DCS-G016	*3	DCV-016
YARIS CROSS (INCL. HYBRID)	2020-	MXPB10, MXPB15, MXPJ10, MXPJ15	DCP-024R/L	DCP-016R/L	DCS-G025 +Side clip	DCS-G016	DCV-024 +Side clip	DCV-016
UD TRUCKS								
BIG THUMB	1992-2005	All	DCP-022R/L	DCP-020R/L (DCP-022R/L)	DCS-G022	DCS-G020 (DCS-G022)	DCV-022	DCV-020 (DCV-022)
CONDOR	1993-2011	LK, MK, PK, PW	DCP-020R/L	DCP-020R/L (DCP-020R/L)	DCS-G020	DCS-G020 (DCS-G020)	DCV-020	DCV-020 (DCV-020)
CONDOR	2010-2016	LK, MK, PK, PW	DCP-022R/L	DCP-022R/L	DCS-G022	DCS-G022	DCV-022	DCV-022
CONDOR	2017-2023	MK, LK	DCP-022R/L	DCP-022R/L	DCS-G022	DCS-G022	DCV-022	DCV-022
CONDOR	2017-2023	PK, PW	DCP-020R/L	DCP-020R/L (DCP-019R/L)	DCS-G020	DCS-G020 (DCS-G019)	DCV-020	DCV-020 (DCV-019)
CONDOR (STANDARD)	1995-2014	N/A	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
CONDOR (WIDE)	1995-2014	N/A	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
FINE CONDOR	1992-2011	N/A	*2	*2	*2	*2	*2	*2

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Conventional Blade Series



MODEL	YEAR	MODEL CODE	DCP		DCS-G		DCV	
			Driver	Passenger	Driver	Passenger	Driver	Passenger
			P/N	P/N	P/N	P/N	P/N	P/N
UD TRUCKS								
FINE CONDOR	1992-2011	N/A	DCP-026R/L	DCP-026R/LL	DCS-G026	DCS-G026	DCV-026	DCV-026
KAZET	2014-	RK	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
KAZET	2014-	SK, SF	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
KAZET	2015-2023	FED	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
KAZET (STANDARD)	2014-2023	FBA, FDA, FEA	DCP-019R/L	DCP-019R/L	DCS-G019	DCS-G019	DCV-019	DCV-019
KAZET (WIDE)	2014-2023	FEB, FEC, FED	DCP-020R/L	DCP-020R/L	DCS-G020	DCS-G020	DCV-020	DCV-020
QUON	2004-2017	CD, CG, CV, CW, CX, CZ, GK, GW, GX	DCP-022R/L	DCP-021R/L (DCP-022R/L)	DCS-G022	DCS-G021 (DCS-G022)	DCV-022	DCV-021 (DCV-022)
VOLKSWAGEN								
NEW BEETLE	2000-				DCS-G021	DCS-G021	DCV-021	DCV-021
VOLVO								
S40	1990-1998				DCS-G020	DCS-G020	DCV-020	DCV-020
XC 70, 90	2002-				DCS-G024	DCS-G022	DCV-024	DCV-022
240	1983				DCS-G016	DCS-G016	DCV-016	DCV-016
760	1987-1991				DCS-G021	DCS-G021	DCV-021	DCV-021
960	1987-1991				DCS-G021	DCS-G020	DCV-021	DCV-020

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Notes

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
DAIHATSU			
APPLAUSE	1998-2000	A101S, A111S	*2 Unique shape
ATLEY	1999-2005	S220G, S220V, S230G, S230V	DCP-015R/L, DCS-G015, DCV-015
ATLEY	2005-2021	S321G, S331G, S321G, S331G	DRA-014
ATLEY	2021-	S700V, S710V, S700W, S710W	*1 DRB-014
ATLEY 7	2000-2004	S221G, S231G	DCP-015R/L, DCS-G015, DCV-015
BE-GO	2006-2016	J200G, J210G	DRB-012
BOON	2004-2010	M300S, M301S, M310S, M312S	DRB-014
BOON	2010-2016	M600S, M601S, M610S	DRB-014
BOON	2016-2018	M700S, M710S	DRB-011
BOON LUMINAS	2008-2012	M502G, M512G	DRB-012
CAST	2015-2023	LA250S, LA260S	DRB-011
CHARADE	1993-2000	G200S, G201S, G203S, G213S	DCP-015R/L, DCS-G015, DCV-015
COO	2006-2013	M401S, M402S, M411S	DRB-012
DELTA VAN/WAGON	1998-2001	CR40N, CR50N, SR40N	DCP-016R/L, DCS-G016, DCV-016
ESSE	2005-2011	L235S, L245S	DRB-012
GRAN MAX (CARGO)	2020-2024	S403V, S413V	DRB-016
HIJET CADDIE	2016-2017	LA700V, LA710V	DRB-012
HIJET VAN/CARGO	1999-2004	S200V, S210V	DCP-015R/L, DCS-G015, DCV-015
HIJET VAN/CARGO	2004-2017	S320V, S321V, S330V, S331V	DRA-014
HIJET VAN/CARGO	2017-2021	S321V, S331V, S321W, S331W	DRA-014
HIJET VAN/CARGO	2021-	S700V, S710V, S700W, S710W	*1 DRB-014
MAX	2001-2005	L950S, L952S, L960S, L962S	DRB-012
MEBIUS	2013-2021	ZVW41N	DRB-011
MIRA	1998-2000	L700S, L700V, L710S, L710V	DCP-012R/L, DCS-G012, DCV-012
MIRA	2002-2006	L250S, L250V, L260S, L260V	DRB-012
MIRA	2006-2018	L275S, L285S, L275V, L285V	DRB-012
MIRA AVY	2002-2006	L250S, L250V, L260S, L260V	DRB-012
MIRA COCOA	2009-2018	L675S, L685S	DRB-012
MIRA E:S	2011-2017	LA300S, LA310S	DRB-011
MIRA E:S	2017-	LA350S, LA360S	*1 DRB-011
MIRA GINO	1999-2004	L700S, L710S	DCP-012R/L, DCS-G012, DCV-012
MIRA GINO	2004-2009	L650S, L660S	DRB-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
DAIHATSU			
MIRA GINO 1000	2002-2004	L701S, L711S	DCP-012R/L, DCS-G012, DCV-012
MIRA TOCOT	2018-2023	LA550S, LA560S	*1 DRB-014
MOVE (INCL. CUSTOM)	1999-2002	L900S, L902S, L910S, L912S	*2 Not removable
MOVE (INCL. CUSTOM)	2002-2006	L150S, L152S, L160S	DRB-012
MOVE (INCL. CUSTOM)	2006-2010	L175S, L185S	DRB-012
MOVE (INCL. CUSTOM)	2010-2014	LA100S, LA110S	DRB-012
MOVE (INCL. CUSTOM)	2014-	LA150S, LA160S	DRB-012
MOVE CANVAS	2016-2022	LA800S, LA810S	DRB-012
MOVE CANVAS	2022-	LA850S, LA860S	DRB-012
MOVE CONTE	2008-2017	L575S, L585S	DRB-011
MOVE TERA	2004-2009	L550S, L560S	DRB-012
NAKED	1999-2004	L750S, L760S	DCP-012R/L, DCS-G012, DCV-012
PYZAR	1998-2002	G301G, G303G, G311G, G313G	DCP-012R/L, DCS-G012, DCV-012
ROCKY	2019-	A200S, A201S, A202S, A210S	DRB-011
SONICA	2006-2009	L405S, L415S	DRB-012
STORIA	1998-2004	M100S, M101S, M110S, M111S, M112S	DCP-012R/L, DCS-G012, DCV-012
TAFT	2020-	LA900S, LA910S	DRB-011
TANTO (INCL. CUSTOM)	2003-2007	L350S, L360S	DRB-012
TANTO (INCL. CUSTOM)	2007-2013	L375S, L385S	DRB-012
TANTO (INCL. CUSTOM)	2013-2019	LA600S, LA610S	DRB-014
TANTO (INCL. CUSTOM)	2016-	LA600S, LA610S	DRB-014
TANTO EXE	2009-2014	L455S, L465S	DRB-012
TANTO FUN CROSS	2022-	LA650S, LA660S	DRB-014
TERIOS	2000-2005	J102G, J122G	DCP-012R/L, DCS-G012, DCV-012
TERIOS	1997-2000	J100G	DCP-012R/L, DCS-G012, DCV-012
TERIOS KID	1998-2000	J111G, J131G	DCP-012R/L, DCS-G012, DCV-012
TERIOS KID/LUCIA	2000-2012	J111G, J131G	DCP-012R/L, DCS-G012, DCV-012
THOR (INCL. CUSTOM)	2016-	M900S, M910S	*1 DRB-014
WAKE	2014-2022	LA700S, LA710S	DRB-012
YRV	2000-2005	M200G, M201G, M211G	DRB-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
HONDA			
ACCORD (INCL. HYBRID)	1997-2002	CF3, CF4, CF5, CL1, CL3	DCP-015R/L, DCS-G015, DCV-015
ACCORD TOURER	2008-2013	CW1, CW2	DRA-012
ACCORD WAGON	1997-2002	CF6, CF7, CH9, CL2	DCP-017R/L, DCS-G017, DCV-017
ACCORD WAGON	2002-2005	CM1, CM2, CM3	DRA-012
ACCORD WAGON	2005-2008	CM1, CM2, CM3	DRA-012
ACTY	1999-2018	HH5, HH6	DCP-012R/L, DCS-G012, DCV-012
AIRWAVE	2005-2008	GJ1, GJ2	*1 DRA-012
AIRWAVE	2008-2010	GJ1, GJ2	*1 DRA-012
AVANCIER	1999-2003	TA1, TA2, TA3, TA4	DRA-014
CAPA	1998-2002	GA4, GA6	DCP-012R/L, DCS-G012, DCV-012
CIVIC HATCHBACK (INCL. HYBRID)	1995-2000	EK2, EK3, EK4	DCP-015R/L, DCS-G015, DCV-015
CIVIC HATCHBACK (INCL. HYBRID/TYPE R)	2017-2021	FK7, FK8	DCP-014R/L, DCS-G014, DCV-014
CIVIC TYPE R (INCL. HYBRID) (EXCL. 5 DOOR)	2000-2003	EU1, EU2, EU3, EU4	DRA-014
CIVIC TYPE R (INCL. HYBRID) (EXCL. 5 DOOR)	2003-2005	EU3, EU4	DRA-012
CROSSROAD	2007-2010	RT1, RT2, RT3, RT4	DRA-012
CR-V (INCL. HYBRID)	1995-2001	RD1, RD2	DCP-012R/L, DCS-G012, DCV-012
CR-V (INCL. HYBRID)	2001-2006	RD4, RD5, RD6, RD7	DCP-012R/L, DCS-G012, DCV-012
CR-V (INCL. HYBRID)	2006-2011	RE3, RE4	DRA-014
CR-V (INCL. HYBRID)	2011-2016	RM1, RM4	*7 012
CR-V (INCL. HYBRID)	2018-2020	RT5, RT6, RW1, RW2	DRA-012
CR-V (INCL. HYBRID)	2020-2022	RT5, RT6, RW1, RW2	DRA-012
CR-Z	2010-2017	ZF1, ZF2	DCP-016R/L, DCS-G016, DCV-016
E	2020-2024	ZC7	DRA-014
EDIX	2004-2009	BE1, BE2, BE3, BE4, BE8	*2
ELEMENT	2003-2005	YH2	DRA-012
ELYSION	2004-2013	RR1, RR2, RR3, RR4, RR5, RR6	DRA-014
FIT (INCL. HYBRID)	2001-2007	GD1, GD2, GD3, GD4	*5 DRA-014
FIT (INCL. HYBRID)	2007-2013	GE6, GE7, GE8, GE9, GP1, GP4	DRA-014
FIT (INCL. HYBRID)	2013-2020	GK3, GK4, GK5, GK6, GP5, GP6	DRA-014
FIT (INCL. HYBRID)	2020-	GR1, GR2, GR3, GR4, GR5, GR6, GR7, GR8	DRA-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
HONDA			
FIT ARIA	2002-2009	GD6, GD7, GD8, GD9	DCP-019R/L, DCS-G019, DCV-019
FIT SHUTTLE (INCL. HYBRID)	2011-2015	GG7, GG8, GP2	DRA-014
FREED	2024-	GT1, GT2, GT3, GT4, GT5, GT6, GT7, GT8	DRA-014
FREED (INCL. HYBRID)	2016-2024	GB5, GB6, GB7, GB8	DRA-014
FREED/FREED SPIKE (INCL. HYBRID)	2008-2016	GB3, GB4, GP3	DRA-014
GRACE	2017-2020	GM4, GM5, GM6, GM9	*1 DRA-014
HR-V	1998-2006	GH1, GH2, GH3, GH4	*2 Not removable
INSIGHT	2009-2011	ZE2	*1 DRA-016
INSIGHT	2011-2014	ZE2, ZE3	*2 Unique shape
INTEGRA	1993-2001	DB6, DB7, DB8, DB9, DC1, DC2	DCP-019R/L, DCS-G019, DCV-019
INTEGRA	2001-2006	DC5	DCP-020R/L, DCS-G020, DCV-020
JADE (INCL. HYBRID)	2015-2020	FR4, FR5	DRA-012
JADE (INCL. HYBRID) (WITH ADAS)	2015-2020	FR4, FR5	DRA-012
LAGREAT	1999-2004	RL1	DCP-017R/L, DCS-G017, DCV-017
LIFE	1998-2003	JB1, JB2	DCP-015R/L, DCS-G015, DCV-015
LIFE	2003-2008	JB5, JB6, JB7, JB8	DRA-014
LIFE	2008-2014	JC1, JC2	DRA-014
LIFE DUNK	2000-2003	JB3, JB4	DCP-015R/L, DCS-G015, DCV-015
LOGO	1999-2001	GA3, GA5	*2 Not removable
MDX	2003-2006	YD1	*2
MOBILIO	2001-2008	GB1, GB2	*1 DRA-014
MOBILIO SPIKE	2002-2008	GK1, GK2	*1 DRA-014
N-BOX	2011-2017	JF1, JF2	DRA-014
N-BOX	2017-2023	JF3, JF4	DRA-014
N-BOX	2023-	JF5, JF6	DRA-014
N-BOX SLASH (INCL. CUSTOM)	2014-2020	JF1, JF2	*2
N-BOX+ (INCL. CUSTOM)	2012-2018	JF1, JF2	DRA-014
N-ONE	2012-2020	JG1, JG2	DRA-014
N-ONE	2020-	JG3, JG4	DRA-014
N-VAN (LOW ROOF)	2018-2021	JJ1, JJ2	DCP-015R/L, DCS-G015, DCV-015
N-VAN (HIGH ROOF)	2018-	JJ1, JJ2	DCP-017R/L, DCS-G017, DCV-017
N-WGN (INCL. CUSTOM)	2013-2019	JH1, JH2	DRA-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
HONDA			
N-WGN (INCL. CUSTOM)	2019-	JH3, JH4	DRA-014
ODYSSEY (INCL. HYBRID)	1999-2003	RA6, RA7, RA8, RA9	DRA-012
ODYSSEY (INCL. HYBRID)	2003-2008	RB1, RB2	DRA-012
ODYSSEY (INCL. HYBRID)	2008-2013	RB3, RB4	DRA-012
ODYSSEY (INCL. HYBRID)	2013-2022	RC1, RC2, RC4	DRA-012
ODYSSEY (INCL. HYBRID)	2023-	RC5	DRA-012
ORTHIA	1996-2002	EL1, EL2, EL3	DCP-012R/L, DCS-G012, DCV-012
PARTNER	1996-2006	EY6, EY7, EY8, EY9	DCP-015R/L, DCS-G015, DCV-015
PARTNER	2006-2010	GJ3, GJ4	*1 DRA-012
PRELUDE	1996-2000	BB5, BB6, BB7, BB8	DCP-015R/L, DCS-G015, DCV-015
SHUTTLE (INCL. HYBRID)	2015-2022	GK8, GK9, GP7, GP8	DRA-014
S-MX	1996-2002	RH1, RH2	DCP-015R/L, DCS-G015, DCV-015
STEP WAGON (INCL. HYBRID)	1996-2001	RF1, RF2	DCP-015R/L, DCS-G015, DCV-015
STEP WAGON (INCL. HYBRID)	2003-2005	RF3, RF4, RF5, RF6, RF7, RF8	DRA-014
STEP WAGON (INCL. HYBRID)	2005-2007	RG1, RG2, RG3, RG4	DRA-014
STEP WAGON (INCL. HYBRID)	2007-2009	RG1, RG2, RG3, RG4	DRA-014
STEP WAGON (INCL. HYBRID)	2009-2015	RK1, RK2, RK3, RK4, RK5, RK6, RK7	*1 DRA-016
STEP WAGON (INCL. HYBRID)	2015-2022	RP1, RP2, RP3, RP4, RP5	DCP-015R/L, DCS-G015, DCV-015
STEP WAGON (INCL. HYBRID)	2021-2023	RF3, RF4	DRA-014
STEP WAGON (INCL. HYBRID)	2022-	RP6, RP7, RP8	DRA-014
STREAM	2000-2006	RN1, RN2, RN3, RN4, RN5	DRA-012
STREAM	2006-2014	RN6, RN7, RN8, RN9	DRA-012
THAT'S	2002-2007	JD1, JD2	*2 Not removable
TORNEO	1997-2002	CF3, CF4, CF5, CL1, CL3	DCP-015R/L, DCS-G015, DCV-015
VAMOS	1999-2003	HM1, HM2	DCP-014R/L, DCS-G014, DCV-014
VAMOS	2003-2018	HM1, HM2	*2 Not removable
VAMOS HOBIO	2003-2018	HM3, HM4, HJ1, HJ2	*2 Not removable
VEZEL (INCL. HYBRID)	2013-2021	RU1, RU2, RU3, RU4	DRA-010
VEZEL (INCL. HYBRID)	2021-	RV3, RV4, RV5, RV6	DRA-014
WR-V	2024-	DG5	DRA-012
Z	1998-2022	PA1	DCP-012R/L, DCS-G012, DCV-012
ZEST	1996-2012	JE1, JE2	DRA-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
ISUZU			
ASKA	1997-2001	CJ2, CJ3	DCP-015R/L, DCS-G015, DCV-015
FILLY	1997-2002	JALE50, JALWE50, JAPE50, JAPWE50, JATE50, JATWE50, JAVE50, JAVWE50	DCP-018R/L, DCS-G018, DCV-018
MOCO	2001-2012	E25	DRA-016 (018 or 019)
MOCO (EXCL. WIDE)	2012-	E26	DRA-016
RODEO BIGHORN	1995-2002	UBS25DW, UBS26DW, UBS26GW, UBS69DW, UBS69GW, UBS73DW, UBS73GW	DCP-015R/L, DCS-G015, DCV-015
LEXUS			
CT	2011-2022	ZWA10	DRB-008
LBX	2023-	MAYH10, MAYH15, GAYA16	** (DRB-010)
LM	2023-	TAWH15W	DRB-014
LX	2015-2021	URJ201W	DRB-012
LX	2022-	VJA310W, VJH310W	DRA-012
NX (INCL. HYBRID)	2014-2018	AGZ10, AGZ15, AYZ10, AYZ15	DRB-012
NX (INCL. HYBRID)	2018-2021	AGZ10, AGZ15, AYZ10, AYZ15	DRB-012
NX (INCL. HYBRID)	2021-	AAZA20, AAZA25, AAZH20, AAZH25, AAZH26, TAZA25	DRB-012
RX	2022-	AALH16, TALA10, TALA15, TALH17, AALH10, AALH15	*2 Unique connect
RX (INCL. HYBRID)	2009-2015	AGL10W, GGL10W, GGL15W, GGL16W, GYL10W, GYL15W, GYL16W	*2 Unique shape
RX (INCL. HYBRID)	2015-2022	AGL20W, AGL25W, GYL20W, GYL25W	*2 Unique shape
RX (INCL. HYBRID)	2017-2022	GYL26W	DRB-012
MAZDA			
2	2019-	DJ5AS, DJ5FS, DJLFS, DJLAS	DRA-014
3 FASTBACK	2019-	BP5P, BP8P, BPEP, BPFJ3P, BPFP, BP5R, BP8R, BPFJ3R, BPEK3R	DRA-014
6 WAGON	2019-2024	GJEFW, GJ2AW, GJ2FW, GJ5FW	DRB-012
ATENZA SEDAN	2008-2012	GHEFP, GH5AP, GH5FP	DRB-014
ATENZA SPORTS	2002-2007	GG3S, GGES	DCP-020R/L, DCS-G020, DCV-020
ATENZA SPORTS	2008-2012	GHEFS, GH5AS, GH5FS	*2 Unique shape
ATENZA WAGON (INCL. SPORTS WAGON)	2002-2007	GYEW, GY3W	DRB-012
ATENZA WAGON (INCL. SPORTS WAGON)	2008-2012	GHEFW, GH5AW, GH5FW	DRB-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
MAZDA			
ATENZA WAGON (INCL. SPORTS WAGON)	2012-2014	GJEFW, GJ2FW, GJ5FW	DRB-012
ATENZA WAGON (INCL. SPORTS WAGON)	2015-2018	GJEFW, GJ2AW, GJ2FW, GJ5FW	DRB-012
ATENZA WAGON (INCL. SPORTS WAGON)	2016-2018	GJEFW, GJ2AW, GJ2FW, GJ5FW	DRB-012
ATENZA WAGON (INCL. SPORTS WAGON)	2018-2019	GJEFW, GJ2AW, GJ2FW, GJ5FW	DRB-012
AXELA SPORTS	2003-2009	BK3P, BK5P, BKEP	*2 Unique shape
AXELA SPORTS	2009-2013	BL5FW, BLEFW, BLEAW, BL3PW, BL6FJ, BLFFW, BL3FW	DRB-014
AXELA SPORTS	2013-2016	BM2FS, BM5FS, BM5AS, BMEFS	DRB-012
AXELA SPORTS	2016-2019	BM2AS, BM2FS, BM5FS, BM5AS, BMEFS, BMLFS	DRB-012
AZ OFFROAD	1998-2014	JM23W	DCP-012R/L, DCS-G012, DCV-012
AZ WAGON	1999-2003	MD11S, MD12S, MD21S, MD22S	*2 Not removable
AZ WAGON	2003-2007	MJ21S, MJ22S	DRB-012 or DRB-014
AZ WAGON	2007-2008	MJ22S	DRB-014
AZ WAGON	2008-2012	MJ23S	*1 DRB-014
BIANTE	2008-2018	CC3FW, CCEAW, CCEFW, CCFFW	DRB-014
BONGO	1999-2020	SK82V, SKF2V, SKP2V, SKP2M, SLP2L, SLP2M, SLP2T, SLP2V	DCP-016R/L, DCS-G016, DCV-016
BONGO (VAN)	2020-	S403Z, S413Z	DRB-016
BONGO BRAWNY	1999-2010	SKE6V, SKF6V	DCP-016R/L, DCS-G016, DCV-016
BONGO BRAWNY (VAN)	2019-	GDH206M, TRH200M, GDH201M	DCP-017R/L, DCS-G017, DCV-017
BONGO FRIENDEE	1995-2005	SG5W, SGEW, SGE3, SGL3, SGL5, SGLR, SGLW	*1 016
CAPELLA WAGON (CAPELLA CARGO)	1997-2002	GW5R, GW8W, GWER, GWEW, GWFW	*1 DRA-013
CAROL (INCL. HYBRID)	1998-2004	HB12S, HB22S, HB23S	012 or 014
CAROL (INCL. HYBRID)	2004-2009	HB24S	DRB-014
CAROL (INCL. HYBRID)	2009-2014	HB25S, HB35S	DRB-011
CAROL (INCL. HYBRID)	2015-2021	HB36S	DRB-011
CAROL (INCL. HYBRID)	2022-	HB37S, HB97S	DRB-011
CX-3	2015-2016	DK5AW, DK5FW	DRA-010
CX-3	2016-	DK5##, DK8##, DKE##, DKL##	DRA-010
CX-30	2019-	DMEP, DMFP, DM8P, DMEJ3P	DRA-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
MAZDA			
CX-5	2012-2017	KEEAW, KEEFW, KE2AW, KE2FW, KE5AW, KE5FW	DRB-014
CX-5	2015-2017	KEEAW, KEEFW, KE2AW, KE2FW, KE5AW, KE5FW	DRB-014
CX-5	2017-	KF2P, KF5P, KFEP	DRB-014
CX-60	2022-2024	KH3P, KH5P, KH3R3P, KH5S3P	DRB-012
CX-60	2024-	KH3P, KH5P, KH3R3P, KH5S3P	DRB-012
CX-7	2006-2011	ER3P	DRB-014
CX-8	2017-2023	KG2P, KG5P	DRA-014
CX-80	2024-	KL3P, KL3R3P, KL5S3P	DRB-012
DEMIO	1999-2002	DW3W, DW5W	DRB-016
DEMIO	2002-2007	DY3R, DY3W, DY5R, DY5W	DRA-014
DEMIO	2007-2014	DE3AS, DE3FS, DE5FS, DEJFS	DRA-014
DEMIO	2014-2016	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS	DRA-014
DEMIO	2016-2017	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS	DRA-014
DEMIO	2017-2019	DJ3AS, DJ3FS, DJ5AS, DJ5FS, DJLFS, DJLAS	DRA-014
FAMILIA S-WAGON	1999-2003	BJ5W, BJ8W, BJFW	DCP-014R/L, DCS-G014, DCV-014
FAMILIA VAN	1999-2008	#Y11	DRA-014 (012)
FAMILIA VAN	2007-2018	BVY12, BVAY12, BVJY12, BVZNY12	DRA-014
FAMILIA VAN	2018-	NCP160M, NCP165M	DRB-014
FLAIR (INCL. HYBRID)	2012-2017	MJ34S, MJ44S	DRA-012
FLAIR (INCL. HYBRID)	2017-2022	MJ55S, MJ95S	DRA-012
FLAIR (INCL. HYBRID)	2022-	MJ55S, MJ95S	DRA-012
FLAIR CROSSOVER (INCL. HYBRID)	2014-2015	MS31S, MS41S	DRB-011
FLAIR CROSSOVER (INCL. HYBRID)	2015-2018	MS41S	DRB-011
FLAIR CROSSOVER (INCL. HYBRID)	2020-	MS52S, MS92S	DRA-010
FLAIR WAGON (INCL. HYBRID)	2012-2013	MM21S	*1 DRA-012
FLAIR WAGON (INCL. HYBRID)	2013-2018	MM32S, MM42S	DRB-012
FLAIR WAGON (INCL. HYBRID)	2018-2023	MM53S	DRA-010
FLAIR WAGON (INCL. HYBRID)	2020-2023	MM53S	DRA-010
FLAIR WAGON (INCL. HYBRID)	2023-	MM94S, MM54S	*1 DRA-010
LAPUTA	1999-2006	HP11S, HP12S, HP21S, HP22S	DCP-012R/L, DCS-G012, DCV-012
MPV	1999-2006	LW3W, LW5W, LW5W, LWFW	DCP-016R/L, DCS-G016, DCV-016

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
MAZDA			
MPV	2006-2016	LY3P	DRB-014
MX-30	2020-	DREJ3P, DRH3P	DRA-014
PREMACY	1999-2005	CP8W, CPEW	DCP-014R/L, DCS-G014, DCV-014
PREMACY	2005-2010	CR3W, CREW	*1 DRB-012
PREMACY	2010-2018	CWEAW, CWEFW, CWFFW	DRB-012
RX-7	1991-2003	FD3S	DCP-018R/L, DCS-G018, DCV-018
SCRUM	1999-2005	DG52V, DG52W, DH52V, DH52W, DG62W, DG62V	DCP-012R/L, DCS-G012, DCV-012
SCRUM	2005-2015	DG64V, DG64W	*1 DRB-014
SCRUM	2015-	DG17V, DG17W	*1 DRB-012
SPIANO	2002-2003	HF21S	DCP-012R/L, DCS-G012, DCV-012
SPIANO	2003-2008	HF21S	*1 DRB-012
TRIBUTE	2000-2005	EP3W, EPEW, EPFW	DCP-012R/L, DCS-G012, DCV-012
VERISA	2004-2015	DC5R, DC5W	DRA-016
MAZDA (FORD JP)			
FESTIVA WAGON	1999-2003	DW3WF, DW5WF	DRB-016
FREDA	1995-2000	SG5WF, SGE3F, SGEWF, SGL3F, SGL5F, SGLRF, SGLWF	*1 016
IXION	1999-2001	CP8WF	DCP-014R/L, DCS-G014, DCV-014
MITSUBISHI			
AIRTREK	2001-2005	CU2W, CU4W, CU5W	DRB-014
ASPIRE	1998-2002	EA1A, EC1A, EA7A, EC7A	DCP-017R/L, DCS-G017, DCV-017
CHALLENGER	1996-2001	K94W, K94WG, K96W, K97WG, K99W	DCP-017R/L, DCS-G017, DCV-017
COLT	2002-2013	Z21A, Z22A, Z23A, Z24A, Z25A, Z26A, Z27A, Z27AG, Z28A	DRB-012
COLT PLUS	2004-2006	Z23W, Z24W, Z27W, Z27WG	DRB-014
COLT PLUS	2006-2012	Z21W, Z22W, Z23W, Z24W, Z27WG	DRB-012
DELICA D:2 (INCL. HYBRID)	2011-2015	MB15S	DRA-012
DELICA D:2 (INCL. HYBRID)	2015-2020	MB36S, MB46S	DRB-012
DELICA D:2 (INCL. HYBRID)	2020-2025	MB37S	DRB-012
DELICA D:2 (INCL. HYBRID)	2025-	MBD7S	DRB-012
DELICA D:3	2011-2019	BM20	DRA-014
DELICA D:5	2007-2019	CV1W, CV2W, CV4W, CV5W	DRA-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
MITSUBISHI			
DELICA D:5 (DIESEL)	2019-	CV1W	DRA-014
DELICA D:5 (GASOLINE)	2019	CV2W, CV5W	DRA-014
DELICA MINI	2023-	B34A B35A B37A B38A	DRA-012
DELICA SPACE GEAR	1994-2005	PA4W, PA5W, PB4W, PB5W, PB6W, PC4W, PC5W, PD4W, PD6W, PD8W, PE8W, PF6W, PF8W	DCP-017R/L, DCS-G017, DCV-017
DELICA SPACE GEAR	2005-2007	PD6W	DCP-016R/L, DCS-G016, DCV-016
DELICA VAN/CARGO	1999-2011	SK22VM, SK22MM, SK82VM, SKF2VM, SKE6VM, SKF6VM	DCP-016R/L, DCS-G016, DCV-016
DELICA VAN/CARGO	2011-2019	BVM20	DRA-014
DIAMANTE	1996-2005	F31A, F34A, F36A, F41A, F46A	DCP-019R/L, DCS-G019, DCV-019
DIAMANTE WAGON	1999-2001	F36W	DCP-016R/L, DCS-G016, DCV-016
DION	2000-2002	CR6W, CR9W	DCP-015R/L, DCS-G015, DCV-015
DION	2002-2006	CR5W, CR6W, CR9W	DRA-014
ECLIPSE CROSS (INCL. PHEV)	2018-2020	GK1W, GK9W	DRA-010
ECLIPSE CROSS (INCL. PHEV)	2020-	GK1W, GL3W	DRA-012
EK CROSS	2019-	B34W, B35W, B37W, B38W	DRA-012
EK CROSS EV	2022-	B5AW	DRA-012
EK CROSS SPACE	2020-2023	B34A, B35A, B37A, B38A	DRA-012
EK SPACE	2014-2020	B11A	DRA-012
EK SPACE	2020-	B34A, B35A, B37A, B38A	DRA-012
EK WAGON (INCL. CUSTOM)	2001-2006	H81W	DRA-012
EK WAGON (INCL. CUSTOM)	2006-2013	H82W	DRA-012
EK WAGON (INCL. CUSTOM)	2013-2019	B11W	DRA-012
EK WAGON (INCL. CUSTOM) (WITH ADAS)	2014-2019	B11W	DRA-012
EK WAGON (INCL. CUSTOM)	2019-	B33W, B36W	DRA-012
GALANT	1996-2005	EA1A, EC1A, EA3A, EC3A, EC5A, EA7A, EC7A	DCP-017R/L, DCS-G017, DCV-017
GRANDIS	1997-2003	N84W, N86W, N94W, N96W	DCP-015R/L, DCS-G015, DCV-015
GRANDIS	2003-2009	NA4W	DRA-012
GTO	1990-2001	Z15A, Z16A	*2 Unique shape
I	2007-2009	HA1W	DRA-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
MITSUBISHI			
I	2009-2013	HA1W	DRA-012
I-MIEV	2009-2021	HA3W, HA4W, HD4W	DRA-012
I-MIEV	2009	HA3W	DRA-012
LANCER	1997-2000	CK1A, CK2A, CK4A, CK6A, CK8A, CM2A, CM5A, CM8A	DCP-016R/L, DCS-G016, DCV-016
LANCER	2003-2010	CS2A, CS5A, CS6A	DCP-017R/L, DCS-G017, DCV-017
LANGER CARGO	2002-2008	CS2V	DCP-014R/L, DCS-G014, DCV-014
LANCER CARGO	2008-2019	CVAY12, CVJY12, CVY12, CVZNY12	DRA-014
LANCER CEDIA	2000-2003	CS2A, CS5A	DCP-017R/L, DCS-G017, DCV-017
LANCER CEDIA WAGON	2000-2003	CS5W	*2 Not removable
LANCER EVOLUTION (VII - IX)	2001-2007	CT9A	DCP-017R/L, DCS-G017, DCV-017
LANCER EVOLUTION WAGON	2005-2007	CT9W	*2 Not removable
LANCER WAGON	2003-2008	CS2W, CS5W	*2 Not removable
LEGNUM	1998-2002	EA1W, EA3W, EA4W, EA7W, EC1W, EC3W, EC5W, EC7W	DCP-016R/L, DCS-G016, DCV-016
LIBERO	1998-2002	CB2W, CB4W, CB5W, CB8W, CD5W	DCP-016R/L, DCS-G016, DCV-016
MINICA	1998-2011	H42A, H42V, H47A, H47V	012 or 014
MINICAB EV	2023-	U69V	*1 DRB-014
MINICAB MIEV	2011-2023	U67V, U68V	DRB-014
MINICAB/TOWN BOX (INCL. WIDE)	1999-2005	U61W, U62W, U63W, U64W, U65W, U66W, U6#V	DCP-014R/L, DCS-G014, DCV-014
MINICAB/TOWN BOX (INCL. WIDE)	2005-2014	U61W, U62W, U61V, U62V, U61T, U61TP, U62T, U62TP	DRB-014
MINICAB/TOWN BOX (INCL. WIDE)	2014-2015	DS64V, DS64W	*1 DRB-014
MINICAB/TOWN BOX (INCL. WIDE)	2015-	DS17V, DS17W	*1 DRB-012
MIRAGE	2012-2020	A03A, A05A	DRB-012
MIRAGE	2020-2023	A03A	DRB-012
MIRAGE DINGO	1998-2002	CQ1A, CQ2A, CQ5A	DCP-016R/L, DCS-G016, DCV-016
MIRAGE SEDAN	1997-2000	CK1A, CK2A, CK4A, CK6A, CK8A, CM2A, CM5A, CM8A	DCP-016R/L, DCS-G016, DCV-016
OUTLANDER	2005-2012	CW4W, CW5W, CW6W	DRA-012
OUTLANDER	2012-2013	GF7W, GF8W	DRA-012
OUTLANDER	2014-2020	GF7W, GF8W	DRA-012
OUTLANDER PHEV	2013-2021	GG2W, GG3W	DRA-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
mitsubishi			
OUTLANDER PHEV	2021-	GN0W	*2 Unique shape
PAJERO	1999-2006	V63W, V65W, V68W, V73W, V75W, V77W, V78W	DCP-016R/L, DCS-G016, DCV-016
PAJERO	2006-2009	V83W, V87W, V93W, V97W, V98W	DRA-014
PAJERO	2009-2019	V83W, V87W, V88W, V93W, V97W, V98W	DRA-012
PAJERO IO	1998-2007	H61W, H62W, H66W, H67W, H71W, H72W, H76W, H77W	014 or 015 or 016
PAJERO MINI	1998-2008	H53A, H58A	012 or 014
PAJERO MINI	1998-2013	H53A, H58A	DCP-012R/L, DCS-G012, DCV-012
ROSA	1997-2019	BE6#, BG6#	DCP-016R/L, DCS-G016, DCV-016
ROSA	2019-	BE7#, BG7#	DCP-016R/L, DCS-G016, DCV-016
RVR	1997-2002	N61W, N64WG, N71W, N73WG, N74WG	DCP-016R/L, DCS-G016, DCV-016
RVR	2010-2024	GA3W, GA4W	DRA-010
TOPPO	2008-2013	H82A	DCP-014R/L, DCS-G014, DCV-014
TOPPO BJ (INCL. WIDE)	1998-2001	H41A, H42A, H42V, H43A, H46A, H47A, H47V, H48A	DCP-014R/L, DCS-G014, DCV-014
TOPPO BJ (INCL. WIDE)	2001-2004	H41A, H42A, H42V, H46A, H47A, H47V	DRA-014
MITSUOKA			
RAY	1996-2000	AC6P, AC6R, HB12S	DCP-015R/L, DCS-G015, DCV-015
VIEWT	1996-2005	K11, K11, AK11, HK11	DCP-016R/L, DCS-G016, DCV-016
NISSAN			
AD	2021-	VY12, VZNY12	DRA-014
AD WAGON/VAN/MAX	2004-2008	Y11	DRA-014 (012)
AD WAGON/VAN/MAX	1999-2004	Y11	DCP-012R/L, DCS-G012, DCV-012
AD/AD EXPART	2006-2016	VAY12, VJY12, VY12, VZNY12	DRA-014
ARIYA	2022-	FE0, SNFE0	DRA-016
AURA	2021-	FE13, FSNE13	*2 Unique shape
AVENIR	1998-2005	PW11, PNW11, RW11, RNW11, SW11, W11	DCS-G013, DCV-013
BASSARA	1999-2000	JU30, JNU30, JHU30, JVU30, JVNU30	DCP-016R/L, DCS-G016, DCV-016
BASSARA	2000-2003	JTU30, JTNU30, JHU30, JU30, JNU30, JVU30, JVNU30	DCP-016R/L, DCS-G016, DCV-016
BLUEBIRD	1996-2000	EU14, ENU14, HU14, HNU14, SU14, QU14	DCP-017R/L, DCS-G017, DCV-017
CARAVAN (EXCL. WIDE)	2021-	###E26	DRA-016
CARAVAN/HOMY	1997-2001	KRE24, KRME24, KRGE24	DCP-016R/L, DCS-G016, DCV-016

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
NISSAN			
CARAVAN/HOMY	2001-2003	CQGE25, CWGE25, CWMGE25, QGE25	DCP-019R/L, DCS-G019, DCV-019
CARAVAN/HOMY	2003-2012	SE25, SGE25, QE25, QGE25, VPE25, VWE25, VWME25	DRA-016 (018 or 019)
CEFIRO	1998-2003	A33, PA33	DCP-018R/L, DCS-G018, DCV-018
CEFIRO WAGON	1998-2003	WPA32, WHA32, WA32	DCP-016R/L, DCS-G016, DCV-016
CIVILIAN	1999-2021	ECW41, EVW41, DCW41, DVW41, EJW41, EHW41, DJW41, DHW41	DCP-016R/L, DCS-G016, DCV-016
CLIPPER EV	2024-	U79V	*1 DRB-014
CLIPPER VAN/TRUCK	2003-2005	U71W, U72W, U71V, U72V, U71T, U71TP, U72T, U72TP	DCP-014R/L, DCS-G014, DCV-014
CLIPPER VAN/TRUCK (INCL. RIO)	2006-2012	U71W, U72W, U71V, U72V, U71T, U71TP, U72T, U72TP	DRB-014
CLIPPER VAN/WAGON (NV100)	2024-	DR17V, DR17W	*1 DRB-012
CUBE/CUBE CUBIC	1999-2000	Z10, AZ10, ANZ10	DCP-012R/L, DCS-G012, DCV-012
CUBE/CUBE CUBIC	2000-2002	AZ10, ANZ10	DCP-012R/L, DCS-G012, DCV-012
CUBE/CUBE CUBIC	2002-2008	BZ11, BNZ11, YZ11, BGZ11, YGZ11, YGNZ11	*2 Unique shape
CUBE/CUBE CUBIC	2008-2020	Z12, NZ12	DRA-012
DAYS	2013-2019	B21W	DRA-012
DAYS (WITH ADAS)	2014-2019	B21W	DRA-012
DAYS	2019-	B43W, B44W, B45W, B46W, B47W, B48W	DRA-012
DAYS ROOX	2014-2020	B21A	DRA-012
DUALIS	2007-2014	J10, KJ10, NJ10, KNJ10	*2 Unique shape
ELGRAND	1997-2002	ALE50, ALWE50, APE50, APWE50, ATE50, ATWE50, FLGE50, FLWGE50	DCP-018R/L, DCS-G018, DCV-018
ELGRAND	2002-2010	E51, ME51, MNE51, NE51	DRA-014
ELGRAND	2010-	PE52, PNE52, TE52, TNE52	DRA-012
EXPERT	1999-2006	VW11, VNW11, VEW11, VENW11	DCS-G013, DCV-013
EXTRAIL (INCL. HYBRID)	2022-	SNT33, T33	*2 Unique shape
FAIRLADY Z	1993-2000	Z32, GZ32, CZ32, GCZ32, HZ32	DCP-016R/L, DCS-G016, DCV-016
FAIRLADY Z	2002-2008	Z33, HZ33	DCP-018R/L, DCS-G018, DCV-018
FAIRLADY Z	2008-2012	Z34, HZ34	DCP-019R/L, DCS-G019, DCV-019
FAIRLADY Z	2008-2022	Z34, HZ34	DCP-019R/L, DCS-G019, DCV-019
JUKE	2010-2020	YF15, F15, NF15	*2 Unique shape
KICKS	2008-2012	H59A	DCP-012R/L, DCS-G012, DCV-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
NISSAN			
KICKS E-POWER	2020-	P15	*2 Unique shape
LAFESTA (INCL. JOY)	2004-2012	B30, NB30	DRA-012
LAFESTA HIGHWAY STAR	2011-2018	CWEAWN, CWEFWN, CWFFWN	DRB-012
LEAF	2010-2017	ZE0, AZE0	DRA-010 (*1 012)
LEAF	2017-	ZE1	DRA-014
MARCH	1995-2002	K11, AK11, ANK11, HK11, FHK11	DCP-018R/L, DCS-G018, DCV-018
MARCH	2002-2003	K12, AK12, BK12, BNK12	*2 Unique shape
MARCH	2003-2010	AK12, BK12, BNK12, YK12	*2 Unique shape
MARCH	2010-2022	K13, NK13	DRA-012
MOCO	2002-2004	MG21S	DCP-012R/L, DCS-G012, DCV-012
MOCO	2004-2006	MG21S	*1 DRB-012
MOCO	2006-2011	MG22S	*1 DRB-014
MOCO	2011-2016	MG33S	DRB-014
MURANO	2004-2008	TZ50, PZ50, PNZ50	DRA-014
MURANO	2008-2015	TNZ51, PNZ51, TZ51	DCP-012R/L, DCS-G012, DCV-012
NOTE (INCL. E-POWER)	2005-2012	E11, NE11, ZE11	DRA-012
NOTE (INCL. E-POWER) (E12)	2012-2021	E12, HE12, NE12, SNE12	DRA-012
NOTE (INCL. E-POWER) (E13)	2020-	E13, SNE13	*2 Unique shape
NV100 CLIPPER (INCL. RIO)	2012-2013	U71V, U72V, U71W, U72W	DRB-014
NV100 CLIPPER (INCL. RIO)	2013-2015	DR64V, DR64W	*1 DRB-014
NV100 CLIPPER (INCL. RIO)	2015-2024	DR17V, DR17W	*1 DRB-012
NV100 CLIPPER (INCL. RIO)	2019-2024	DR17V, DR17W	*1 DRB-012
NV150 AD	2016-2021	VY12, VZNY12	DRA-014
NV200 VANNET	2009-	M20, VM20, VNM20	DRA-014
NV350 CARAVAN (EXCL. WIDE)	2012-2022	###E26	DRA-016
OTTI	2005-2006	H91W	DRA-012
OTTI	2006-2013	H92W	DRA-012
PINO	2007-2010	HC24S	DRB-014
PRAIRIE/LIBERTY	1998-2004	PM12, PNM12, RM12, RNM12	DCP-014R/L, DCS-G014, DCV-014
PRESEA	1995-2000	R11, HR11, PR11	DCP-018R/L, DCS-G018, DCV-018
PRESAGE	1998-2000	U30, NU30, HU30, VU30, VNU30	DCP-016R/L, DCS-G016, DCV-016

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
NISSAN			
PRESAGE	2000-2003	TU30, TNU30, HU30, U30, NU30, VU30, VNU30	DCP-016R/L, DCS-G016, DCV-016
PRESAGE	2003-2009	TU31, TNU31, PU31, PNU31	DRA-012
PRIMER/PRIMERA CAMINO	1995-2000	P11, FHP11, HP11, HNP11, QP11	DCP-017R/L, DCS-G017, DCV-017
PRIMERA WAGON/PRIMERA CAMINO WAGON	2000-2000	WQP11, WHP11, WHNP11	DCP-014R/L, DCS-G014, DCV-014
PRIMERA WAGON/PRIMERA CAMINO WAGON	2001-2005	WTP12, WTNP12, WRP12, WHP12	*2 Unique shape
PULSAR/LANGLEY HATCHBACK	1995-2000	FN15, FNN15, EN15, JN15, HN15	DCP-014R/L, DCS-G014, DCV-014
PULSAR/LANGLEY SEDAN	1995-2000	FN15, FNN15, SN15, SNN15, EN15, JN15, HN15	DCP-018R/L, DCS-G018, DCV-018
PULSAR/LANGLEY (5 DOOR)	1995-2000	N15	DCP-014R/L, DCS-G014, DCV-014
PULSAR SERIE S-RV	1996-2000	FN15, FNN15, JN15, HNN15	DCP-014R/L, DCS-G014, DCV-014
RASHEEN	1994-2000	RKNB14, RFNB14	DCP-012R/L, DCS-G012, DCV-012
R'NESSA	1998-2001	N30, NN30, PNN30	DCP-014R/L, DCS-G014, DCV-014
ROOX	2009-2010	ML21S	DRA-012
ROOX	2010-2013	ML21S	DRA-012
ROOX	2020-	B44A, B45A, B47A, B48A	DRA-012
SAFARI	1997-2007	WFGY61, WTY61, VRGY61, WGY61, WYY61	DCP-014R/L, DCS-G014, DCV-014
SAKURA	2022-		DRA-012
SERENA (INCL. HYBRID)	1999-2001	PC24, PNC24, VC24, VNC24	DCP-018R/L, DCS-G018, DCV-018
SERENA (INCL. HYBRID)	2001-2005	TC24, TNC24, RC24	*2 Unique shape
SERENA (INCL. HYBRID)	2005-2010	C25, NC25, CC25, CNC25	DRA-016 (016)
SERENA (INCL. HYBRID)	2010-2013	C26, FC26, NC26, FNC26, HC26, HFC26	DRA-014
SERENA (INCL. HYBRID)	2013-2016	C26, NC26, FNC26, HC26, HFC26	DRA-014
SERENA (INCL. HYBRID)	2016-2022	C27, GC27, GFC27, GFNC27, GNC27, HC27, HFC27	DRA-012
SERENA (INCL. HYBRID)	2022-	C28 FC28 FNC28 GC28 GFC28 NC28 SFNC28 SNC28	DRA-012
SILVIA	1999-2002	S15	DCP-017R/L, DCS-G017, DCV-017
SKYLINE	1998-2000	ER34, BNR34, ENR34, HR34	DCP-018R/L, DCS-G018, DCV-018
SKYLINE	2000-2001	BNR34, HR34, ER34, ENR34	DCP-018R/L, DCS-G018, DCV-018
SKYLINE	2001-2006	V35, NV35, PV35, HV35	DCP-015R/L, DCS-G015, DCV-015
SKYLINE CROSSOVER	2009-2011	J50, NJ50	DRA-014
SKYLINE CROSSOVER	2011-2012	J50, NJ50	DRA-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
NISSAN			
SKYLINE CROSSOVER	2012-2016	J50, NJ50	DRA-014
STAGEA	1999-2001	WHC34, WGC34, WGNC34	DCP-012R/L, DCS-G012, DCV-012
STAGEA	2001-2007	M35, NM35, PM35, PNM35	*1 DRA-010
SUNNY	1998-2004	B15, FB15, FNB15, QB15, SB15, JB15	DCP-017R/L, DCS-G017, DCV-017
SUNNY LUCINO HATCH	1995-2000	FN15, FNN15, EN15, JN15, HN15	DCP-014R/L, DCS-G014, DCV-014
SUNNY LUCINO S-RV	1996-2000	FN15, FNN15, JN15, HNN15	DCP-014R/L, DCS-G014, DCV-014
TEANA	2008-2014	J32, TNJ32, PJ32	DCP-016R/L, DCS-G016, DCV-016
TERRANO (INCL. REGRAS)	1998-2002	TR50, LR50, LUR50, JTR50, JLUR50	DCP-012R/L, DCS-G012, DCV-012
TIIDA	2004-2012	C11, NC11, JC11	DRA-012
TINO	1998-2003	V10, HV10, PV10	DCP-019R/L, DCS-G019, DCV-019
VANNETTE	1999-2017	SK	DCP-016R/L, DCS-G016, DCV-016
WINGROAD	1999-2001	WFY11, WHNY11, WHY11, WPY11	DCP-012R/L, DCS-G012, DCV-012
WINGROAD	2001-2005	WFY11, WHNY11, WRY11	DRA-014 (012)
WINGROAD	2005-2018	Y12, NY12, JY12	DRA-014
X-TRAIL (INCL. HYBRID)	2000-2007	T30, NT30, PNT30	DCP-017R/L, DCS-G017, DCV-017
X-TRAIL (INCL. HYBRID)	2007-2010	DNT31, NT31, T31, TNT31	DRA-014
X-TRAIL (INCL. HYBRID)	2010-2013	DNT31, NT31, T31, TNT31	DCP-014R/L, DCS-G014, DCV-014
X-TRAIL (INCL. HYBRID)	2013-2022	HNT32, HT32, NT32, T32	*2 Unique shape
SUBARU			
CHIFFON (INCL. CUSTOM)	2016-2019	LA600F, LA610F	DRB-014
CHIFFON (INCL. CUSTOM)	2019-	LA650F, LA660F	DRB-014
CROSSTRECK	2022-	GUD, GUE, GUF	DRA-014
DEX	2008-2011	M401F, M411F	DRB-012
DIAS WAGON	2009-2017	S321N, S331N	DRA-014
DIAS WAGON	2017-2020	S321N, S331N	DRA-014
EXIGA	2008-2015	YA4, YA5, YA9, YAM	DRA-014
FORESTER	2000-2002	SF5	DCP-015R/L, DCS-G015, DCV-015
FORESTER	2002-2003	SG5	DCP-015R/L, DCS-G015, DCV-015
FORESTER	2003-2005	SG5, SG9	DRA-016
FORESTER	2005-2007	SG5, SG9	DRA-014
FORESTER	2007-2012	SH5, SH9, SHJ	DRA-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
SUBARU			
FORESTER	2017-2018	SJ5, SJG	DRA-014
FORESTER	2018-2025	SK5, SK9, SKE	DRA-014
FORESTER (2.0i)	2012-2017	SJ5	DRA-014
FORESTER (2.0i-L/2.0i-S)	2012-2015	SJ5	DRA-014
FORESTER (2.0i-L/2.0i-S)	2015-2017	SJ5	DRA-014
FORESTER (S/X/2.0XT)	2012-2015	SJ5, SJG	DRA-014
FORESTER (S/X/2.0XT)	2015-2017	SJ5, SJG	DRA-014
IMPREZA	2023-	GU6, GU7, GUD, GUE	DRA-014
IMPREZA (1.5i)	2009-2011	GH2, GH3	DRA-016
IMPREZA (1.5i-S)	2009-2011	GH2, GH3	DRA-016
IMPREZA (5 DOOR)	2007-2009	GH2, GH3, GH6, GH7, GH8	DRA-016
IMPREZA (5 DOOR)	2009-2011	GH6, GH7, GH8	DRA-016
IMPREZA ANESIS	2008-2009	GE2, GE3, GE6, GE7	DRA-016
IMPREZA ANESIS	2009-2011	GE6, GE7	DRA-016
IMPREZA ANESIS (1.5i)	2009-2011	GE2, GE3	DRA-016
IMPREZA ANESIS (1.5-i-L)	2009-2011	GE2, GE3	DRA-016
IMPREZA G4	2011-2014	GJ2, GJ3, GJ6, GJ7	DRA-016
IMPREZA G4	2014-2016	GJ2, GJ3, GJ6, GJ7	DRA-016
IMPREZA G4	2016-2023	GK2, GK3, GK6, GK7	DRA-016
IMPREZA SEDAN	1992-2000	GC1, GC2, GC4, GC6, GC8	DCP-017R/L, DCS-G017, DCV-017
IMPREZA SEDAN	2000-2007	GD2, GD3, GD9, GDA, GDB, GDC, GDD	DCP-015R/L, DCS-G015, DCV-015
IMPREZA SPORT (INCL. HYBRID)	2011-2014	GP2, GP3, GP6, GP7, GPE	DRA-012
IMPREZA SPORT (INCL. HYBRID)	2014-2016	GP2, GP3, GP6, GP7, GPE	DRA-012
IMPREZA SPORT (INCL. HYBRID)	2016-2023	GT2, GT3, GT6, GT7, GTE	DRA-012
IMPREZA WAGON	1992-2000	GF1, GF2, GF3, GF4, GF5, GF6, GF8, GFA	DCP-015R/L, DCS-G015, DCV-015
IMPREZA WAGON	2000-2004	GG2, GG3, GG9, GGA, GGB	DCP-015R/L, DCS-G015, DCV-015
IMPREZA WAGON	2004-2007	GG2, GG3, GG9, GGA, GGB GGC, GGD	DRA-014
IMPREZA WRX STI (4 DOOR)	2010-2014	GVB, GVF	DRA-016
IMPREZA WRX STI (5 DOOR)	2007-2014	GRB, GRF	DRA-016
IMPREZA XV	2010-2011	GH2, GH3, GH6, GH7	DRA-016
JUSTY (INCL. CUSTOM)	2016-2018	M900F, M910F	*1 DRB-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
SUBARU			
JUSTY (INCL. CUSTOM)	2018-	M900F, M910F	*1 DRB-014
LEGACY AUTOBACK	2003-2009	BP9, BPE, BPH	DRA-014
LEGACY AUTOBACK	2009-2014	BR9, BRF, BRM	DRA-014
LEGACY AUTOBACK	2014-2021	BS9	DRA-014
LEGACY AUTOBACK	2021-2025	BT5	DRA-016
LEGACY B4 SEDAN	1998-2001	BE5, BE9	DCP-018R/L, DCS-G018, DCV-018
LEGACY B4 SEDAN	2001-2003	BE5, BE9, BEE, BES	DCP-018R/L, DCS-G018, DCV-018
LEGACY B4 SEDAN	2003-2009	BL5, BL9, BLE	*1 DRA-016
LEGACY B4 SEDAN	2009-2014	BM9, BMG, BMM	*1 DRA-016
LEGACY B4 SEDAN	2014-2015	BN9	DRA-016
LEGACY B4 SEDAN	2015-2020	BN9	DRA-016
LEGACY TOURING WAGON	1998-2003	BH5, BH9, BHC, BHE	DCP-015R/L, DCS-G015, DCV-015
LEGACY TOURING WAGON	2003-2009	BP5, BP9, BPE	DRA-014
LEGACY TOURING WAGON	2009-2014	BR9, BRG, BRM	DRA-014
LEVORG	2014-2020	VM4, VMG	DRA-014
LEVORG	2020-	VN5, VNH	DRA-014
LUCRA	2010-2015	L455F, L465F	DRB-012
PREO	1998-2000	RA1, RA2, RV1, RV2	DCP-014R/L, DCS-G014, DCV-014
PREO	2000-2010	RA1, RA2, RV1, RV2	DCP-014R/L, DCS-G014, DCV-014
PREO	2010-2018	L275F, L285F	DRB-012
PREO PLUS	2012-2017	LA300F, LA310F	DRB-011
PREO PLUS	2017-	LA350F, LA360F	*1 DRB-011
R1	2004-2010	RJ1, RJ2	DRA-012
R2	2003-2010	RC1, RC2	DRA-012
REX	2022-	A201F	DRB-011
SAMBAR TRY/DIAS	1999-2002	TV1, TV2, TW1	DCP-016R/L, DCS-G016, DCV-016
SAMBAR TRY/DIAS	2002-2003	TW1, TW2, TV1, TV2, TT1, TT2	DCP-016R/L, DCS-G016, DCV-016
SAMBAR TRY/DIAS	2003-2006	TW1, TW2, TV1, TV2, TT1, TT2	DCP-016R/L, DCS-G016, DCV-016
SAMBAR TRY/DIAS	2006-2012	TW1, TW2, TV1, TV2, TT1, TT2	DCP-016R/L, DCS-G016, DCV-016
SAMBAR TRY/DIAS	2012-2017	S321B, S331B, S321Q, S331Q	DRA-014
SAMBAR TRY/DIAS	2017-2021	S321B, S331B, S321Q, S331Q	DRA-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
SUBARU			
SAMBAR VAN	2022-	S700B, S710B	*1 DRB-014
STELLA (INCL. CUSTOM)	2006-2011	RN1, RN2	DRA-014
STELLA (INCL. CUSTOM)	2011-2014	LA100F, LA110F	DRB-012
STELLA (INCL. CUSTOM)	2014-2017	LA150F, LA160F	DRB-012
STELLA (INCL. CUSTOM)	2017-	LA150F, LA160F	DRB-012
TRAVIQ	2000-2004	XM182, XM220	*2
TREZIA	2010-2016	NSP120X, NCP120X, NCP125X	DRB-012
WRX S4	2014-2016	VAG	DRA-016
WRX S4	2016-2021	VAG	DRA-016
WRX S4	2021-	VBH	*7 DRA-014
WRX STI	2014-2016	VAB	DRA-016
WRX STI	2016-2020	VAB	DRA-016
XV (INCL. HYBRID)	2012-2014	GP7, GPE	DRA-012
XV (INCL. HYBRID)	2014-2017	GP7, GPE	DRA-012
XV (INCL. HYBRID)	2017-2022	GT3, GT7, GTE	DRA-012
SUZUKI			
AERIO	2001-2003	RA21S, RB21S, RC51S, RD51S	D/CP-012R/L, DCS-G012, DCV-012
AERIO	2003-2007	RA21S, RB21S, RC51S, RD51S	DRA-012
ALTO (INCL. HYBRID)	1998-2004	HA12S, HA12V, HA22S, HA23S, HA23V	012 or 014
ALTO (INCL. HYBRID)	2004-2009	HA24S, HA24V	DRB-014
ALTO (INCL. HYBRID)	2009-2014	HA25S, HA25V, HA35S	DRB-011
ALTO (INCL. HYBRID)	2014-2021	HA36S, HA36V	DRB-011
ALTO (INCL. HYBRID)	2021-	HA37S, HA97S	DRB-011
BALENO	2016-2020	WB32S, WB42S	DRB-012
CARRY/EVERY	1999-2002	DA52V, DA52W, DA62V, DA62W, DB52V, DA62T	D/CP-012R/L, DCS-G012, DCV-012
CARRY/EVERY	2002-2005	DA62V, DA62W, DA63T	D/CP-012R/L, DCS-G012, DCV-012
CARRY/EVERY	2005-2013	DA64V, DA64W, DA63T, DA65T	*1 DRB-014
CERVO	2006-2009	HG21S	DRA-012
CHEVROLET CRUISE	2001-2008	HR51S, HR52S, HR81S, HR82S	DRA-012
CHEVROLET MW	2000-2010	ME34S, ME63S, ME64S	D/CP-014R/L, DCS-G014, DCV-014
ESCUDO (INCL. HYBRID)	1997-2005	TA02W, TA52W, TD02W, TD32W, TD62W, TL52W	D/CP-015R/L, DCS-G015, DCV-015

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
SUZUKI			
ESCUDO (INCL. HYBRID)	2005-2015	TA74W, TDA4W, TDB4W, TD54W, TD94W	DRB-012
ESCUDO (INCL. HYBRID)	2015-2024	YD21S, YE21S, YEAT1S, YEH1S	DRA-010
ESCUDO 2.4	2015-2017	TDA4W	DRB-012
EVERY	2013-2015	DA64V, DA64W	*1 DRB-014
EVERY	2015-2019	DA17V, DA17W	*1 DRB-012
EVERY	2019-	DA17V, DA17W	*1 DRB-012
EVERY PLUS/LANDY	1999-2005	DA32W	DCP-012R/L, DCS-G012, DCV-012
FRONX	2024-	WDB3S WEB3S	DRB-012
HUSSLER (INCL. HYBRID)	2014-2015	MR31S, MR41S	DRB-011
HUSSLER (INCL. HYBRID)	2015-2019	MR31S, MR41S	DRB-011
HUSSLER (INCL. HYBRID)	2015-2019	MR41S	DRB-011
HUSSLER (INCL. HYBRID)	2020-	MR52S, MR92S	DRA-010
IGNIS (INCL. HYBRID)	2016-	FF21S	DRA-012
JIMNY	1995-1998	JA12C, JA12V, JA12W, JA22W	DCP-012R/L, DCS-G012, DCV-012
JIMNY	1998-2018	JB23W	*2
JIMNY	2018-	JB64W	DCP-012R/L, DCS-G012, DCV-012
JIMNY SIERRA	2002-2018	JB43W	*2
JIMNY SIERRA	2018-	JB74W	DCP-012R/L, DCS-G012, DCV-012
JIMNY WIDE	1998-2001	JB33W, JB43W	DCP-012R/L, DCS-G012, DCV-012
KEI	1998-2003	HN11S, HN12S, HN21S, HN22S	DCP-012R/L, DCS-G012, DCV-012
KEI	2003-2006	HN22S	DCP-012R/L, DCS-G012, DCV-012
KEI	2006-2009	HN22S	DRA-012
LANDY (INCL. HYBRID)	2007-2010	SC25, SNC25	DRA-016
LANDY (INCL. HYBRID)	2010-2013	SC26, SNC26	DRA-014
LANDY (INCL. HYBRID)	2014-2016	SC26, SNC26, SHC26	DRA-014
LANDY (INCL. HYBRID)	2016-2022	SC27, SGC27, SGNC27	DRA-012
LANDY (INCL. HYBRID)	2022-	MZRA90C, MZRA95C, ZWR90C, ZWR95C	DRA-014
LAPIN	2002-2003	HE21S	DCP-012R/L,DCS-G012,DCV-012
LAPIN	2003-2008	HE21S	*1 DRB-012
LAPIN	2008-2015	HE22S	DRB-011
LAPIN	2015-2022	HE33S	DRA-010
LAPIN	2022-	HE33S	DRA-010

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series




MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
SUZUKI			
MR WAGON	2001-2004	MF21S	DCP-012R/L, DCS-G012, DCV-012
MR WAGON	2004-2005	MF21S	*1 DRB-012
MR WAGON	2006-2010	MF22S	*1 DRB-014
MR WAGON	2011-2016	MF33S	DRB-014
PALLET	2008-2010	MK21S	DRA-012
PALLET	2010-2013	MK21S	DRA-012
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2005-2010	MA34S	DCP-014R/L, DCS-G014, DCV-014
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2011-2015	MA15S	DRA-012
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2015-2020	MA26S, MA36S, MA46S	DRB-012
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2020-2024	MA27S, MA37S	DRB-012
SOLIO/SOLIO BANDIT (INCL. HYBRID)	2025-	MAD47S	DRB-012
SPACIA (INCL. HYBRID)	2013-2017	MK32S, MK42S	DRB-012
SPACIA (INCL. HYBRID)	2017-2020	MK53S	DRA-010
SPACIA (INCL. HYBRID)	2020-2023	MK53S	DRA-010
SPACIA (INCL. HYBRID)	2023-	MK54S, MK94S	*1 DRB-010
SPACIA BASE	2022-	MK33V	DRA-010
SPLASH	2008-2014	XB32S	DRA-010
SWIFT (INCL. HYBRID)	2017-2023	ZC13S, ZC43S, ZC53S, ZC83S, ZD53S, ZD83S	*2
SWIFT (INCL. HYBRID)	2023-	ZCEDS, ZDEDS, ZCDDS, ZDDDS	*1 DRB-008
SWIFT SPORTS	2017-	ZC33S	*2
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2000-2003	HT51S	DCP-014R/L,DCS-G014,DCV-014
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2003-2006	HT51S, HT81S	DRA-012 (014)
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2004-2010	ZC11S, ZC21S, ZC31S, ZC71S, ZD11S, ZD21S	DRA-010
SWIFT/SWIFT SPORTS (INCL. HYBRID)	2010-2016	ZC32S, ZC72S, ZD72S	DRA-010
SX4	2006-2014	YA11S, YA41S, YB11S, YB41S, YC11S	DRA-010
SX4 S CROSS	2015-2020	YA22S, YB22S	DRA-010
WAGON R SMILE (INCL. HYBRID)	2021-2024	MX81S, MX91S	*2
WAGON R SMILE (INCL. HYBRID)	2024-	MX81S, MX91S	DR025
WAGON R SOLIO	1999-2000	MA63S	DCP-014R/L, DCS-G014, DCV-014
WAGON R SOLIO	2000-2005	MA34S, MA64S	DCP-014R/L, DCS-G014, DCV-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
SUZUKI			
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	1999-2003	MC11S, MC12S, MC21S, MC22S	*2 Not removable
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2003-2007	MH21S, MH22S	DRB-012 or DRB-014
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2007-2008	MH22S	DRB-014
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2008-2012	MH23S	*1 DRB-014
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2012-2017	MH34S, MH44S	DRA-012
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2017-2022	MH35S, MH55S, MH85S, MH95S	DRA-012
WAGON R/WAGON R STINGLEY (INCL. HYBRID)	2022-	MH55S, MH85S, MH95S	DRA-012
XBEE (INCL. HYBRID)	2017-2020	MN71S	DRB-011
XBEE (INCL. HYBRID)	2020-	MN71S	DRB-011
TOYOTA			
ALEX	2001-2006	NZE121, NZE124, ZZE122, ZZE123, ZZE124	DRA-014
ALLION	2001-2007	AZT240, NZT240, ZZT240, ZZT245	DRB-016
ALLION	2007-2021	NZT260, ZRT260, ZRT261, ZRT265	DRB-014
ALPHARD (INCL. HYBRID)	2002-2008	ANH10W, ANH15W, ATH10W, MNH10W, MNH15W	DRB-016
ALPHARD (INCL. HYBRID)	2008-2014	ANH20W, ANH25W, ATH20W, GGH20W, GGH25W	DRB-016
ALPHARD (INCL. HYBRID)	2015-2017	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	DRB-014
ALPHARD (INCL. HYBRID)	2018-2023	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	DRB-014
ALPHARD (INCL. HYBRID)	2023-	AAHH40W, AAHH45W, AGH40W, AGH45W AAHP45W	DRB-012
ALTEZA JETA	2001-2005	GXE10W, GXE15W, JCE10W, JCE15W	DRB-014
AQUA	2011-2021	NHP10	DRB-008
AQUA	2021-	MXPK10, MXPK11, MXPK15, MXPK16	DRA-010
AURIS (INCL. HYBRID)	2006-2012	NZE151H, NZE154H, ZRE152H, ZRE154H	DRA-012
AURIS (INCL. HYBRID)	2012-2018	ZRE186H, ZWE186H, NZE181H, NZE184H, NRE185H	*2 200mm
AVENSIS WAGON	2003-2008	AZT250W, AZT251W, AZT255W	DRB-012
AVENSIS WAGON	2011-2018	ZRT272W	DRB-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
TOYOTA			
BB (INCL. OPEN DECK)	2000-2005	NCP30, NCP31, NCP34, NCP35	*2 Not removable
BB (INCL. OPEN DECK)	2005-2016	QNC20, QNC21, QNC25	DRB-012
BLADE	2006-2012	AZE154H, AZE156H, GRE156H	DRA-012
CALDINA	1997-2002	AT211G, CT216G, ST210G, ST215G, ST215W	DCP-014R/L, DCS-G014, DCV-014
CALDINA	2002-2007	AZT241W, AZT246W, ST246W, ZZT241W	DRB-012
CAMI	1999-2000	J100E	DCP-012R/L, DCS-G012, DCV-012
CAMI	2000-2006	J102E, J122E	DCP-012R/L, DCS-G012, DCV-012
CALDINA	1997-2002	AT211G, CT216G, ST210G, ST215G, ST215W	DCP-014R/L, DCS-G014, DCV-014
CALDINA	2002-2007	AZT241W, AZT246W, ST246W, ZZT241W	DRB-012
CAMI	1999-2000	J100E	DCP-012R/L, DCS-G012, DCV-012
CAMI	2000-2006	J102E, J122E	DCP-012R/L, DCS-G012, DCV-012
CELICA	1999-2006	ZZT230, ZZT231	DCP-020R/L, DCS-G020, DCV-020
CHASER	1996-2001	GX100, GX105, JZX100, JZX101, JZX105, LX100, SX100	DCP-019R/L, DCS-G019, DCV-019
C-HR (INCL. HYBRID)	2016-2018	ZYX10, NGX50	DRB-014
C-HR (INCL. HYBRID)	2018-2023	NGX10, NGX50, ZYX10, ZYX11	DRB-014
COASTER	1993-2004	BB4#, HZB4#, HDB5#, HZB5#	DCP-016R/L, DCS-G016, DCV-016
COASTER	2004-2016	XZB40, XZB46V, XZB50, XZB51, BZB40, BZB50	DCP-016R/L, DCS-G016, DCV-016
COASTER	2017-	XZB60, XZB70	DCP-014R/L, DCS-G014, DCV-014
COROLLA (INCL. HYBRID)	2019-	MZEA17, NRE210, ZRE212, ZWE211, ZWE214, ZWE215, ZWE219	*1 DRB-012
COROLLA AXIO (INCL. HYBRID)	2012-2025	NKE165, NRE160, NRE161, NZE161, NZE164	*1 DRB-014
COROLLA CROSS (INCL. HYBRID)	2021-	ZSG10, ZVG11, ZVG15	*2
COROLLA FIELDER (INCL. HYBRID)	2000-2006	NZE121G, NZE124G, ZZE122G, ZZE123G, ZZE124G, CE121G	DRB-014
COROLLA FIELDER (INCL. HYBRID)	2006-2012	NZE141G, NZE144G, ZRE142G, ZRE144G	DRB-012
COROLLA FIELDER (INCL. HYBRID)	2012-2025	NKE165G, NRE161G, NZE161G, NZE164G, ZRE162G	DRB-012
COROLLA LEVIN/SPRINTER TRUENO	1997-2000	AE110, AE111	DCP-018R/L, DCS-G018, DCV-018
COROLLA LUMION	2007-2015	NZE151N, ZRE152N, ZRE154N	DRB-014
COROLLA RUNX	2001-2006	NZE121, NZE124, ZZE122, ZZE123, ZZE124	DRA-014
COROLLA SPACIO	1997-2001	AE111N, AE115N	DCP-016R/L, DCS-G016, DCV-016
COROLLA SPACIO	2001-2007	NZE121N, ZZE122N, ZZE124N	DRB-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
TOYOTA			
COROLLA SPORTS (INCL. HYBRID)	2018-	NRE210H, NRE214H, ZWE211H, ZWE213H, ZWE219H, MZEA12H	DRA-012
COROLLA TOURING (INCL. HYBRID)	2019-	MZEA12W, MZEA17W, NRE210W, ZRE212W, ZWE211W, ZWE214W, ZWE215W, ZWE219W	DRB-012
COROLLA WAGON	1997-2000	AE100G, AE101G, AE104G, CE101G, CE102G, EE104G	DCP-016R/L, DCS-G016, DCV-016
CORONA PREMIO	1996-2001	AT210, AT211, CT211, CT216, ST210, ST215	DCP-016R/L, DCS-G016, DCV-016
CRESTA	1996-2001	GX100, GX105, JZV100, JZX101, JZX105, LX100	DCP-019R/L, DCS-G019, DCV-019
CROWN ESTATE	2001-2007	GS171W, JZS171W, JZS173W, JZS175W	DCP-012R/L, DCS-G012, DCV-012
CROWN SPORTS	2023-	AZSH36W, AZSH37W	DRB-012
DUET	1998-2004	M100A, M101A, M110A, M111A	DCP-012R/L, DCS-G012, DCV-012
ESQUIRE (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZWR80G	DRB-016
ESTIMA (INCL. HYBRID)	2000-2005	ACR30W, ACR40W, AHR10W, MCR30W, MCR40W	DRB-016
ESTIMA (INCL. HYBRID)	2006-2019	ACR50W, ACR55W, AHR20W, GSR50W, GSR55W	DRB-012
FJ CRUISER	2010-2018	GSJ15W	*2 225mm
FUN CARGO	1999-2002	NCP20, NCP21, NCP25	DCP-016R/L, DCS-G016, DCV-016
FUN CARGO	2002-2005	NCP20, NCP21, NCP25	DRB-016
GAIA	1998-2002	ACM10G, CXM10G, SXM10G, SXM15G	DCP-016R/L, DCS-G016, DCV-016
GAIA	2002-2004	ACM10G, ACM15G, CXM10G	DRB-016
GRANACE	2019-2024	GDH303W	DRA-016
GRAND HIACE	1999-2002	KCH10W, KCH16W, VCH10W, VCH16W	DCP-018R/L, DCS-G018, DCV-018
GRANVIA	1998-2002	KCH10W, KCH16W, VCH10W, VCH16W	DCP-018R/L, DCS-G018, DCV-018
HARRIER (INCL. HYBRID)	1997-2003	ACU10W, ACU15W, MCU10W, MCU15W, SXU10W, SXU15W	DCP-016R/L, DCS-G016, DCV-016
HARRIER (INCL. HYBRID)	2003-2013	ACU30W, ACU35W, GSU30W, GSU31W, GSU35W, GSU36W, MCU30W, MCU31W, MCU35W, MCU36W, MHU38W	DRB-014
HARRIER (INCL. HYBRID)	2013-2020	AVU65W, ZSU60W, ZSU65W, ASU60W, ASU65W	DRB-014
HARRIER (INCL. HYBRID)	2020-	AXUH80, AXUH85, AXUP85, MXUA80, MXUA85,	DRB-014
HIACE VAN/WAGON	1996-2004	KZH1###, RZH1###, TRH1###	DCP-017R/L, DCS-G017, DCV-017
HIACE VAN/WAGON (STANDARD)	2004-	GDH20###, KDH20###, TRH20###	DCP-017R/L, DCS-G017, DCV-017

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
TOYOTA			
HIACE VAN/WAGON (WIDE)	2004-	GDH21###, GDH22###, KDH21###, KDH22###, TRH21###, TRH22###	DCP-017R/L, DCS-G017, DCV-017
HIACE LEGIAS	1998-2002	KCH40G, KCH40W, KCH46G, KCH46W, RCH41W, RCH47W	DCP-018R/L, DCS-G018, DCV-018
HILUX SURF	1995-2002	KDN185W, KZN185G, KZN185W, RZN180W, RZN185W, VZN185W	*2
HILUX SURF	2002-2009	GRN215W, KDN215W, RZN210W, RZN215W, TRN210W, TRN215W, VZN210W, VZN215W	*2 Unique shape
IPSUM	1998-2001	SXM10G, SXM15G, CXM10G	DCP-016R/L, DCS-G016, DCV-016
IPSUM	2001-2009	ACM21W, ACM26W	DRB-016
IQ	2008-2016	KGJ10, NGJ10	DRB-011
ISIS	2004-2017	ANM10G, ANM15G, ANM10W, ANM15W, ZGM10G, ZGM11G, ZGM15G, ZGM10W, ZGM11W, ZGM15W, ZNM10G, ZNM10W	DRB-014
IST	2002-2007	NCP60, NCP61, NCP65	DRB-012
IST	2007-2016	NCP110, NCP115, ZSP110	DRB-008
JPN TAXI	2017-	NTP10	DRB-014
KLUGAR	2000-2007	ACU20W, ACU25W, MCU20W, MCU25W, MHU28W	DRB-012
LAND CRUISER (70)	1994-2004	J70, J71, J73, J74, J76, J77	DCP-014R/L, DCS-G014, DCV-014
LAND CRUISER (100)	1999-2007	HDJ101K, UZJ100W	DCP-016R/L, DCS-G016, DCV-016
LAND CRUISER (200)	2007-2021	UZJ200W, URJ202W	DRB-012
LAND CRUISER (250)	2024-	GDJ250W, TRJ250W	DRB-012
LAND CRUISER (300)	2021-	FJA300W, VJA300W	DRA-012
LAND CRUISER PRADO (90)	1996-2002	KDJ90W, KDJ95W, KZJ90W, KZJ95W, RZJ90W, RZJ95W, VZJ90W, VZJ95W	DCP-014R/L, DCS-G014, DCV-014
LAND CRUISER PRADO (120)	2002-2009	GRJ120W, GRJ121W, KDJ120W, KDJ121W, KDJ125W, TRJ120W, TRJ125W, VZJ120W, VZJ121W, VZJ125W	DRB-016 (018)
LAND CRUISER PRADO (150)	2009-	GDJ150W, GDJ151W, GRJ150W, GRJ151W, TRJ150W	DRB-012
LEGIUS ACE (STANDARD)	2004-2020	GDH20###, KDH20###, TRH20###	DCP-017R/L, DCS-G017, DCV-017
LEGIUS ACE (WIDE)	2004-2020	GDH21###, GDH22###, KDH21###, KDH22###, TRH21###, TRH22###	DCP-017R/L, DCS-G017, DCV-017
MARK X	2004-2009	GRX120, GRX121, GRX125	DCP-016R/L, DCS-G016, DCV-016
MARK X	2009-2012	GRX130, GRX133, GRX135	*1 016
MARK X	2012-2019	GRX130, GRX133, GRX135	*1 DRB-016

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	D/CP/DCS/DCV/DRA/B (Conv.)
			P/N
TOYOTA			
MARK X GIO	2007-2013	ANA10, ANA15, GGA10	DRB-012
MARK II	1996-2000	GX100, GX105, JZX100, JZX101, JZX105, LX100	DCP-019R/L, DCS-G019, DCV-019
MARK II BRIT	2002-2007	GX110W, GX115W, JZX110W, JZX115W	DRB-012
MARK II WAGON QUALIS	1997-2002	MCV20W, MCV21W, MCV25W, SXV20W, SXV25W	DCP-014R/L, DCS-G014, DCV-014
NADIA	1998-2003	ACN10, ACN10H, ACN15, ACN15H, SXN10, SXN10H, SXN15, SXN15H	DCP-017R/L, DCS-G017, DCV-017
NOAH (INCL. HYBRID)	2001-2007	AZR60G, AZR65G	DRB-016
NOAH (INCL. HYBRID)	2007-2013	ZRR70G, ZRR75G, ZRR70W, ZRR75W	DRB-016
NOAH (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZRR80W, ZRR85W, ZWR80G	DRB-016
NOAH (INCL. HYBRID)	2022-	ZWR90W, ZWR92W, ZWR95W, MZRA90W, MZRA92W, MZRA95W, MZRA97W	DRA-014
OPA	2000-2005	ACT10, ZCT10, ZCT15	DRB-014
PASSO	2004-2010	KGC10, KGC15, QNC10	DRB-014
PASSO	2010-2016	NGC30, KGC30, KGC35	DRB-014
PASSO	2016-2018	M700A, M710A	DRB-011
PASSO	2018-2023	M700A, M710A	DRB-011
PASSO SETTE	2008-2012	M502E, M512E	DRB-012
PIXIS EPOCH	2012-2017	LA300A, LA310A	DRB-011
PIXIS EPOCH	2017-	LA350A, LA360A	*1 DRB-011
PIXIS JOY	2016-2017	LA250A, LA260A	DRB-011
PIXIS JOY	2017-2023	LA250A, LA260A	DRB-011
PIXIS SPACE	2011-2017	L575A, L585A	DRB-011
PIXIS VAN	2011-2017	S321M, S331M	DRA-014
PIXIS VAN	2017-2021	S321M, S331M	DRA-014
PIXIS VAN	2021-	S700M, S710M	*1 DRB-014
PIXIS MEGA	2015-2017	LA700A, LA710A	DRB-012
PIXIS MEGA	2018-2022	LA700A, LA710A	DRB-012
PORTE	2004-2012	NNP10, NNP11, NNP15	DRB-016
PORTE	2012-2020	NCP141, NCP145, NSP140, NSP141	DRB-014
PREMIO	2001-2007	AZT240, NZT240, ZZT240, ZZT245	DRB-016
PREMIO	2007-2021	NZT260, ZRT260, ZRT261, ZRT265	DRB-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
TOYOTA			
PRIUS	2003-2009	NHW20	DRB-016
PRIUS	2009-2015	ZVW30	*1 DRB-016
PRIUS	2015-2017	ZVW50, ZVW51, ZVW55	DRB-016
PRIUS	2017-2022	ZVW50, ZVW51, ZVW55	DRB-016
PRIUS PHV	2012-2016	ZVW35	*1 DRB-016
PRIUS α	2011-2021	ZVW40W, ZVW41W	DRB-011
PROBOX (INCL. HYBRID)	2002-2014	NCP50V, NCP51V, NCP52V, NCP55V, NCP58G, NCP59G, NLP51V	DRB-014
PROBOX (INCL. HYBRID)	2014-	NSP160V, NCP160V, NCP165V, NHP160V	DRB-014
RACTIS	2005-2010	NCP100, NCP105, SCP100	DRB-014
RACTIS	2010-2016	NCP120, NCP122, NCP125, NSP120, NSP122	DRB-012
RAIZE	2019-	A200A, A201A, A202A, A210A	DRB-011
RAUM	1997-2003	EXZ10, EXZ15	DCP-016R/L, DCS-G016, DCV-016
RAUM	2003-2011	NCZ20, NCZ25	DRB-014
RAV4 (INCL. HYBRID)	1996-2000	SXA10C, SXA10G, SXA10W, SXA11G, SXA11W, SXA15G, SXA16G	DCP-014R/L, DCS-G014, DCV-014
RAV4 (INCL. HYBRID)	2000-2005	ACA20W, ACA21W, ZCA25W, ZCA26W	DRB-012
RAV4 (INCL. HYBRID)	2005-2016	ACA31W, ACA36W	DRB-012
RAV4 (INCL. HYBRID)	2019-	AXAH52, AXAH54, AXAP54, MXAA52, MXAA54	DRB-012
ROOMY (INCL. CUSTOM)	2016-2018	M900A, M910A	*1 DRB-014
ROOMY (INCL. CUSTOM)	2018-	M900A, M910A	*1 DRB-014
RUSH	2006-2016	J200E, J210E	DRB-012
SIENTA (INCL. HYBRID)	2003-2015	NCP81G, NCP85G	DRB-012
SIENTA (INCL. HYBRID)	2015-2018	NCP175G, NHP170G, NSP170G, NSP172G	DRB-012
SIENTA (INCL. HYBRID)	2018-2022	NCP175G, NHP170G, NSP170G, NSP172G	DRB-012
SIENTA (INCL. HYBRID)	2022-	MXPC10G, MXPL10G, MXPL15G, MXPC12G, MXPL12G	DRB-012
SOARER	1991-2001	JZZ30, JZZ31, UZZ31, UZZ32	*2
SPADE	2012-2020	NCP141, NCP145, NSP140, NSP141	DRB-014
SPARKY	2000-2003	S221E, S231E	DCP-015R/L, DCS-G015, DCV-015
SPRINTER CARIB	1997-2002	AE111G, AE114G, AE115G	DCP-014R/L, DCS-G014, DCV-014
SUCCEED (INCL. HYBRID)	2002-2014	NCP58G, NCP59G, NCP51V, NCP55V, NLP51V	DRB-012
SUCCEED (INCL. HYBRID)	2014-2020	NCP160V, NCP165V, NHP160V	DRB-014

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
TOYOTA			
SUPRA	1993-2002	JZA80	DCP-018R/L, DCS-G018, DCV-018
TANK (INCL. CUSTOM)	2016-2018	M900A, M910A	*1 DRB-014
TANK (INCL. CUSTOM)	2018-2020	M900A, M910A	*1 DRB-014
TOURING HIACE	1999-2002	KCH40W, KCH46W, RCH41W, RCH47W	DCP-018R/L, DCS-G018, DCV-018
TOWNACE/LITEACE VAN	1998-2001	KR4#V, CR4#V, CR5#V	DCP-016R/L,DCS-G016,DCV-016
TOWNACE/LITEACE VAN/TRUCK	2008-2009	S402M, S412M, S402U, S412U	DRB-014
TOWNACE/LITEACE VAN/TRUCK	2009-2020	S402M, S412M, S402U, S412U	DRB-016
TOWNACE NOAH/LITEACE NOAH	1998-2001	CR40G, CR50G, SR40G, SR50G	DCP-016R/L, DCS-G016, DCV-016
TOWNACE VAN	2020-	S403M, S413M	DRB-016
VANGUARD	2007-2013	ACA33W, ACA38W, GSA33W	DRB-012
VELFIRE (INCL. HYBRID)	2008-2014	ANH20W, ANH25W, ATH20W, GGH20W, GGH25W	DRB-016
VELFIRE (INCL. HYBRID)	2015-2017	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	DRB-014
VELFIRE (INCL. HYBRID)	2018-2023	AGH30W, AGH35W, AYH30W, GGH30W, GGH35W	DRB-014
VELFIRE (INCL. HYBRID)	2023-	AAHH40W, AAHH45W, TAHA40W, TAHA45W AAHP45W	DRB-012
VEROSSA	2001-2004	GX110, GX115, JZX110	DCP-019R/L, DCS-G019, DCV-019
VISTA	1998-2003	AZV50, AZV55, SV50, SV55, ZZV50	DCP-019R/L, DCS-G019, DCV-019
VISTA ALDEO	1998-2003	AZV50G, AZV55G, SV50G, SV55G, ZZV50G	DCP-014R/L, DCS-G014, DCV-014
VITZ (INCL. HYBRID)	1999-2005	NCP10, NCP13, NCP15, SCP10, SCP13	*2 Not removable
VITZ (INCL. HYBRID)	2005-2010	KSP90, NCP91, NCP95, SCP90	DRB-012
VITZ (INCL. HYBRID)	2010-2020	KSP130, NCP131, NHP130, NSP130, NSP135	DRB-012
VOLTZ	2002-2004	ZZE136, ZZE137, ZZE138	DRB-011
VOXY (INCL. HYBRID)	2001-2007	AZR60G, AZR65G	DRB-016
VOXY (INCL. HYBRID)	2007-2013	ZRR70G, ZRR75G, ZRR70W, ZRR75W	DRB-016
VOXY (INCL. HYBRID)	2014-2021	ZRR80G, ZRR85G, ZRR80W, ZRR85W, ZWR80G	DRB-016
VOXY (INCL. HYBRID)	2022-	ZWR90W, ZWR92W, ZWR95W, MZRA90W, MZRA92W, MZRA95W	DRA-014
WILL CYPHA	2002-2005	NCP70, NCP75	DRB-014
WILL VS	2001-2004	NZE127, ZZE127, ZZE128, ZZE129	DRB-012
WINDOM	1996-2001	MCV20, MCV21	DCP-020R/L,DCS-G020,DCV-020
WISH	2003-2005	ANE10G, ANE11W, ZNE10G, ZNE14G	DRB-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Rear Blade Series



MODEL	YEAR	MODEL CODE	DCP/DCS/DCV/DRA/B (Conv.)
			P/N
TOYOTA			
WISH	2005-2009	ANE10G, ANE11W, ZNE10G, ZNE14G	DRB-012
WISH	2009-2017	ZGE20G, ZGE21G, ZGE25G, ZGE20W, ZGE21W, ZGE22W, ZGE25W	DRB-012
YARIS (INCL. HYBRID)	2020-	KSP210, MXPA10, MXPA15, MXPB10, MXPB15	*2
YARIS CROSS (INCL. HYBRID)	2020-	MXPB10, MXPB15, MXPJ10, MXPJ15	DRB-012

Notes:

- Possible to make contact with the mole when the wiper is operated at high speed
- No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area
- Please take off the plastic part put on the wiper arm
- Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape

- *1 Wiper could be installed but no applicable item is set because of unwiped area => *1 000is reference
- *2 No applicable item is available
- *3 No applicable item is available because of contact with the car body or wiper arm
- *4 Please take off the plastic part put on the wiper arm
- *5 Please be careful for the damage on the wiper stopper as the wiper arm connect portion is special shape
- *6 Pa. side wiper shall be changed at the same time of Dr. side wiper => Only changing Pa. side wiper possibly make contact with Dr. side wiper
- *7 Shorter than OEM wiper
- *8 Possible to make contact with the mole when the wiper is operated at high speed
- *9 No applicable item is available for ADAS installed vehicles because of insufficient wipe at the sensor area

Regional Sales Network in Asia Pacific, Middle East and Africa

Singapore

DENSO INTERNATIONAL ASIA PTE. LTD.

Main business: Regional headquarters for Asia and Oceania
Sale of aftermarket products
Address: 51 Science Park Road, #01-19 The Aries, Science Park II,
Singapore 117586
Tel: +65 6776 8268 Fax: +65 6776 8698

Australia

DENSO AUTOMOTIVE SYSTEMS AUSTRALIA PTY. LTD.

Main business: Regional headquarters for Australia
Sale of automotive components
Address: 46 Merrindale Drive, Croydon, Victoria 3136, Australia
Tel: +61 3 8761 1100 Fax: +61 3 8761 1501

India

DENSO INTERNATIONAL INDIA PVT LTD

Main business: Sales of automotive components
Address: Plot No.3, Sector-3, IMT Manesar, Gurugram,
Haryana – 122052
TEL: +91 124 480 3200 Fax: +91 124 480 3201

Indonesia

PT DENSO SALES INDONESIA

Main business: Sale of automotive components
Address: Jalan Gaya Motor 1 no. 6, Sunter II, Kel. Sungai Bambu,
Kec. Tanjung Priok Jakarta 14330
Tel: +62 21 651 2279 Fax: +62 21 651 2284

Malaysia

DENSO (MALAYSIA) SDN. BHD.

Main business: Sale of automotive components
Address: Ground Floor, No 14, Jalan Glenmarie (Persiaran Kerjaya),
Section U1, 40150 Shah Alam, Selangor Darul Ehsan,
Malaysia
Tel: +60 3 5569 9933 Fax: +60 3 5567 3301

Taiwan

DENSO TAIWAN CORP.

Main business: Sale of automotive components
Address: 525, Sec. 2 Mei Su Road, Yang Mei Town, Taoyuan Hsien,
Taiwan, R.O.C
Tel: +886 3 482 8001 Fax: +886 3 482 8003

Thailand

DENSO SALES (THAILAND) CO. LTD.

Main business: Sale of automotive components
Address: 888 Moo 1, Bangna-Trad Km. 27.5, Tambol Bangbo,
Amphur Bangbo, Samutprakarn 10560 Thailand
Tel: +66 2 315 9500 Fax: +66 2 315 9555

The Philippines

DENSO PHILIPPINES CORPORATION

Main business: Sale of automotive components
Address: 109 Unity Avenue, Special Economic Zone,
Carmelray Industrial Park 1, Canlubang, Calamba City,
Philippines 4037
Tel: +63-49-549-3030 loc 4711 Fax: +63 49 549 3089

UAE

DENSO SALES MIDDLE EAST & NORTH AFRICA FZE

Main business: Sales and services of aftermarket products in
Middle Eastern and North African countries
Address: P.O. Box 261986 - S3B3SR03 - Jebel Ali Free Zone South -
Dubai - UAE
Tel: +971 4880 7789 Fax: +971 4880 7790

Vietnam

DENSO MANUFACTURING VIETNAM CO., LTD

Main business: Sales of automotive components
Address: Plot E-1, Thang Long Industrial Park
Dong Anh Dist., Hanoi, Vietnam
Tel: +84 4 3881 1608 Fax: +84 4 3881 2238



We welcome your feedback & suggestions!

If you have any feedback or suggestions on this catalogue,
please send email to ap_dias_asiamarketing@ap.denso.com,
or call our DENSO office in your country.



DENSO INTERNATIONAL ASIA PTE. LTD.
51 Science Park Road #01-19 The Aries Science Park II
Singapore 117586