



# Diesel Components

## Change of part numbering on the DENSO CR Injector and Pumps for Aftermarket

Due to global standardization of DENSO products, we hereby announce a part numbering change of our CR Injector and CR Pump range for the aftermarket in Europe.

The part number printed on the body will change from the DENSO 10-digit part number to the (already existing) catalogue part number (DCRI\*\*\*\*\* or DCRP\*\*\*\*\*).

This new part numbering will be done for all CR Injectors and Supply Pumps packed in the aftermarket blue box. For further details, please consult the information below.

### DENSO EUROPE B.V.

Hogeweyselaan 165 | 1382 JL Weesp | The Netherlands  
Tel. +31 (0)294 - 493 493 | Fax. +31 (0)294 - 417 122

[www.denso-am.eu](http://www.denso-am.eu)

[www.denso-am.co.uk](http://www.denso-am.co.uk)

Driven by  
**Quality**

## Change of part numbering on the DENSO CR Injector for Aftermarket



The new standardised part numbering will be done for all CR injectors packed in the aftermarket blue box (See below).

The part number printed on the body will change from the DENSO 10-digit part number to the (already existing) DCRI\*\*\*\*\* catalogue part number.

Affected range (Blue Box)	Old design	New design
		

**Please be aware that in both cases this is still a genuine DENSO CR injector, meeting the OE specifications!**

We also would like to express that the printed part number change will have no influence on the injector performance in the vehicle.

This part number printing change is considered as a "running change". So, for a period of time, it can be possible that both versions will be available. The existing stock will be sold first before the new version will be supplied.

Implementation of the new version is as of: **July, 2020.**

In the following table the complete affected range of CR injectors can be found with the cross reference of the old and the new part number printed on the injector body.

Please be aware that availability of part numbers can differ depending on sales region (EU / non-EU) or customer type (Service Network / non-Service Network). For the full availability, please utilize the price list provided by your local DENSO Aftermarket contact.

**The complete list of affected part numbers is added to this bulletin**

### DENSO EUROPE B.V.

Hogeweyselaan 165 | 1382 JL Weesp | The Netherlands  
 Tel. +31 (0)294 - 493 493 | Fax. +31 (0)294 - 417 122

[www.denso-am.eu](http://www.denso-am.eu)

[www.denso-am.co.uk](http://www.denso-am.co.uk)

Driven by  
**Quality**

## Change of part numbering on the DENSO CR Injector for Aftermarket



NO.	DENSO PN	CATALOGUE DNEU PN	DNEU PN (AM)
1	095000-036#	DCRI100360	0950000366AM
2	095000-051#	DCRI100510	0950000510AM
3	095000-057#	DCRI100570	0950000570AM
4	095000-064#	DCRI100640	0950000640AM
5	095000-074#	DCRI100740	0950000740AM
6	095000-075#	DCRI100750	0950000750AM
7	095000-088#	DCRI100880	0950000880AM
8	095000-094#	DCRI100940	0950000940AM
9	095000-095#	DCRI100950	0950000950AM
10	095000-508#	DCRI105080	0950005085AM
11	095000-513#	DCRI105130	0950005130AM
12	095000-518#	DCRI105180	0950005180AM
13	095000-525#	DCRI105250	0950005250AM
14	095000-560#	DCRI105600	0950005600AM
15	095000-565#	DCRI105650	0950005650AM
16	095000-576#	DCRI105760	0950005760AM
17	095000-578#	DCRI105780	0950005780AM
18	095000-580#	DCRI105800	0950005801AM
19	095000-583#	DCRI105830	0950005830AM
20	095000-588#	DCRI105880	0950005880AM
21	095000-602#	DCRI106020	0950006021AM
22	095000-613#	DCRI106130	0950006132AM
23	095000-620#	DCRI106200	0950006200AM
24	095000-624#	DCRI106240	0950006240AM
25	095000-625#	DCRI106250	0950006250AM
26	095000-662#	DCRI106620	0950006620AM
27	095000-698#	DCRI106980	0950006980AM
28	095000-706#	DCRI107060	0950007060AM
29	095000-750#	DCRI107500	0950007500AM
30	095000-758#	DCRI107580	0950007581AM
31	095000-761#	DCRI107610	0950007610AM
32	095000-764#	DCRI107640	0950007640AM
33	095000-767#	DCRI107670	0950007670AM
34	095000-769#	DCRI107690	0950007690AM
35	095000-978#	DCRI109780	0950009780AM
36	195000-114#	DCRI107730	1950001140AM
37	195000-115#	DCRI107760	1950001150AM

NO.	DENSO PN	CATALOGUE DNEU PN	DNEU PN (AM)
38	195000-116#	DCRI107780	1950001160AM
39	195000-117#	DCRI107800	1950001170AM
40	095000-782#	DCRI107820	0950007820AM
41	095000-784#	DCRI107840	0950007840AM
42	095000-785#	DCRI107850	0950007850AM
43	095000-786#	DCRI107860	0950007860AM
44	095000-789#	DCRI107890	0950007890AM
45	095000-793#	DCRI107930	0950007930AM
46	095000-803#	DCRI108030	0950008030AM
47	095000-811#	DCRI108110	0950008110AM
48	095000-956#	DCRI109560	0950009560AM
49	095000-984#	DCRI109840	0950009840AM
50	295050-001#	DCRI300010	2950500010AM
51	295050-005#	DCRI300050	2950500050AM
52	295050-010#	DCRI300100	2950500100AM
53	295050-012#	DCRI300120	2950500120AM
54	295050-025#	DCRI300250	2950500250AM
55	295050-030#	DCRI300300	2950500300AM
56	295050-046#	DCRI300460	2950500460AM
57	295050-047#	DCRI300470	2950500470AM
58	295050-056#	DCRI300560	2950500560AM
59	295050-077#	DCRI300770	2950500770AM
60	295050-081#	DCRI300810	2950500810AM
61	295050-082#	DCRI300820	2950500820AM
62	295050-083#	DCRI300830	2950500830AM
63	295050-090#	DCRI300900	2950500900AM
64	295050-103#	DCRI301030	2950501030AM
65	295050-105#	DCRI301050	2950501050AM
66	295050-106#	DCRI301060	2950501060AM
67	295050-190#	DCRI301900	2950501900AM
68	295900-011#	DCRI200110	2959000110AM
69	295900-024#	DCRI200240	2959000240AM
70	295900-026#	DCRI200260	2959000260AM
71	295900-028#	DCRI200280	2959000280AM
72	295900-041#	DCRI200410	2959000410AM
73	295900-042#	DCRI200420	2959000420AM
74	295900-043#	DCRI200430	2959000430AM

### DENSO EUROPE B.V.

Hogeweyselaan 165 | 1382 JL Weesp | The Netherlands  
Tel. +31 (0)294 - 493 493 | Fax. +31 (0)294 - 417 122

[www.denso-am.eu](http://www.denso-am.eu)

[www.denso-am.co.uk](http://www.denso-am.co.uk)

Driven by  
**Quality**

## Change of part numbering on the DENSO CR Pumps for Aftermarket



This new design will be done for all CR Pumps packed in the aftermarket blue box (See below).

The 10-digit part number will be removed from the DENSO label and will now only display the (already existing) DCRP\*\*\*\*\* catalogue part number.

Affected range (Blue Box)	Old design	New design
		

**Please be aware that in both cases it is still a genuine DENSO CR Pump, meeting the OE specifications!**

We also would like to express that the printed part number change will have no influence on the pump performance in the vehicle. This part number printing change is considered as a "running change". So, for a period of time, it can be possible that both versions will be available. The existing stock will be sold first before the new version will be supplied.

Implementation of the new version is as of: **July, 2020.**

In the following table the complete affected range of CR Pumps can be found with the cross reference of the old and the new part number printed on the pump body.

Please be aware that availability of part numbers can differ depending on sales region (EU / non-EU) or customer type (Service Network / non-Service Network). For the full availability, please utilize the price list provided by your local DENSO Aftermarket contact.

**The complete list of affected part numbers is added to this bulletin**

### DENSO EUROPE B.V.

Hogeweyselaan 165 | 1382 JL Weesp | The Netherlands  
 Tel. +31 (0)294 - 493 493 | Fax. +31 (0)294 - 417 122



## Change of part numbering on the DENSO CR Pumps for Aftermarket



NO.	DENSO PN	CATALOGUE DNEU PN	DNEU PN (AM)
1	094000-048#	DCRP100480	0940000480AM
2	294000-029#	DCRP300290	2940000293AM
3	294000-038#	DCRP300380	2940000380AM
4	294000-047#	DCRP300470	2940000470AM
5	294000-055#	DCRP300550	2940000550AM
6	294000-070#	DCRP300700	2940000700AM
7	294000-119#	DCRP301190	2940001190AM
8	294000-166#	DCRP301660	2940001660AM
9	294000-260#	DCRP302600	2940002600AM
10	294050-004#	DCRP400040	2940500040AM
11	294050-028#	DCRP400280	2940500280AM
12	294050-056#	DCRP400560	2940500560AM
13	294050-076#	DCRP400760	2940500760AM
14	294000-037#	DCRP300370	2940000371AM
15	294000-040#	DCRP300400	2940000400AM
16	294000-050#	DCRP300500	2940000502AM
17	294000-053#	DCRP300530	2940000533AM
18	294000-095#	DCRP300950	2940000951AM
19	294000-100#	DCRP301000	2940001000AM
20	294000-101#	DCRP301010	2940001010AM
21	294000-122#	DCRP301220	2940001223AM
22	294000-232#	DCRP302320	2940002322AM
23	294000-261#	DCRP302610	2940002610AM
24	294000-262#	DCRP302620	2940002620AM
25	294000-078#	DCRP300780	2940000781AM
26	294000-121#	DCRP301210	2940001210AM
27	294000-124#	DCRP301240	2940001240AM
28	294000-125#	DCRP301250	2940001250AM
29	294000-137#	DCRP301370	2940001370AM
30	294000-234#	DCRP302340	2940002340AM

### DENSO EUROPE B.V.

Hogeweyselaan 165 | 1382 JL Weesp | The Netherlands  
Tel. +31 (0)294 - 493 493 | Fax. +31 (0)294 - 417 122

[www.denso-am.eu](http://www.denso-am.eu)

[www.denso-am.co.uk](http://www.denso-am.co.uk)

Driven by  
**Quality**